
Overview of the Second Quarter 2015 Surveillance and Maintenance Report for the LM Rocky Flats Site

April–June 2015




U.S. DEPARTMENT OF
ENERGY

Legacy
Management

Quarterly Monitoring and Reporting

- Quarterly reports are required under the Rocky Flats Legacy Management Agreement (RFLMA), to document that the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA) remedy continues to be protective
 - Primary goal: Surface water protection
- Response action under the final remedy for Rocky Flats
 - Maintain two landfill covers
 - Maintain four groundwater treatment systems
 - Monitor surface water and groundwater
 - Maintain physical controls
 - Signage
 - Access restriction
 - Enforce institutional controls
 - No building construction or occupation
 - Excavation and soil-disturbance restrictions
 - No surface water consumption or agricultural use
 - No groundwater wells, except for monitoring
 - Landfill covers and engineered remedy-components protection



Surface Water Monitoring




Second Quarter 2015



U.S. DEPARTMENT OF
ENERGY

Legacy
Management

Select RFLMA Surface-Water Monitoring Locations



Original Landfill (OLF) Performance Monitoring

- OLF (Woman Creek – location GS59)
 - April 21 through 30, 2015 – Composite sampling results for lead and selenium above RFLMA standard
 - Lead 6.8 $\mu\text{g/L}$ (RFLMA standard is 6.5 $\mu\text{g/L}$); Selenium 5.5 $\mu\text{g/L}$ (RFLMA standard is 4.6 $\mu\text{g/L}$)
 - Prompted increased sampling frequency (monthly), per RFLMA evaluation protocols
 - Neither lead nor selenium were detected in the subsequent composite sample
 - June 12 through July 7, 2015 – Composite sampling results for selenium above RFLMA standard
 - Selenium 5.8 $\mu\text{g/L}$ (RFLMA standard is 4.6 $\mu\text{g/L}$)
 - Prompted increased sampling frequency (monthly), per RFLMA evaluation protocols
 - Selenium was not detected in the subsequent composite sample



Present Landfill (PLF) Performance Monitoring

- PLF (System effluent – location PLFSYSEFF)
 - Routine first quarter sampling result for vinyl chloride was 0.23 $\mu\text{g}/\text{L}$
 - Above RFLMA 0.2 $\mu\text{g}/\text{L}$ standard
 - Prompted increased sampling frequency (monthly), per RFLMA evaluation protocols
 - Three consecutive monthly sampling results during the second quarter were above standard at 0.24 – 0.26 $\mu\text{g}/\text{L}$
 - Prompted former PLF Pond outfall to No Name Gulch (location NNG01) sampling
 - Vinyl chloride was not detected at NNG01; sampling frequency reverted to quarterly, per RFLMA protocols



Point of Evaluation (POE) Monitoring

- Location SW027 – 12-month rolling average for plutonium, reportable as of April 30, 2015
 - Standard is 0.15 pCi/L
 - 12-month rolling averages 0.22 through 0.72 pCi/L
 - RFLMA Contact Record 2015-05 (July 8, 2015)
 - Mitigating actions include enhancing upstream erosion controls
 - All results from downstream WOMPOC are less than applicable standards
- No other RFLMA POE analyte concentrations were reportable throughout second quarter calendar year (CY) 2015



Point of Compliance (POC) Monitoring

- All RFLMA POC analyte concentrations remained below reporting levels throughout second quarter CY 2015



Questions?



U.S. DEPARTMENT OF
ENERGY

Legacy
Management

Groundwater Monitoring and Operations

Second Quarter 2015




U.S. DEPARTMENT OF
ENERGY

Legacy
Management

RFLMA Monitoring

- Heavy sampling quarter
 - 10 RCRA wells (quarterly)
 - 9 AOC wells and 1 Surface Water Support location (semiannual)
 - 27 Sentinel wells (semiannual)
 - 9 treatment system locations (semiannual)
- Results will be evaluated in the annual report





NOTE: Groundwater treatment system locations omitted for clarity




RFLMA Monitoring

- Groundwater quality generally consistent with previous results
 - AOC well 10304 was one exception
 - Located in Woman Creek valley downgradient of Ryan's Pit Plume
 - TCE reported at 15 µg/L (RFLMA level is 2.5 µg/L)
 - First result above RFLMA level at this location
 - RFLMA defines reportable conditions for AOC wells
 - No other well categories have RFLMA reportable conditions defined



Location of AOC Well 10304



AOC well 10304 (green symbol)



RFLMA Monitoring

- Heavy spring 2015 precipitation
 - Groundwater levels measured in monitoring wells were higher in many cases
 - One historically dry Sentinel well provided samples for the first time on record
 - Treatment systems received higher than normal flows
 - Treatment system flows during this quarter were comparable to a normal year's entire flow volume
 - Higher flows correspond to shorter residence times in treatment media at MSPTS and SPPTS
 - Result is reduced treatment effectiveness
 - Elevated VOCs in MSPTS effluent and at performance location GS10 (2.6 µg/L TCE at GS10, compared to RFLMA level of 2.5 µg/L)
 - Elevated nitrate, uranium in SPPTS effluent
 - Designs are in process to reconfigure the MSPTS and interim SPPTS



Non-RFLMA Monitoring

- Selected Evaluation wells
 - Most to support geochemistry study
 - Most locations associated with former Solar Evaporation Ponds
 - Several samples submitted to LBNL for high-resolution uranium isotopes analysis to determine natural versus anthropogenic content
- SPPTS
 - Microcell and lagoon testing
 - Bench tests of lagoon effluent clarifying and filtration



Treatment System Activities

- All treatment systems experienced above-average flows
- MSPTS
 - Routine air stripper and other system maintenance
 - Designing system reconfiguration
 - Will route MSPTS influent to ETPTS air stripper for treatment
 - Scheduled for construction in FY 2016
- ETPTS
 - Reconfiguration project completed in first quarter 2015, routine RFLMA sampling begun in second quarter
 - Added temporary, second pump in effluent tank to keep up with treated influent



Treatment System Activities

■ SPPTS

- Continued microcell tests
- Continued pilot-scale lagoon tests (including sampling)
- Replaced components damaged by rising groundwater in metering vault after prolonged heavy rainfall
- Installed automated sump pump in vault to manage shallow groundwater
 - Pumped water to treatment cells
- Began developing Statement of Work to empty original “Big Box” structure
 - Will convert to interim configuration early in FY 2016
 - Includes full-scale lagoon



Questions?



U.S. DEPARTMENT OF
ENERGY

Legacy
Management

Site Operations



U.S. DEPARTMENT OF
ENERGY

Legacy
Management

Quarterly Sign Inspections

- RFLMA physical control
- All signs are in good condition



Site Operations – OLF (continued)

- Performed three monthly inspections
 - One weather-related inspection occurred in April, two in May, and three in June
 - All weather-related inspections were due to precipitation events producing more than 1 inch of rain in a 24-hour period
- Monitored eight settlement monuments
- Cracking and slumping more pronounced on OLF east and west sides, compared to March observations
- Carried out multiple efforts to minimize ponding and route water away from affected areas using heavy equipment and hand labor throughout the second quarter
- CDPHE and EPA inspected the landfill on May 14 and 20
- The geotechnical engineer inspected the landfill on April 23, May 12, and May 20



Site Operations – OLF (continued)



Site Operations – OLF (continued)





East Perimeter Channel slumps, June 2015



U.S. DEPARTMENT OF
ENERGY

Legacy
Management



West Perimeter Channel slumps, June 2015



Site Operations – PLF

- Performed one quarterly inspection and six weather-related inspections for precipitation events producing more than 1 inch of rain in a 24-hour period
 - No issues were observed during inspections



Former Building Areas 371, 771, 881, and 991

- Inspected former building areas
 - Observed and filled subsidence areas at 881 and 771
 - Subsidences ranged from 1 to 5 feet wide, and 1 to 3 feet deep



Questions?



Ecology Activities

- Weed mapping
- Wetland delineations/mapping
- Conducted nest-box and prairie-dog surveys
- Conducted wetland water-level surveys
- Installed and irrigated 45 woody plants as habitat enhancement
- Treated approximately 194 acres with herbicides for weed control
 - Conducted hand-control and spot herbicide applications at some locations
- Prepared for third-quarter revegetation, wetland, and Preble's mouse mitigation monitoring

