

1035

REMOVAL #6 PIT 6
U.S. DOE-FERNALD
OH6 890 008 976

DOCUMENT DATE 12-13-90



UNITED STATES ENVIRONMENTAL
REGION 8
230 SOUTH DEARBORN ST.
CHICAGO, ILLINOIS 60604

1035

DEC 13 1990

REPLY TO ATTENTION OF:

Mr. Andrew P. Avel
United States Department Of Energy
Feed Materials Production Center
P.O. Box 398705
Cincinnati, Ohio 45239-8705

5HR-12

RE: Removal #6 Pit 6
U.S. DOE-Fernald
OH6 890 008 976

Dear Mr. Avel:


On November 15, 1990, the United States Department of Energy (U.S. DOE) submitted a work plan for removal action #6 - Waste Pit 6 at the Feed Materials Production Center in Fernald, Ohio. The purpose of this removal action is to control fugitive dust emissions from Waste Pit 6. On December 7, 1990, the United States Environmental Protection Agency (U.S. EPA) disapproved the work plan and provided a list of comments that U.S. DOE was to address in a revised proposed work plan. On December 11, 1990, U.S. DOE submitted a revised work plan. U.S. EPA has reviewed this work plan and is approving it with the following modifications:

1. Quality Assurance procedures of the approved Quality Assurance Project Plan (QAPP) must be followed, as supplemented by the work plan (Page 8).
2. The CERCLA Health and Safety Plan must be followed during this removal action (Page 8).
3. The laboratory that is to be used to analyze samples is the laboratory that is specified in U.S. DOE's response to comments (Attachment E, page 1).
4. Quality control blanks are to include both field and trip blanks (Attachment E, page 2).
5. U.S. DOE shall test the use of the fogger unit to ensure that visibility will not be diminished to the point where work can not be properly monitored.

1

Please contact me at (312/FTS) 886-4436 if there are any questions regarding this matter.

Sincerely yours,



Catherine A. McCord
On-Scene Coordinator

cc: Richard Shank, OEPA
Graham Mitchell, OEPA - SWDO
Joe LaGrone, U.S. DOE - ORO
Leo Duffy, U.S. DOE - HDQ