



**Department of Energy**  
Washington, DC 20585

July 9, 2014

Mr. Timothy Fischer  
U.S. Environmental Protection Agency  
Region V-SRF-6J  
77 W. Jackson Blvd.  
Chicago, IL 60604-3590

Mr. Thomas A. Schneider  
Ohio Environmental Protection Agency  
401 East 5th Street  
Dayton, Ohio 45402

Dear Mr. Fischer and Mr. Schneider:

**SUBJECT:** Transmittal of the June 2014 Fernald Preserve On-Site Disposal Facility Inspection Forms

The purpose of this letter is to transmit the completed forms for the June 2014 inspection of the On-Site Disposal Facility (OSDF) at the Fernald, Ohio, Site. The inspection was conducted on June 4 and 5, 2014. Photographs of the OSDF and the surrounding area were taken to accompany the inspection and are included with this report. The inspection was conducted by Stoller, the Ohio Environmental Protection Agency (Ohio EPA), and the Ohio Department of Health.

The Fernald Preserve *Comprehensive Legacy Management and Institutional Controls Plan* (LMICP) describes the inspection process. The June 2014 inspection included a walk of the toe, drainages, and fence line.

Individuals recorded their findings on the Fernald Preserve OSDF Walkdown Inspection Form and indicated the locations of those findings on a map of the OSDF.

The consolidated Fernald Preserve OSDF Walkdown Inspection Report and a map documenting the findings from the inspection are included with this report. Most findings were related to the presence of woody and invasive vegetation. No major changes were observed in the status of erosion along the toe of the slope or the fence line. These findings have been noted during previous inspections and maintenance at these locations is ongoing.

Findings from this inspection have been added to the Fernald Maintenance and Repair Action Items database. A database report of current items is enclosed. Resolution of the findings is tracked through this database. Items on the list that were resolved since the previous inspection are included in the report with the date and a description of the resolution. Previously reported resolved items are removed from the list. Resolution descriptions for older findings can be found on previous quarterly inspection reports.



Mr. Timothy Fischer  
Mr. Thomas A. Schneider  
Page 2

Note that maintenance activities to address restricted flow in several locations along the west inner drainage were completed on June 18. This work was in response to a "follow-up" inspection, pursuant to Section 7.2 of the *Post Closure Care and Inspection Plan*. A joint seam was repaired at Gravity Inlet Structure (GIS) 10, which is located near Valve House 6. The seam was sealed with concrete, the design grade was restored, and riprap was reinstalled within the channel. After these improvements, the GIS functioned as designed following recent rains. Other GIS outlets were surveyed to confirm that sufficient channel slope is maintained.

The next OSDF cell cap inspection is scheduled for September 2014 and will include a walkdown inspection of the toe, drainages, fence line, and any items of special interest or concern. Maintenance repair activities in the west inner drainage discussed above also will be inspected and evaluated.

If you have any questions or require additional information, please call me at (513) 648-3333. Please send any correspondence to:

U.S. Department of Energy  
Office of Legacy Management  
10995 Hamilton-Cleves Hwy.  
Harrison, OH 45030

Sincerely,

  
Gwendolyn Hooten  
Fernald Preserve Site Manager  
DOE-LM-20.2


Enclosure

cc w/enclosure:  
M. Murphy, USEPA-V, A-18J  
T. Schneider, OEPA (three copies of enclosure)  
Project Record File FER 115.02.05(A)  
Administrative Records (thru B. Irvine)

cc w/o enclosure:  
(electronic)  
G. Hooten, DOE  
K. Reed, DOE  
B. Hertel, Stoller  
J. Homer, Stoller  
L. McHenry, Stoller

# On-Site Disposal Facility Inspection Report

## June 2014



6319-D6320



U.S. DEPARTMENT OF  
**ENERGY**

Legacy  
Management



6319D-6322

**East Face Cell 1**



6319D-6346

**West Face Cell 1**




6319D-6320

**North Face Cell 1**



6319D-6321

**North Drainage (looking west)**




6319D-6324

**East Face Cell 2**



6319D-6345

**West Face Cell 2**



**East Face Cell 3**



**West Face Cell 3**



**East Face Cell 4**



**West Face Cell 4**



**East Face Cell 5**



**West Face Cell 5**



6319D-6329

**East Face Cell 6**



6319D-6340

**West Face Cell 6**



6319D-6330

**East Face Cell 7**



6319D-6338

**West Face Cell 7**



**East Face Cell 8**



**West Face Cell 8**



**South Face Cell 8**



**South Drainage (looking west)**



6319D-6331

**East Drainage Cell 7 (looking south)**



6319D-6327

**East Drainage Cell 4 (looking south)**



**East Drainage Cell 1 (looking south)**



**West Inner Drainage Cell 7 (looking south)**



6319D-6343

**West Inner Drainage Cell 4 (looking south)**



6319D-6319

**West Inner Drainage Cell 1 (looking south)**



6319D-6318

**West Outer Drainage Cell 1 (looking south)**



6319D-6337

**West Outer Drainage Cell 8 (looking south)**



**West Outer Drainage Cell 8 (looking north)**

U.S. Department of Energy Office of Legacy Management

Fernald Preserve OSDF Walkdown Inspection Report

Beginning: 06/04/2014

Ending: 06/05/2014

Area(s): Toe, drainages and fence line

Inspector(s): Stoller, Ohio EPA, Ohio Department of Health

Map No.	Location	GPS?	Type of Finding	Description	Photo? (File No.)
DB1	Edge of road on slant of rip rap	No	Vegetation	Honeysuckle	
DB2	End of cell 3 along road	No	Vegetation	Woody	
DB3	South toe edge of slope	No	Vegetation	Honeysuckle	
DB4	West above to of 8, end of 8	No	Vegetation	Thistle	
DB5	South of valve house 6 at edge of road	No	Vegetation	possible thistle	
DB6	Across from VH4, in rip rap at corner next to wells	No	Settlement	Depression	
DB7	Near VH3, next to mushroom in toe	No	Vegetation	Looks like thistle	
DB8	South of VH2	No	Vegetation	thistle in edge of road	
HS1	East drain at cell 4	No	Vegetation	Pear trees	
HS2	East drain near edge of rocks at 4/5 boundary	No	Vegetation	Canada thistle	
HS3	East drain next to fence at 5/6 boundary	No	Vegetation	Canada thistle, hackberry, musk thistle	
HS4	East drain in rocks	No	Vegetation	Canada thistle	
HS5	East drain at cell 6 next to fence	No	Vegetation	Musk thistle, ash tree, honeysuckle	

Map No.	Location	GPS?	Type of Finding	Description	Photo? (File No.)
HS6	East drain	No	Vegetation	Cottonwood	
HS7	AT rocks and into grass	No	Vegetation	Honeysuckle	
HS8	At crook in fence in drain	No	Vegetation	thistle and honeysuckle	
HS9	At the east 7/8 boundary in drain	No	Vegetation	Japanese honeysuckle	
HS10	AT hump in drain	No	Vegetation	mulberry, bull thistle	
HS11	East drain, midpoint to corner	No	Vegetation	hackberry, honeysuckle, cherry	
HS12	In drain coming out of southeast corner.	No	Vegetation	Cottonwoods in cattails	
HS13	South drain, quarter way across berm on rocks	No	Vegetation	Honeysuckle	
HS14	South drain, near southwest corner	No	Vegetation	willow and honeysuckle in the cattails	
HS15	In drain on the berm	No	Vegetation	Cedar, canada thistle, box elder, honeysuckle	
HS16	Prairie pocket at south end next to gate	No	Vegetation	Canada and musk thistle	
HS17	Southwest corner in drain	No	Vegetation	Honeysuckle, rosa, bull thistle, pear, elm, canada thistle	
HS18	East drain in rocks at 4/3 split	No	Vegetation	Canada thistle	
HS19	In cattails	No	Vegetation	Cottonwood, green ash	
HS20	East drain cell 2 midway in rocks	No	Vegetation	Teasel	
HS21	East drain at cell 1 midway in rocks	No	Vegetation	Honeysuckle, pear	
HS22	East drain at cell 1 in cattails and rocks	No	Vegetation	Ash and thistle	
HS23	Northeast drain in rocks	No	Vegetation	Cherry, teasel, honeysuckle	

Map No.	Location	GPS?	Type of Finding	Description	Photo? (File No.)
HS24	North drain above rocks in grasses	No	Vegetation	Rosa, honeysuckle, teasel	
HS25	North drain in cattails at old gate location	No	Vegetation	Ash tree	
HS26	North drain in grasses	No	Vegetation	teasel	
HS27	North drain at northwest corner	No	Vegetation	phragmites, teasel, ash	
HS28	North drain in grasses and rocks	No	Vegetation	Corylus, pear	
HS29	West drain at culvert beside north west gate	No	Vegetation	honeysuckle and teasel	
HS30	West drain at cell 1 along fence	No	Vegetation	Ash, teasel, honeysuckle, orchard grass	
HS31	West outer drain at cell 2 midway in rocks of drainage	No	Vegetation	honeysuckle, canada thistle	
HS32	Behind VH 2 in outer west drain	No	Vegetation	honeysuckle, canada thistle, orchard grass, willow	
HS33	West outer drain midway between VH2 and VH3 in grasses	No	Vegetation	musk thistle, teasel	
HS34	Behind VH 3	No	Vegetation	Teasel, musk thistle, honeysuckle	
HS35	Between VH3 and VH4 in grasses	No	Vegetation	musk thistle	
HS36	West drain along fence south of 4/5 boundary	No	Vegetation	Cedar	
HS37	Just north and south of VH5 in grasses	No	Vegetation	musk thistle	
HS38	Half way between VH 5 and VH 6 in grass	No	Vegetation	Musk thistle, canada thistle	

Map No.	Location	GPS?	Type of Finding	Description	Photo? (File No.)
HS39	Around and behind VH 6	No	Vegetation	musk thistle and honeysuckle	
HS40	South of VH 6, north of drain	No	Vegetation	musk thistle, teasel	
HS41	Just north of VH 7 and behind VH 7	No	Vegetation	musk thistle and teasel	
HS42	Around well south of VH 7	No	Vegetation	musk thistle	
HS43	At leachate line sign	No	Other	asphalt	
HS44	between drainage and fence at cell 8 (at owl box)	No	Vegetation	teasel, patch of trumpet creeper	
HS45	Behind VH8	No	Vegetation	musk thistle	
HS46	Southwest drainage	No	Vegetation	Teasel, willow, honeysuckle	
LM1	West 6:1 slope of cell 1	No	Vegetation	Crown vetch	
LM2	East drain at cell 2	No	Vegetation	Woody vegetation	
LM3	East drain at cell 3	No	Vegetation	Woody vegetation	
LM4	East 6:1 at cell 3/4 boundary	No	Vegetation	Crown vetch patches	
LM5	East 6:1 cell 5	No	Vegetation	Crown vetch	
LM6	Cell 8 cap	No	Vegetation	Large patches of thistle in various locations	
LM7	South drain	No	Vegetation	Honeysuckle	
LM8	Prairie pocket at southwest corner of OSDF at south gate	No	Vegetation	Thistle and crown vetch patches	
SB1	East toe at end of Cell 2 and into Cell 3	No	Vegetation	Honeysuckle and pear	
SB2	East drainage, middle, rip rap	No	Vegetation	Pear	

Map No.	Location	GPS?	Type of Finding	Description	Photo? (File No.)
SB3	Just south of 7/8 boundary, east drain, rip rap	No	Vegetation	Woody vegetation	
SB4	East drain, just south of "dog leg" in drain, rip rap.	No	Vegetation	Honeysuckle x 2	
SB5	East drain in rip rap, southeast corner	No	Vegetation	Patch of woody vegetation	
SB6	South drain in rip rap, southwest corner	No	Vegetation	Honeysuckle x 3	
SB7	West toe of cell 8	No	Vegetation	Nodding and Canada thistle	
SB8	west drain in rip rap	No	Vegetation	pear tree	
SB9	Near west boundary of cell 7 and 8	No	Vegetation	Thistle patch	

**Additional Notes**



FERNALD PRESERVE MAINTENANCE AND REPAIR ACTION ITEMS

JULY 2014 UPDATE

No.	Location	GPS?	Maintenance Item Identified	Date Identified	Origin of Finding	Inspection Finding No.	Resolution	Date of Resolution	Comments
856	Duke Energy substation	No	Honeysuckle all along bank east of Duke Energy substation	12/14/2009	December 2009 quarterly field walkdown	11			
862	Field at Rainbow bridge	No	Honeysuckle	12/14/2009	December 2009 quarterly field walkdown	17			
1002	South of Visitors Center parking lot in woods	No	Honeysuckle	6/2/2010	June 2010 quarterly field walkdown	34			
1004	Southeast of arsenic hot spot	No	Multiflora rose	6/2/2010	June 2010 quarterly field walkdown	36			
1006	South pines north of Sycamore trail	No	Honeysuckle all over	6/2/2010	June 2010 quarterly field walkdown	38			
1013	South side of south pines deer fence	No	Honeysuckle	6/2/2010	June 2010 quarterly field walkdown	45			
1020	Southeast of dance hall	No	Honeysuckle	6/2/2010	June 2010 quarterly field walkdown	52			
1022	Drainage west of northern most well in south field	No	Honeysuckle	6/2/2010	June 2010 quarterly field walkdown	54			
1091	Lodge pond basin – center	No	Invasive Schoenoplectus	9/8/2010	September 2010 quarterly field walkdown	2			
1116	Basin across from triangle	No	Honeysuckle, pear, crown vetch	9/8/2010	September 2010 quarterly field walkdown	28			
1117	Basin across from triangle	No	Honeysuckle, pear, crown vetch	9/8/2010	September 2010 quarterly field walkdown	29			
1118	Basin across from triangle	No	Pear, Honeysuckle	9/8/2010	September 2010 quarterly field walkdown	30			
1135	Pines near access road	No	Honeysuckle	9/8/2010	September 2010 quarterly field walkdown	48			
1136	North pines	No	Multiflora rose	9/8/2010	September 2010 quarterly field walkdown	49			

No.	Location	GPS?	Maintenance Item Identified	Date Identified	Origin of Finding	Inspection Finding No.	Resolution	Date of Resolution	Comments
1139	North pines along access rd.	No	Honeysuckle	9/8/2010	September 2010 quarterly field walkdown	53			
1211	Cell 5/6, east toe	No	Broken survey marker	3/8/2011	March 2011 OSDF Inspection	JC1			
1282	West of VH 7	No	Old leachate line unreadable	6/14/2011	June 2011 OSDF Inspection	DN13			
1285	East fence, east field	No	Honeysuckle along fence	9/7/2011	September 2011 quarterly field walkdown	1			
1291	North pines	No	Honeysuckle along woodline	9/7/2011	September 2011 quarterly field walkdown	10			
1292	Lodge pond - west	No	Olive species	9/7/2011	September 2011 quarterly field walkdown	11			
1293	East perimeter	No	Scattered pear	9/7/2011	September 2011 quarterly field walkdown	14			
1294	Lodge pond basin	No	Callery pear	9/7/2011	September 2011 quarterly field walkdown	15			
1296	OSDF fencing	No	Erosion at post bases, gaps and burrows at various locations	9/8/2011		na			
1305	East Cell 6, 6:1	No	12' x 4' bare area	9/13/2011	September 2011 OSDF Inspection	BL2			
1306	East Cell 7, 6:1	No	12' x 4' bare area	9/13/2011	September 2011 OSDF Inspection	BL3			
1315	Toe, east Cell 2	No	Erosion	9/13/2011	September 2011 OSDF Inspection	JH3			
1353	Restoration storage shed	No	Bottom of corner trim lost bolt.	9/8/2011		na			
1355	Cell 1 (west)	No	Bare spot	12/13/2011	December 2011 OSDF Inspection	LH1			
1356	Cell 1/2	No	Bare spot	12/13/2011	December 2011 OSDF Inspection	LH5			
1383	Waste Pits, north Pit 3	No	Erosion	3/6/2012	March 2012 quarterly field walkdown	12			
1443	East fence line	No	Black pipe	3/13/2012	March 2012 OSDF Inspection	HS10			

No.	Location	GPS?	Maintenance Item Identified	Date Identified	Origin of Finding	Inspection Finding No.	Resolution	Date of Resolution	Comments
1451	West fence line	No	Erosion	3/13/2012	March 2012 OSDF Inspection	HS18			
1460	Ditch line on edge of road	No	Sink holes	6/5/2012	June 2012 quarterly field walkdown	8			
1466	Shingle Oak trail	No	Teasel	6/5/2012	June 2012 quarterly field walkdown	24			
1468	Drainage area	No	Garlic mustard	6/5/2012	June 2012 quarterly field walkdown	26			
1482	North toe	No	Sycamore and willow	6/12/2012	June 2012 OSDF Inspection	LH1			
1485	Drainage west cell 8	No	Willow	6/12/2012	June 2012 OSDF Inspection	LH7			
1491	West toe cell 6	No	Wetland vegetation	6/12/2012	June 2012 OSDF Inspection	JH5	Manage water levels	6/18/2014	
1492	West toe south of VH4	No	Standing water	6/12/2012	June 2012 OSDF Inspection	JH6	No Action Required	6/18/2014	Confirmed sufficient drainage
1526	WM1, W4 and 3	No	Honeysuckle/pear	9/5/2012	September 2012 quarterly field walkdown	6			
1527	WM1, W5 and 1	No	Honeysuckle	9/5/2012	September 2012 quarterly field walkdown	7			
1528	WM1, W7	No	Honeysuckle	9/5/2012	September 2012 quarterly field walkdown	9			
1533	WM1, fenceline	No	Large honeysuckle	9/5/2012	September 2012 quarterly field walkdown	14			
1534	WM1	No	Multiflora rose	9/5/2012	September 2012 quarterly field walkdown	15			
1538	Cell 5, west toe inner drain	No	Standing water – follow up	9/11/2011	September 2011 OSDF Inspection	JH1			
1539	Gravity inlet at VH#6	No	Erosion from gravel road	9/11/2011	September 2011 OSDF Inspection	JH3	Erosion Repair	6/18/2014	
1540	Cell 7, west inner drain	No	Standing water	9/11/2011	September 2011 OSDF Inspection	JH4	No Action Required	6/18/2014	Confirmed sufficient drainage
1555	Cell 4, west riprap	No	Ponding and vegetation in riprap	12/5/2012	December 2012 OSDF Inspection	LH2	No Action Required	6/18/2014	Confirmed sufficient drainage

No.	Location	GPS?	Maintenance Item Identified	Date Identified	Origin of Finding	Inspection Finding No.	Resolution	Date of Resolution	Comments
1557	Cell 1, top	No	Burrows from moles	12/5/2012	December 2012 OSDF Inspection	TM1			
1585	CAWWT	No	North gate bent and signs are down	3/6/2013		na			
1599	Former WP PR1	No	Erosion	3/12/2013	March 2013 quarterly field walkdown	13			
1609	East of burn pit WPA PR1	No	Erosion	3/12/2013	March 2013 quarterly field walkdown	23			
1612	South of FPA	No	Erosion at outfall	3/12/2013	March 2013 quarterly field walkdown	26			
1625	PR1 north face	No	Erosion	3/12/2013	March 2013 quarterly field walkdown	39			
1639	Cell 8, south toe	No	Rock	3/12/2013	March 2013 OSDF Inspection	MS2			
1646	Cell 7, west toe	No	Erosion	3/12/2013	March 2013 OSDF Inspection	RE5			
1651	West inner drain between VHS and VH6	No	Poor drainage	3/12/2013	March 2013 OSDF Inspection	JH5	Manage water levels	6/18/2014	
1656	Cell 3/4, west toe	No	Standing water	3/12/2013	March 2013 OSDF Inspection	BL2	No Action Required	6/18/2014	Confirmed sufficient drainage
1668	Cell 7, east toe	No	Wash area	3/12/2013	March 2013 OSDF Inspection	HS7			
1671	Behind VH8	No	Culvert pipe	3/12/2013	March 2013 OSDF Inspection	HS13			
1673	Leachate signs	No	Faded and unreadable	3/12/2013	March 2013 OSDF Inspection	HS15			
1685	Cell 1, north drain	No	Erosion from roadway	3/12/2013	March 2013 OSDF Inspection	HS29			
1708	East side of road	No	Canada thistle	6/12/2013	June 2013 quarterly field walkdown	20			
1721	South field prairie	No	Canada thistle	6/12/2013	June 2013 quarterly field walkdown	33			
1722	North edge of VC parking lot	No	Pear and honeysuckle	6/6/2013	June 2013 quarterly field walkdown	34			
1735	Prairie north of parking lot	No	Pear and crown vetch	6/6/2013	June 2013 quarterly field walkdown	48			
1739	East bank Paddys Run	No	Multiflora rose	6/6/2013	June 2013 quarterly field walkdown	52			

No.	Location	GPS?	Maintenance Item Identified	Date Identified	Origin of Finding	Inspection Finding No.	Resolution	Date of Resolution	Comments
1740	Woods along Shingle Oak	No	Multiflora rose	6/6/2013	June 2013 quarterly field walkdown	53			
1741	Overlook on Shingle Oak at pond	No	Pear	6/6/2013	June 2013 quarterly field walkdown	54			
1745	NE corner	No	Musk thistle	6/12/2013	June 2013 OSDF Inspection	JH2			
1750	SW drainage and inner drain	No	Canada, musk, bull thistles (no flag)	6/12/2013	June 2013 OSDF Inspection	JH10			
1769	SW corner drain	No	Woody trees and shrubs	6/12/2013	June 2013 OSDF Inspection	HS17			
1773	East of Restoration shed	No	Vines growing up deer fence	9/4/2013	September 2013 quarterly field walkdown	2			
1774	Hill along SR 126	No	Teasel and honeysuckle	9/4/2013	September 2013 quarterly field walkdown	3			
1775	East fence WM1	No	Callery pear	9/4/2013	September 2013 quarterly field walkdown	4			
1776	East fence WM1	No	Honeysuckle	9/4/2013	September 2013 quarterly field walkdown	5			
1777	East fence WM1	No	Teasel	9/4/2013	September 2013 quarterly field walkdown	6			
1778	East fence WM1	No	Teasel	9/4/2013	September 2013 quarterly field walkdown	7			
1779	East fence WM1	No	Callery pear	9/4/2013	September 2013 quarterly field walkdown	8			
1780	East fence and south	No	Callery pear	9/4/2013	September 2013 quarterly field walkdown	9			
1781	Hill along SR 126	No	Honeysuckle	9/4/2013	September 2013 quarterly field walkdown	10			
1782	WM1 W6	No	Teasel	9/4/2013	September 2013 quarterly field walkdown	11			

No.	Location	GPS?	Maintenance Item Identified	Date Identified	Origin of Finding	Inspection Finding No.	Resolution	Date of Resolution	Comments
1783	WM1 W6 berm	No	Callery pear	9/4/2013	September 2013 quarterly field walkdown	12			
1788	WM1 W4 between pond and swale	No	Honeysuckle	9/4/2013	September 2013 quarterly field walkdown	17			
1790	By well south of WM1	No	Callery pear	9/4/2013	September 2013 quarterly field walkdown	19			
1791	By road pull off	No	Bare area	9/4/2013	September 2013 quarterly field walkdown	20			
1792	CAWWT fencing	No	Woody vegetation growing quickly around north portion	9/4/2013	September 2013 quarterly field walkdown	na			
1795	East edge Cell 8	No	Debris	9/10/2013	September 2013 OSDF Inspection	JH3			
1798	Cell 2, east 6:1	No	Rock/concrete	9/10/2013	September 2013 OSDF Inspection	JH7			
1815	SW corner	No	Woody vegetation	9/10/2013	September 2013 OSDF Inspection	HS17			
1816	SW corner	No	Bull thistle	9/10/2013	September 2013 OSDF Inspection	HS18			
1817	West fence at Cell 7/8	No	Debris	9/10/2013	September 2013 OSDF Inspection	HS19			
1823	NWEPR1 - Northwest corner of old access road and Hickory trail	No	Two old pipes from previous inspection	12/3/2013	December 2013 quarterly field walkdown	1			
1824	In Paddys Run just west of bench on Hickory Trail.	No	Large white board (cornhole board?)	12/3/2013	December 2013 quarterly field walkdown	2			
1825	Deer trail below slope west of road.	No	Old orange marker in evergreen	12/3/2013	December 2013 quarterly field walkdown	3			
1826	south side of trail just east of stone-paved section	No	Old yellow marker in shrub with red berries	12/3/2013	December 2013 quarterly field walkdown	4			
1827	Fence along south boundary with PR1	No	Hole under fence	12/3/2013	December 2013 quarterly field walkdown	5			

No.	Location	GPS?	Maintenance Item Identified	Date Identified	Origin of Finding	Inspection Finding No.	Resolution	Date of Resolution	Comments
1828	Opposite buildings on west side of road	No	plastic debris - corrugated sheets	12/3/2013	December 2013 quarterly field walkdown	6			
1829	PRTRF2	No	Old pink flags	12/3/2013	December 2013 quarterly field walkdown	7	General Cleaning	5/19/2014	
1830	Directly north of coverboard #2	No	Concrete	12/3/2013	December 2013 quarterly field walkdown	8	Debris Removal	4/2/2014	
1831	South of trestle-west of Paddy's Run	No	Orange fencing on far south end down from limb	12/3/2013	December 2013 quarterly field walkdown	9	General Cleaning	5/19/2014	
1832	South of trestle-west of Paddys Run	No	2 "steep slope" signs are down	12/3/2013	December 2013 quarterly field walkdown	10	General Cleaning	5/19/2014	
1833	West of Paddys Run	No	Deer fence slid down	12/3/2013	December 2013 quarterly field walkdown	11	Deer Fence Repair	5/19/2014	
1834	West of Paddys Run	No	Deer fence sliding	12/3/2013	December 2013 quarterly field walkdown	12	Deer Fence Repair	5/19/2014	
1835	West of Paddys Run - South of deer fence	No	2 "steep slope" signs down.	12/3/2013	December 2013 quarterly field walkdown	13	General Cleaning	5/19/2014	
1836	West of Paddys Run - South of deer fence	No	Yellow rope down	12/3/2013	December 2013 quarterly field walkdown	14	General Cleaning	5/19/2014	
1839	Deer fence	No	Fence overgrown	12/3/2013	December 2013 quarterly field walkdown	17			OK to remove fence
1840	Floodplain	No	Deer cages can be removed	12/3/2013	December 2013 quarterly field walkdown	18			Deer cages can be removed
1841	Along Paddys Run	No	Rope barricade and sign down	12/3/2013	December 2013 quarterly field walkdown	19	General Cleaning	5/19/2014	
1842	PRTRF2 - north deerfence	No	Hole in fence	12/3/2013	December 2013 quarterly field walkdown	20	Deer Fence Repair	5/18/2014	
1846	North east side of deer fence	No	Fence down	12/3/2013	December 2013 quarterly field walkdown	24	Deer Fence Repair	5/8/2014	

No.	Location	GPS?	Maintenance Item Identified	Date Identified	Origin of Finding	Inspection Finding No.	Resolution	Date of Resolution	Comments
1847	West bank of Paddys Run	No	Safety rope down	12/3/2013	December 2013 quarterly field walkdown	25	General Cleaning	5/9/2014	
1848	Southeast of chestnut plot	No	remove tree fence	12/3/2013	December 2013 quarterly field walkdown	26			Photo taken by inspector.
1849	Bluff along west side of Paddys Run midway along deer fence	No	Tree cage tipped over, needs removed	12/3/2013	December 2013 quarterly field walkdown	27	Deer Cages	5/9/2014	
1851	CAWWT fence.	No	Fencing is damaged on the east and north sides. Fence appears to have been pulled out of shape.	12/5/2013	December 2013 point-specific institutional controls inspection	NA			
1852	Northwest corner of parking area	No	Cedar tree	12/11/2013	December 2013 OSDF Inspection	HS1			
1853	North fenceline at former gate location	No	Metal gate stop...needs removed	12/11/2013	December 2013 OSDF Inspection	HS2			
1854	South gate	No	Sign is hanging	12/11/2013	December 2013 OSDF Inspection	HS3			
1855	Southwest corner at drainage	No	Cedars	12/11/2013	December 2013 OSDF Inspection	HS4			
1856	100 yards north of southwest corner	No	Sign hanging	12/11/2013	December 2013 OSDF Inspection	HS5			
1858	East of MDC	No	Asphalt	3/10/2014	March 2014 quarterly field walkdown	1	Debris Removal	4/2/2014	
1859	East of MDC	No	Asphalt	3/10/2014	March 2014 quarterly field walkdown	2	Debris Removal	4/2/2014	
1860	East of MDC	No	Asphalt	3/10/2014	March 2014 quarterly field walkdown	3	Debris Removal	4/2/2014	
1861	Next to firebreak	No	Concrete block chip	3/10/2014	March 2014 quarterly field walkdown	4			
1862	West of Skillet Pond	No	Glazed tile	3/10/2014	March 2014 quarterly field walkdown	5	Debris Removal	4/2/2014	
1863	South of serpent swale	No	Asphalt	3/10/2014	March 2014 quarterly field walkdown	6	Debris Removal	4/2/2014	
1864	Northwest of CAWWT near drainage	No	bent corrugated metal	3/10/2014	March 2014 quarterly field walkdown	7	Debris Removal	4/2/2014	
1865	Northwest of CAWWT near drainage	No	Power pole anchor, conduit	3/10/2014	March 2014 quarterly field walkdown	8			

No.	Location	GPS?	Maintenance Item Identified	Date Identified	Origin of Finding	Inspection Finding No.	Resolution	Date of Resolution	Comments
1866	Southeast of CAWWT fence SE corner	No	concrete chunk	3/10/2014	March 2014 quarterly field walkdown	9	Debris Removal	4/2/2014	
1867	West of OSDF VH 6	No	Concrete	3/10/2014	March 2014 quarterly field walkdown	10			
1868	Between wells 2436 and 22200	No	Concrete	3/10/2014	March 2014 quarterly field walkdown	11	Debris Removal	4/2/2014	
1869	Between wells 2436 and 22200	No	Stainless steel debris	3/10/2014	March 2014 quarterly field walkdown	12	Debris Removal	4/2/2014	
1870	northwest drainage corridor	No	glazed tile	3/10/2014	March 2014 quarterly field walkdown	13	Debris Removal	4/2/2014	
1871	Northwest drainage corridor on boundary with FWP-RF1	No	Power pole top, cable	3/10/2014	March 2014 quarterly field walkdown	14			
1872	North of former WPRP swale	No	Concrete	3/10/2014	March 2014 quarterly field walkdown	15			
1873	North of former WPRP swale	No	Glazed brick	3/10/2014	March 2014 quarterly field walkdown	16			
1874	North of former WPRP swale	No	ductile iron pipe (4" diameter)	3/10/2014	March 2014 quarterly field walkdown	17			
1875	Cut in Pit 3 west berm	No	Acid brick	3/10/2014	March 2014 quarterly field walkdown	18	Debris Removal	4/2/2014	
1876	SW of OSDF, just west of small pond	No	Concrete	3/10/2014	March 2014 quarterly field walkdown	19	Debris Removal	4/2/2014	
1877	SW of OSDF, just northwest of small pond	No	Concrete	3/10/2014	March 2014 quarterly field walkdown	20	Debris Removal	4/2/2014	No flag - near flag #1 (map # 19)
1878	West of OSDF VH 7	No	Concrete	3/10/2014	March 2014 quarterly field walkdown	21			
1879	NW of OSDF VH 7	No	Concrete	3/10/2014	March 2014 quarterly field walkdown	22			
1880	SW of OSDF VH 6	No	Concrete	3/10/2014	March 2014 quarterly field walkdown	23			
1881	SW of OSDF VH3 and south of drainage	No	Concrete	3/10/2014	March 2014 quarterly field walkdown	24			
1882	SW of OSDF VH3 and south of drainage	No	Concrete	3/10/2014	March 2014 quarterly field walkdown	25			
1883	North of CAWWT	No	Asphalt	3/10/2014	March 2014 quarterly field walkdown	26	Debris Removal	4/2/2014	
1884	West of MDC	No	Concrete	3/10/2014	March 2014 quarterly field walkdown	27	Debris Removal	4/2/2014	

No.	Location	GPS?	Maintenance Item Identified	Date Identified	Origin of Finding	Inspection Finding No.	Resolution	Date of Resolution	Comments
1885	East of MDC, SE of 5 oaks	No	Asphalt/Concrete	3/10/2014	March 2014 quarterly field walkdown	28	Debris Removal	4/2/2014	
1886	East of MDC, East of 5 oaks	No	Concrete	3/10/2014	March 2014 quarterly field walkdown	29	Debris Removal	4/2/2014	
1887	East of Pond/west of cell 8	No	Concrete	3/10/2014	March 2014 quarterly field walkdown	30	Debris Removal	4/2/2014	
1888	North hillside of MDC	No	Asphalt and other debris	3/10/2014	March 2014 quarterly field walkdown	31	Debris Removal	4/2/2014	
1889	High ground in MDC	No	Metal rod	3/10/2014	March 2014 quarterly field walkdown	32	Debris Removal	4/2/2014	
1890	High ground in MDC - just south of firebreak	No	Concrete	3/10/2014	March 2014 quarterly field walkdown	33			
1891	Northeast bank of pond	No	concrete/fence in water	3/10/2014	March 2014 quarterly field walkdown	34			
1892	NE of CAWWT	No	Going into pond 4B	3/10/2014	March 2014 quarterly field walkdown	35			
1893	West of MDC	No	HDPE chunk	3/10/2014	March 2014 quarterly field walkdown	36	Debris Removal	4/2/2014	
1894	North of depression	No	asphalt	3/10/2014	March 2014 quarterly field walkdown	37			
1895	North of access road	No	plastic bag/trash	3/10/2014	March 2014 quarterly field walkdown	38			
1896	west of firebreak	No	field of debris	3/10/2014	March 2014 quarterly field walkdown	39			
1897	SE corner of Angel pond	No	Pile of concrete and rebar	3/10/2014	March 2014 quarterly field walkdown	40			
1898	NE Angel pond at edge of rip rap	No	Debris	3/10/2014	March 2014 quarterly field walkdown	41	Debris Removal	4/2/2014	
1899	wetland piezometer	No	Piezometer down	3/10/2014	March 2014 quarterly field walkdown	42			
1900	west of Hickory trail, East of swale	No	Concrete	3/10/2014	March 2014 quarterly field walkdown	43			
1901	Bank of pond	No	Fresh erosion	3/10/2014	March 2014 quarterly field walkdown	44			
1902	bank between ponds	No	Fresh	3/10/2014	March 2014 quarterly field walkdown	45			
1903	Bank of Paddys Run	No	Bank cut at Paddy's Run	3/10/2014	March 2014 quarterly field walkdown	46			

No.	Location	GPS?	Maintenance Item Identified	Date Identified	Origin of Finding	Inspection Finding No.	Resolution	Date of Resolution	Comments
1904	West bank of community pond	No	litter/trash	3/10/2014	March 2014 quarterly field walkdown	47	Debris Removal	4/2/2014	
1905	East of community pond	No	Litter/trash	3/10/2014	March 2014 quarterly field walkdown	48	Debris Removal	4/2/2014	
1906	Ridge between ponds	No	Litter/trash	3/10/2014	March 2014 quarterly field walkdown	49	Debris Removal	4/2/2014	
1907	Ridge between ponds	No	ceramic piping	3/10/2014	March 2014 quarterly field walkdown	50	Debris Removal	4/2/2014	
1908	north edge of overflow bwtween ponds	No	small piece of ceramic piping	3/10/2014	March 2014 quarterly field walkdown	51	Debris Removal	4/2/2014	
1909	on end of peninsula	No	peninsula eroding	3/10/2014	March 2014 quarterly field walkdown	52			
1910	northwest of skillet pond	No	concrete	3/10/2014	March 2014 quarterly field walkdown	53			
1911	northwest of skillet pond	No	metal sheet	3/10/2014	March 2014 quarterly field walkdown	54			
1912	east side of swale	No	debris	3/10/2014	March 2014 quarterly field walkdown	55			
1913	southwest edge of wetland	No	small concrete	3/10/2014	March 2014 quarterly field walkdown	56	Debris Removal	4/2/2014	
1914	west edge of wetland	No	concrete	3/10/2014	March 2014 quarterly field walkdown	57	Debris Removal	4/2/2014	
1915	SE of dirt road	No	concrete	3/10/2014	March 2014 quarterly field walkdown	58	Debris Removal	4/2/2014	
1916	West of Biowetland along culvert	No	concrete	3/10/2014	March 2014 quarterly field walkdown	59	Debris Removal	4/2/2014	
1917	SW of pond, adjacent to pond inlet west of CAWWT	No	concrete	3/10/2014	March 2014 quarterly field walkdown	60	Debris Removal	4/2/2014	
1918	South of 5 oaks approx 75 yards	No	concrete	3/10/2014	March 2014 quarterly field walkdown	61	Debris Removal	4/2/2014	
1919	At water's edge, west bank of pond	No	concrete	3/10/2014	March 2014 quarterly field walkdown	62			
1920	Northwest edge of pond (about 8' from water)	No	glazed tile	3/10/2014	March 2014 quarterly field walkdown	63	Debris Removal	4/2/2014	
1921	Northwest of pond (10' from water)	No	18" x 18" concrete	3/10/2014	March 2014 quarterly field walkdown	64			
1922	Northwest of pond	No	concrete	3/10/2014	March 2014 quarterly field walkdown	65	Debris Removal	4/2/2014	

No.	Location	GPS?	Maintenance Item Identified	Date Identified	Origin of Finding	Inspection Finding No.	Resolution	Date of Resolution	Comments
1923	SE of swan pond, about 10' east of water's edge	No	glazed tile	3/10/2014	March 2014 quarterly field walkdown	66	Debris Removal	4/2/2014	
1924	North bank of swan pond at water's edge	No	oil slick/cess pool	3/10/2014	March 2014 quarterly field walkdown	67			
1925	West of Hickory trail	No	several pieces of concrete	3/10/2014	March 2014 quarterly field walkdown	68	Debris Removal	4/2/2014	
1926	West of Hickory trail	No	several pieces of concrete	3/10/2014	March 2014 quarterly field walkdown	69	Debris Removal	4/2/2014	
1927	West of Hickory trail	No	concrete	3/10/2014	March 2014 quarterly field walkdown	70	Debris Removal	4/2/2014	
1928	West of Hickory trail	No	concrete	3/10/2014	March 2014 quarterly field walkdown	71	Debris Removal	4/2/2014	
1929	Northeast of bio-wetland	No	concrete	3/10/2014	March 2014 quarterly field walkdown	72	Debris Removal	4/2/2014	
1930	North of bio-wetland	No	concrete	3/10/2014	March 2014 quarterly field walkdown	73	Debris Removal	4/2/2014	
1931	north of bio-wetland	No	concrete	3/10/2014	March 2014 quarterly field walkdown	74	Debris Removal	4/2/2014	
1932	north of CAWWT	No	Building material/concrete	3/10/2014	March 2014 quarterly field walkdown	75	Debris Removal	4/2/2014	
1933	North of CAWWT	No	Marker	3/10/2014	March 2014 quarterly field walkdown	76	Debris Removal	4/2/2014	
1934	inlet to pond, west of CAWWT	No	concrete	3/10/2014	March 2014 quarterly field walkdown	77	Debris Removal	4/2/2014	
1935	Midway between road and 5 oaks	No	asphalt	3/10/2014	March 2014 quarterly field walkdown	78	Debris Removal	4/2/2014	
1936	south of 5 oaks	No	asphalt	3/10/2014	March 2014 quarterly field walkdown	79	Debris Removal	4/2/2014	
1937	east of five oaks on east edge of pond	No	asphalt, plastic	3/10/2014	March 2014 quarterly field walkdown	80			
1938	northeast corner of pond near the willows	No	concrete	3/10/2014	March 2014 quarterly field walkdown	81			
1939	in drainage north of willows	No	glazed clay tile	3/10/2014	March 2014 quarterly field walkdown	82			
1940	east of pond	No	tile and coal?	3/10/2014	March 2014 quarterly field walkdown	83			
1941	west finger of "boot" pond	No	overturned plant cages in the water	3/10/2014	March 2014 quarterly field walkdown	84			

No.	Location	GPS?	Maintenance Item Identified	Date Identified	Origin of Finding	Inspection Finding No.	Resolution	Date of Resolution	Comments
1942	Knoll west of "boot" pond	No	metal fence post with no cage	3/10/2014	March 2014 quarterly field walkdown	85			
1943		No	piece of metal	3/10/2014	March 2014 quarterly field walkdown	86			
1944	North of Visitors Center	No	Asphalt/concrete	3/10/2014	March 2014 quarterly field walkdown	87			
1945	North of Visitors Center	No	Asphalt/concrete	3/10/2014	March 2014 quarterly field walkdown	88			
1946	Northeast of bio-wetland	No	glazed tile, asphalt, concrete	3/10/2014	March 2014 quarterly field walkdown	89	Debris Removal	4/2/2014	
1947	Northeast of bio-wetland	No	concrete	3/10/2014	March 2014 quarterly field walkdown	90			
1948	Northeast of bio-wetland	No	erosion	3/10/2014	March 2014 quarterly field walkdown	91			
1949	West of Visitors Center	No	asphalt	3/10/2014	March 2014 quarterly field walkdown	92			Finding just outside of inspection area boundary
1950	East 10:1, near southern border and into cell 5	No		3/11/2014	March 2014 OSDF Inspection	HB1	Erosion Repair	4/1/2014	
1951	Southwest 6:1 slope, cell 8	No	Burrow	3/11/2014	March 2014 OSDF Inspection	HB2	Seeding-HandBroadcast	4/1/2014	
1952	East 6:1, cell 2	No	Burrow	3/11/2014	March 2014 OSDF Inspection	HB3			
1953	Boundary between cell 3 and cell 4 at west toe	No	erosion near riprap	3/11/2014	March 2014 OSDF Inspection	LH1	Erosion Repair	4/1/2014	
1954	West toe of cell 5 near border of cell 4.	No	Large rock, couldn't pry	3/11/2014	March 2014 OSDF Inspection	LH2	Debris Removal	4/1/2014	
1955	East 20:1 cell 6	No	Cedar tree	3/11/2014	March 2014 OSDF Inspection	LM1	Woody Removal	4/1/2014	
1956	East 10:1 cell 4	No	Cedar	3/11/2014	March 2014 OSDF Inspection	LM2	Woody Removal	4/1/2014	
1957	West 6:1, cell 1	No	woody vegetation	3/11/2014	March 2014 OSDF Inspection	AT1	Woody Removal	4/1/2014	
1958	West 6:1, cell 2	No	Longer than 3'	3/11/2014	March 2014 OSDF Inspection	AT2	Erosion Repair	4/1/2014	
1959	West 6:1, cell 3	No	Thistle	3/11/2014	March 2014 OSDF Inspection	AT3	No Action Required	4/1/2014	
1960	West 6:1 north of VH, cell 5	No	longer than 3'	3/11/2014	March 2014 OSDF Inspection	AT4	No Action Required	4/1/2014	

No.	Location	GPS?	Maintenance Item Identified	Date Identified	Origin of Finding	Inspection Finding No.	Resolution	Date of Resolution	Comments
1961	West 6:1 at cell 5/6 boundary	No	longer than 3'	3/11/2014	March 2014 OSDF Inspection	AT5	No Action Required	4/1/2014	area of concern is vegetated
1962	West 6:1, north end, cell 7	No	Thistle	3/11/2014	March 2014 OSDF Inspection	AT6	No Action Required	4/1/2014	Standing dead vegetation from previous year
1963	West 6:1 across from VH, cell 8	No	Thistle	3/11/2014	March 2014 OSDF Inspection	AT7	No Action Required	4/1/2014	Standing dead vegetation from previous year
1964	East 6:1 at 4/5 boundary	No	Woody vegetation	3/11/2014	March 2014 OSDF Inspection	AT8	Woody Removal	4/1/2014	
1965	West 6:1, cell 2	No	Thistle	3/11/2014	March 2014 OSDF Inspection	BL1	No Action Required	4/1/2014	Dead vegetation from previous year
1966	West 6:1, across from VH, cell 2	No	thistle	3/11/2014	March 2014 OSDF Inspection	BL2	No Action Required	4/1/2014	Dead vegetation from previous year
1967	west 10:1 cell 4	No	burrow/hole	3/11/2014	March 2014 OSDF Inspection	BL3	Seeding-HandBroadcast	4/1/2014	
1968	West 6:1, in line with VH near top, cell 8	No	Honeysuckle	3/11/2014	March 2014 OSDF Inspection	BL4	Woody Removal	4/1/2014	
1969	Southeast 6:1, cell 8	No	Thistle rosettes	3/11/2014	March 2014 OSDF Inspection	BL5	No Action Required	4/1/2014	Cress rosettes
1970	East 6:1 cell 7	No	Thistle rosettes	3/11/2014	March 2014 OSDF Inspection	BL6	No Action Required	4/1/2014	Cress rosettes
1971	west 6:1, cell 3	No		3/11/2014	March 2014 OSDF Inspection	SD1			
1972	West 6:1, cell 5	No	2 large holes	3/11/2014	March 2014 OSDF Inspection	SD2			
1973	Inspector unsure of location. Cell 5 or 6.	No	Large bare spot. Rocks.	3/11/2014	March 2014 OSDF Inspection	SD3			Unable to locate
1974	West 6:1, cell 5	No	Large groundhog hole	3/11/2014	March 2014 OSDF Inspection	SD4	No Action Required	4/1/2014	
1975	20:1 top of cell 8 is indicated on map. "Midway down toe" is written on form.	No	Beginnings of deep rill	3/11/2014	March 2014 OSDF Inspection	SD5	Seeding-HandBroadcast	4/1/2014	
1976	East 6:1 midway up slope, cell 5	No	Bare spot approximately 3 feet circular	3/11/2014	March 2014 OSDF Inspection	SD6	No Action Required	4/1/2014	
1977	east 6:1 of either cell 4 (map) or cell 3 (form)...inspector unsure of location	No	Large hole, 6" deep	3/11/2014	March 2014 OSDF Inspection	SD7	Erosion Repair	4/1/2014	
1978	west 6:1, just south of VH 5	No	Musk thistle, several	3/11/2014	March 2014 OSDF Inspection	PB1			
1979	west 6:1, halfway between VH 5 and 6	No	Musk thistle	3/11/2014	March 2014 OSDF Inspection	PB2			

No.	Location	GPS?	Maintenance Item Identified	Date Identified	Origin of Finding	Inspection Finding No.	Resolution	Date of Resolution	Comments
1980	west 6:1, on edge of mowed grass, cell 6	No	Musk thistle, several	3/11/2014	March 2014 OSDF Inspection	PB3			
1981	Just north of rise, cell 8	No		3/11/2014	March 2014 OSDF Inspection	PB4			
1982	West 6:1, half way up slope, cell 7	No	Teasel rosettes	3/11/2014	March 2014 OSDF Inspection	HS1			
1983	North drainage	No	cedar tree	3/11/2014	March 2014 OSDF Inspection	LM3			
1984	East drain, cell 2	No	Cedar tree	3/11/2014	March 2014 OSDF Inspection	LM4	Woody Removal	4/1/2014	
1985	East edge of grassy area in SW corner of fenced area	No	Cedar tree	3/11/2014	March 2014 OSDF Inspection	LM5	Woody Removal	4/1/2014	
1986	Former compost area	No	Area needs re-seeded	6/3/2014	June 2014 quarterly field walkdown	1			
1987	Soutwest of bio-wetland	No	asphalt	6/3/2014	June 2014 quarterly field walkdown	2			
1988	South of drainage ditch	No	Crown vetch	6/3/2014	June 2014 quarterly field walkdown	3	Herbicide Applied	6/13/2014	
1989	Near road and along drainage	No	Crown vetch	6/3/2014	June 2014 quarterly field walkdown	4	Herbicide Applied	6/13/2014	
1990	Ridge top	No	Thistle and crown vetch	6/3/2014	June 2014 quarterly field walkdown	5	Herbicide Applied	6/13/2014	
1991	North of "Ant Island" basin	No	Remove deer cages as needed	6/3/2014	June 2014 quarterly field walkdown	6			
1992	NW of "Ant Island" basin	No	Phragmites	6/3/2014	June 2014 quarterly field walkdown	7	Herbicide Applied	6/16/2014	
1993	Edge of trail	No	reed canary grass	6/3/2014	June 2014 quarterly field walkdown	8	Herbicide Applied	6/16/2014	
1994	Edge of trail	No	reed canary grass	6/3/2014	June 2014 quarterly field walkdown	9	Herbicide Applied	6/16/2014	
1995	SW of storm water retention basin	No	reed canary grass	6/3/2014	June 2014 quarterly field walkdown	10	Herbicide Applied	6/18/2014	
1996	Bank of storm water retention basin	No	canada thistle	6/3/2014	June 2014 quarterly field walkdown	11	Herbicide Applied	6/18/2014	
1997	At outlet to storm sewer outfall ditch	No	reed canary grass	6/3/2014	June 2014 quarterly field walkdown	12	Herbicide Applied	6/18/2014	
1998	West fence	No	Hole in deer fence (2)	6/3/2014	June 2014 quarterly field walkdown	13			

No.	Location	GPS?	Maintenance Item Identified	Date Identified	Origin of Finding	Inspection Finding No.	Resolution	Date of Resolution	Comments
1999	North fence	No	Hole in fence	6/3/2014	June 2014 quarterly field walkdown	14			
2000	SE fence	No	Hole in fence	6/3/2014	June 2014 quarterly field walkdown	15			
2001	Southern deer fence	No	Fence needs to be removed	6/3/2014	June 2014 quarterly field walkdown	16			
2002	Between ponds	No	Individual musk thistle	6/3/2014	June 2014 quarterly field walkdown	17	Herbicide Applied	6/16/2014	
2003	North	No	Individual musk thistle and teasel	6/3/2014	June 2014 quarterly field walkdown	18	Herbicide Applied	6/13/2014	
2004	West of Sycamore trail next to Paddys Run	No	Old cages	6/3/2014	June 2014 quarterly field walkdown	19			
2005	West deer fence	No	Gate down	6/3/2014	June 2014 quarterly field walkdown	20			
2006	Inside deer fence	No	Teasel	6/3/2014	June 2014 quarterly field walkdown	21	Herbicide Applied	6/18/2014	
2007	Between wells	No	Fencing sliding down poles	6/3/2014	June 2014 quarterly field walkdown	22			
2008	Behind deer fence	No	Old cages	6/3/2014	June 2014 quarterly field walkdown	23			
2009	South edge	No	Sliding down poles	6/3/2014	June 2014 quarterly field walkdown	24			
2010	West of 'speed limit 15' sign	No	teasel	6/3/2014	June 2014 quarterly field walkdown	25	Herbicide Applied	6/16/2014	
2011	Under power lines in ravine	No	Nodding thistle (musk thistle)	6/3/2014	June 2014 quarterly field walkdown	26	Herbicide Applied	6/18/2014	
2012	West of Visitors Center, north of silo ponds	No	Crown vetch	6/3/2014	June 2014 quarterly field walkdown	27	Herbicide Applied	6/13/2014	
2013	Deer fence north of 'dance hall'	No	teasel	6/3/2014	June 2014 quarterly field walkdown	28	Herbicide Applied	6/17/2014	
2014	South of gravel road	No	teasel	6/3/2014	June 2014 quarterly field walkdown	29			
2015	SWU slope	No	teasel	6/3/2014	June 2014 quarterly field walkdown	30	Herbicide Applied	6/17/2014	
2016	Field across from Comm building and Lodge Pond	No	teasel	6/3/2014	June 2014 quarterly field walkdown	31	Herbicide Applied	6/18/2014	
2017		No	aluminum well cap	6/3/2014	June 2014 quarterly field walkdown	32			

No.	Location	GPS?	Maintenance Item Identified	Date Identified	Origin of Finding	Inspection Finding No.	Resolution	Date of Resolution	Comments
2018	East slope of basin	No	sheet metal roofing	6/3/2014	June 2014 quarterly field walkdown	33	No Action Required	6/3/2014	This finding was an identification of a cover board used for ecological monitoring purposes.
2019	North perimeter along SR 126	No	Unable to locate sign	6/5/2014	June 2014 point-specific institutional controls inspection				
2020	train trestle across Paddys Run	No	Thick vegetation along fencing and gate of trestle	6/3/2014	June 2014 point-specific institutional controls inspection	NA			
2021	Edge of road on slant of rip rap	No	Honeysuckle	6/4/2014	June 2014 OSDF Inspection	DB1			
2022	End of cell 3 along road	No	Woody	6/4/2014	June 2014 OSDF Inspection	DB2			
2023	South toe edge of slope	No	Honeysuckle	6/4/2014	June 2014 OSDF Inspection	DB3			
2024	West above to of 8, end of 8	No	Thistle	6/4/2014	June 2014 OSDF Inspection	DB4			
2025	South of valve house 6 at edge of road	No	possible thistle	6/4/2014	June 2014 OSDF Inspection	DB5			
2026	Across from VH4, in rip rap at corner next to wells	No	Depression	6/4/2014	June 2014 OSDF Inspection	DB6	No Action Required	6/18/2014	Confirmed sufficient drainage
2027	Near VH3, next to mushroom in toe	No	Looks like thistle	6/4/2014	June 2014 OSDF Inspection	DB7			
2028	South of VH2	No	thistle in edge of road	6/4/2014	June 2014 OSDF Inspection	DB8			
2029	East toe at end of Cell 2 and into Cell 3	No	Honeysuckle and pear	6/4/2014	June 2014 OSDF Inspection	SB1			
2030	East drainage, middle, rip rap	No	Pear	6/4/2014	June 2014 OSDF Inspection	SB2			
2031	Just south of 7/8 boundary, east drain, rip rap	No	Woody vegetation	6/4/2014	June 2014 OSDF Inspection	SB3			
2032	East drain, just south of "dog leg" in drain, rip rap.	No	Honeysuckle x 2	6/4/2014	June 2014 OSDF Inspection	SB4			
2033	East drain in rip rap, southeast corner	No	Patch of woody vegetation	6/4/2014	June 2014 OSDF Inspection	SB5			
2034	South drain in rip rap, southwest corner	No	Honeysuckle x 3	6/4/2014	June 2014 OSDF Inspection	SB6			
2035	West toe of cell 8	No	Nodding and Canada thistle	6/4/2014	June 2014 OSDF Inspection	SB7			

No.	Location	GPS?	Maintenance Item Identified	Date Identified	Origin of Finding	Inspection Finding No.	Resolution	Date of Resolution	Comments
2036	west drain in rip rap	No	pear tree	6/4/2014	June 2014 OSDF Inspection	SB8			
2037	Near west boundary of cell 7 and 8	No	Thistle patch	6/4/2014	June 2014 OSDF Inspection	SB9	Herbicide Applied	6/5/2014	
2038	West 6:1 slope of cell 1	No	Crown vetch	6/4/2014	June 2014 OSDF Inspection	LM1	Herbicide Applied	6/9/2014	
2039	East drain at cell 2	No	Woody vegetation	6/4/2014	June 2014 OSDF Inspection	LM2			
2040	East drain at cell 3	No	Woody vegetation	6/4/2014	June 2014 OSDF Inspection	LM3			
2041	East 6:1 at cell 3/4 boundary	No	Crown vetch patches	6/4/2014	June 2014 OSDF Inspection	LM4	Herbicide Applied	6/9/2014	
2042	East 6:1 cell 5	No	Crown vetch	6/4/2014	June 2014 OSDF Inspection	LM5			
2043	Cell 8 cap	No	Large patches of thistle in various locations	6/4/2014	June 2014 OSDF Inspection	LM6	Herbicide Applied	6/5/2014	
2044	South drain	No	Honeysuckle	6/4/2014	June 2014 OSDF Inspection	LM7			
2045	Prairie pocket at southwest corner of OSDF at south gate	No	Thistle and crown vetch patches	6/4/2014	June 2014 OSDF Inspection	LM8	Herbicide Applied	6/5/2014	
2046	East drain at cell 4	No	Pear trees	6/4/2014	June 2014 OSDF Inspection	HS1			
2047	East drain near edge of rocks at 4/5 boundary	No	Canada thistle	6/4/2014	June 2014 OSDF Inspection	HS2			
2048	East drain next to fence at 5/6 boundary	No	Canada thistle, hackberry, musk thistle	6/4/2014	June 2014 OSDF Inspection	HS3			
2049	East drain in rocks	No	Canada thistle	6/4/2014	June 2014 OSDF Inspection	HS4			
2050	East drain at cell 6 next to fence	No	Musk thistle, ash tree, honeysuckle	6/4/2014	June 2014 OSDF Inspection	HS5			
2051	East drain	No	Cottonwood	6/4/2014	June 2014 OSDF Inspection	HS6			
2052	AT rocks and into grass	No	Honeysuckle	6/4/2014	June 2014 OSDF Inspection	HS7			
2053	At crook in fence in drain	No	thistle and honeysuckle	6/4/2014	June 2014 OSDF Inspection	HS8			
2054	At the east 7/8 boundary in drain	No	Japanese honeysuckle	6/4/2014	June 2014 OSDF Inspection	HS9			

No.	Location	GPS?	Maintenance Item Identified	Date Identified	Origin of Finding	Inspection Finding No.	Resolution	Date of Resolution	Comments
2055	AT hump in drain	No	mulberry, bull thistle	6/5/2014	June 2014 OSDF Inspection	HS10			
2056	East drain, midpoint to corner	No	hackberry, honeysuckle, cherry	6/4/2014	June 2014 OSDF Inspection	HS11			
2057	In drain coming out of southeast corner.	No	Cottonwoods in cattails	6/4/2014	June 2014 OSDF Inspection	HS12			
2058	South drain, quarter way across berm on rocks	No	Honeysuckle	6/4/2014	June 2014 OSDF Inspection	HS13			
2059	South drain, near southwest corner	No	willow and honeysuckle in the cattails	6/4/2014	June 2014 OSDF Inspection	HS14			
2060	In drain on the berm	No	Cedar, cananda thistle, box elder, honeysuckle	6/4/2014	June 2014 OSDF Inspection	HS15			
2061	Prairie pocket at south end next to gate	No	Canada and musk thistle	6/4/2014	June 2014 OSDF Inspection	HS16			
2062	Southwest corner in drain	No	Honeysuckle, rosa, bull thistle, pear, elm, canada thistle	6/4/2014	June 2014 OSDF Inspection	HS17			
2063	East drain in rocks at 4/3 split	No	Canada thistle	6/4/2014	June 2014 OSDF Inspection	HS18			
2064	In cattails	No	Cottonwood, green ash	6/4/2014	June 2014 OSDF Inspection	HS19			
2065	East drain cell 2 midway in rocks	No	Teasel	6/4/2014	June 2014 OSDF Inspection	HS20			
2066	East drain at cell 1 midway in rocks	No	Honeysuckle, pear	6/4/2014	June 2014 OSDF Inspection	HS21			
2067	East drain at cell 1 in cattails and rocks	No	Ash and thistle	6/4/2014	June 2014 OSDF Inspection	HS22			
2068	Northeast drain in rocks	No	Cherry, teasel, honeysuckle	6/4/2014	June 2014 OSDF Inspection	HS23			
2069	North drain above rocks in grasses	No	Rosa, honeysuckle, teasel	6/4/2014	June 2014 OSDF Inspection	HS24			
2070	North drain in cattails at old gate location	No	Ash tree	6/4/2014	June 2014 OSDF Inspection	HS25			
2071	North drain in grasses	No	teasel	6/4/2014	June 2014 OSDF Inspection	HS26			
2072	North drain at northwest corner	No	phragmites, teasel, ash	6/4/2014	June 2014 OSDF Inspection	HS27			
2073	North drain in grasses and rocks	No	Corylus, pear	6/4/2014	June 2014 OSDF Inspection	HS28			

No.	Location	GPS?	Maintenance Item Identified	Date Identified	Origin of Finding	Inspection Finding No.	Resolution	Date of Resolution	Comments
2074	West drain at culvert beside north west gate	No	honeysuckle and teasel	6/4/2014	June 2014 OSDF Inspection	HS29			
2075	West drain at cell 1 along fence	No	Ash, teasel, honeysuckle, orchard grass	6/5/2014	June 2014 OSDF Inspection	HS30			
2076	West outer drain at cell 2 midway in rocks of drainage	No	honeysuckle, canada thistle	6/5/2014	June 2014 OSDF Inspection	HS31			
2077	Behind VH 2 in outer west drain	No	honeysuckle, canada thistle, orchard grass, willow	6/5/2014	June 2014 OSDF Inspection	HS32			
2078	West outer drain midway between VH2 and VH3 in grasses	No	musk thistle, teasel	6/5/2014	June 2014 OSDF Inspection	HS33			
2079	Behind VH 3	No	Teasel, musk thistle, honeysuckle	6/5/2014	June 2014 OSDF Inspection	HS34			
2080	Between VH3 and VH4 in grasses	No	musk thistle	6/5/2014	June 2014 OSDF Inspection	HS35			
2081	West drain along fence south of 4/5 boundary	No	Cedar	6/5/2014	June 2014 OSDF Inspection	HS36			
2082	Just north and south of VH5 in grasses	No	musk thistle	6/5/2014	June 2014 OSDF Inspection	HS37			
2083	Half way between VH 5 and VH 6 in grass	No	Musk thistle, canada thistle	6/5/2014	June 2014 OSDF Inspection	HS38			
2084	Around and behind VH 6	No	musk thistle and honeysuckle	6/5/2014	June 2014 OSDF Inspection	HS39			
2085	South of VH 6, north of drain	No	musk thistle, teasel	6/5/2014	June 2014 OSDF Inspection	HS40			
2086	Just north of VH 7 and behind VH 7	No	musk thistle and teasel	6/5/2014	June 2014 OSDF Inspection	HS41			
2087	Around well south of VH 7	No	musk thistle	6/5/2014	June 2014 OSDF Inspection	HS42			
2088	At leachate line sign	No	asphalt	6/5/2014	June 2014 OSDF Inspection	HS43			old finding
2089	between drainage and fence at cell 8 (at owl box)	No	teasel, patch of trumpet creeper	6/5/2014	June 2014 OSDF Inspection	HS44			
2090	Behind VH8	No	musk thistle	6/5/2014	June 2014 OSDF Inspection	HS45			
2091	Southwest drainage	No	Teasel, willow, honeysuckle	6/5/2014	June 2014 OSDF Inspection	HS46			
2092	North perimeter fence line along SR 126	No	Could not locate sign	6/3/2014	June 2014 point-specific institutional controls inspection	NA			

No.	Location	GPS?	Maintenance Item Identified	Date Identified	Origin of Finding	Inspection Finding No.	Resolution	Date of Resolution	Comments
2093	east slope of basin NDAP4	No	Rill erosion from road into pond.	7/1/2014					Reported by CAWWT last winter.
2094	access path	No	low spot due to beaver dam is rutted and needs rock added.	7/1/2014					Reported by Mike Stott