

ROCKY FLATS ENVIRONMENTAL TECHNOLOGY SITE REGULATORY CONTACT RECORD

Date/Time: 06/17/02
06/18/02
06/25/02

Site Contact(s): C. J. Freiboth (KH) – (CJF-006)
Phone: (303) 966-2823

Regulatory Contact: James Hindman, CDPHE
Phone: (303) 692-3345

Agency: CDPHE

Purpose of Contact: State (CDPHE) concurrence on Room Groups 11, 12, and 13 Mechanical Disconnects – T0110119

Meeting Attendance

C. J. Freiboth, KH PM J. Hindman, CDPHE

Discussion

- (1) On June 17, 2002, at 1020, a copy of T0110119 – Building 444 Mechanically Disconnect Groups 11, 12, and 13 Equipment and Remove from Rooms was give to the State (Hindman). In addition, the State (Hindman) was notified of the intent to remove loose property.
- (2) On June 18, 2002, at 1107, update page 11 and attachment were faxed to the State (Hindman).
- (3) On June 25, 2002 at 1305, the State (Hindman) requested additional information related to Work Package T0110119. Specifically, (1) the Work Package identified equipment via the old property numbers and the Idle Equipment List which identifies RCRA equipment identifies new property numbers – A cross-walk is needed, and (2) Why does some of the equipment description include the word RCRA.
- (4) On June 25, 2002 at 1405, a cross-walk of the equipment was faxed to the State (Hindman).
- (5) On June 25, 2002 at 1410, the State (Hindman) agreed with the cross-walk supplied. In addition, clarification was provided that the RCRA designation was for circuit boards. Additional questions from the State (Hindman) included that (1) the HDIT 6. Should be checked yes. This will be changed in the work package. (2) The BWF

Contact Record 06/25/02

Rev. 2/7/02

DOCUMENT CLASSIFICATION
REVIEW WAIVER PER
CLASSIFICATION OFFICE

Page 1 of 2

ADMIN RECORD
B444-A-000008

1/2
CEX-105-01

requires HEPA filtration is required / change out after each use while the Respiratory Protection Selection On-The-Job Verification Worksheet requires HEPA cartridge replacement every 8 hours. This will be corrected to be consistent. (3) For all pieces of equipment where exhaust ventilation is removed, the State requested that the work package be modified to take Beryllium sampling (swipe) in the duct before the duct is capped and removed. If beryllium is detected in the duct, the State (Hindman) requested that the exhaust be isolated (blanked or filtration supplied) during remaining duct removal if the effluent does not go through any additional filtration (i.e. the exhaust goes directly outside to the environment unfiltered). This will be added to the work package instructions.

Pending incorporation of the changes into the work package, the State (Hindman) concurred with the performance of the work in accordance with the work package.

Contact Record Prepared By: C. J. Freiboth

Required Distribution:

R. DiSalvo, RFFO
S. MacLeod, RFFO
J. Legare, RFFO
N. Newell, CDPHE
S. Gunderson, CDPHE
T. Rehder, USEPA
C. Deck, K-H
C. Gilbreath, K-H 771
T. Hopkins, K-H 776

S. Nesta, K-H
D. Shelton, K-H
K. North, K-H ESS
A. Rosenman, K-H ESS
J. Mead, K-H ESS

Additional Distribution:

S. Tower, DOE
C. Freiboth, K-H
J. Hindman, CDPHE
D. Kruchek, CDPHE



N/N