

7394

G-000-1012.158

RESULTS OF WELL SAMPLING

12/27/95

DOE-0241-96
DOE-FN CITIZEN
2
LETTER




Department of Energy
Fernald Environmental Management Project
 P. O. Box 538705
 Cincinnati, Ohio 45253-8705
 (513) 648-3155

7394

DEC 27 1995
 DOE-0241-96

Mr. David Brate



Dear Mr. Brate:

The purpose of this letter is to provide you with the results of the water sampling of your well conducted by Fernald Environmental Restoration Management Corporation (FERMCO). The farm and house wells at [redacted] were sampled on October 13, 1995, in response to your request. The results of this sampling are expressed below in parts of uranium per billion parts of water (ppb), and picocuries of uranium per liter of water (pCi/L). Picocuries per liter are the units used to express groundwater data in the Site Environmental Report.

<u>Sampling Date</u>	<u>Uranium Concentration</u>	
	<u>(ppb)</u>	<u>(pCi/L)</u>
<u>Kitchen Tap</u>		
October 13, 1995	0.7	0.5
<u>Barn Well</u>		
October 13, 1995	0.8	0.5

For comparison, a groundwater study conducted by an independent consultant for the Fernald Site determined that background concentrations of naturally-occurring uranium in the groundwater for this area range from less than 0.1 ppb to 2.7 ppb (0.068 to 2.0 pCi/L). Also, a U. S. Geological Survey study (J.D. Hem, 1970, Geological Survey Water-Supply Paper 1473) reported a range of uranium concentration of less than 0.1 ppb to 10 ppb (0.068 to 6.8 pCi/L) in most natural water within the United States.

The Environmental Protection Agency (EPA) has proposed an interim drinking water standard for total uranium of 20 ppb (13.5 pCi/L). The uranium concentration in your samples are well below this limit and are within the range expected for naturally-occurring background uranium in this area.

1

7394

D. Brate

-2-

If you have any questions regarding the results reported to you in this letter or on any aspect of our environmental program, please contact me by phone (648-3137) at your convenience.

Sincerely,

Wally Quaider
Walter J. Quaider
Associate Director
Office of Safety & Technical Support

cc: Dale Shaw, resident

2