~~R-001-206.13~~
G-000-206.13

147

REQUEST FOR SPECIAL PROJECT SOIL SAMPLE ANALYSES - ANALYTICAL LABORATORIES

05-23-89

WMCO
4
DATA

REQUEST FOR SPECIAL PROJECT SOIL SAMPLE ANALYSES - ANALYTICAL LABORATORIES

(7) Project No.: SOIL
(8) SubProject No.: 0012
(12) Cust. Dept. Number: 0001
(9) Customer Name: RI/FS
(15) Date/Time Rcvd. 5/23/89 @ 1019 (In Lab.)

(4) Chain of Custody: Y
(5) Priority: 1 (1,2,3)
(6) Deadline Date:
(10) Charge (Account #):
(16) Sample Matrix: SOIL
(18) Sampled By: ASI/IT
(23) Est. Disposal Date:

(Sample Receiving Lab - Add to Comments:)
1. Send copy of results to R. Conner.
2. Send excess sample to ASI.
3. Expedite U and Th results.

(11) Cust. Sample No.	(13) Sampled From: Depth	(17) Date/Time Sampled	(19) Material Description "Outfall Pipe Line Spill" LOCATION ~~Coordinates~~	(14) Customer Request Number (R/A Control No.)	COMMENTS	(1) Computer Lab. No. Assigned (For SRL Use Only)
06344	0-6in.	5/22/89@ 1015	IN- MH-176-1 E-	40799	SAMPLES LISTED THIS R/A ARE TO BE SPLIT EQUALLY BY WMCO LAB (AFTER DRYING ETC.) FOR ANALYSIS BY WMCO LAB/ITLAB. CONTACT: WALTER WEICK 7383100 OR 5353206 WHEN SAMPLES BECOME AVAILABLE	
06349	12-18in.	5/22/89@ 1045	IN- MH-176-2 E-	40799		
			IN- E-			
			IN- E-			
			IN- E-			
			IN- E-			
			IN- E-			
			IN- E-			
			IN- E-			
			IN- E-			

(X) Analyses Requested:

A. X All SPECIAL PROJECT Analyses (# 1, 2, 3, 4, 5)
1. ____ Total U, XRF method (ppm)
2. ____ Total Th, XRF method (ppm)
3. ____ U-234, U-235, U-236, U-238 (pCi/g)
4. ____ Th-228, Th-230, Th-232 (pCi/g)
5. ____ Tc-99 (pCi/g)

(X) Other Analyses Requested:

2192

6-000-206.13

~~#1~~ 0149

REQUEST FOR SPECIAL PROJECT SOIL SAMPLE ANALYSES - ANALYTICAL LABORATORIES

(7) Project No.: SOIL
(8) SubProject No.: 0012
(12) Cust. Dept. Number: 0001
(9) Customer Name: RI/FS

(15) Date/Time Rcvd. 5/23/89 @1019 (In Lab.)

(4) Chain of Custody: Y
(5) Priority: 1 (1,2,3)
(6) Deadline Date:
(10) Charge (Account #):
(16) Sample Matrix: SOIL
(18) Sampled By: ASI/IT
(23) Est. Disposal Date:

(Sample Receiving Lab - Add to Comments:)
1. Send copy of results to R. Conner.
2. Send excess sample to ASI.
3. Expedite U and Th results.

(11) Cust. Sample No.	(13) Sampled From: Depth	(17) Date/Time Sampled	(19) Material Description "Outfall Pipe Line Spill" LOCATION ~~Coordinates~~	(14) Customer Request Number (R/A Control No.)	COMMENTS	(1) Computer Lab. No. Assigned (For SRL Use Only)
06348	6-12in	5/22/89@1040	~~IN~~ MH-176-2 ~~E~~	40800		890525-053
06358	12-18in	5/22/89@1355	~~IN~~ MH-176-5 ~~E~~	40800		890525-054
			IN- E-			
			IN- E-			
			IN- E-			
			IN- E-			
			IN- E-			
			IN- E-			
			IN- E-			
			IN- E-			

(X) Analyses Requested:

A. X All SPECIAL PROJECT Analyses (# 1, 2, 3, 4, 5)
1. ____ Total U, XRF method (ppm)
2. ____ Total Th, XRF method (ppm)
3. ____ U-234, U-235, U-236, U-238 (pCi/g)
4. ____ Th-228, Th-230, Th-232 (pCi/g)
5. ____ Tc-99 (pCi/g)

(X) Other Analyses Requested:

DEDt.

2

17

REQUEST FOR SPECIAL PROJECT SOIL SAMPLE ANALYSES - ANALYTICAL LABORATORIES

(7) Project No.: SOIL
(8) SubProject No.: 0012
(12) Cust. Dept. Number: 0001
(9) Customer Name: RI/FS

(15) Date/Time Rcvd. 5/23/89 @ 1019 (In Lab.)

(4) Chain of Custody: Y
(5) Priority: 1 (1,2,3)
(6) Deadline Date:
(10) Charge (Account #):
(16) Sample Matrix: SOIL
(18) Sampled By: ASI/IT
(23) Est. Disposal Date:

(Sample Receiving Lab - Add to Comments:)
1. Send copy of results to R. Conner.
2. Send excess sample to ASI.
3. Expedite U and Th results.

(11) Cust. Sample No.	(13) Sampled From: Depth	(17) Date/Time Sampled	(19) Material Description "Outfall Pipe Line Spill" LOCATION ~~Coordinates~~	(14) Customer Request Number (R/A Control No.)	COMMENTS	(1) Computer Lab. No. Assigned (For SRL Use Only)
06345	6-12 in.	5/22/89 @ 1020	MH-176-1	40797		
06346	12-18 in.	5/22/89 @ 1025	MH-176-1	40797		
06347	0-6 in.	5/22/89 @ 1035	MH-176-2	40797		
06350	0-6 in.	5/22/89 @ 1100	MH-176-3	40797		
06351	6-12 in.	5/22/89 @ 1105	MH-176-3	40797		
06352	12-18 in	5/22/89 @ 1110	MH-176-3	40797		
06353	0-6 in.	5/22/89 @ 1325	MH-176-4	40797		
06354	6-12 in.	5/22/89 @ 1330	MH-176-4	40797		
06355	12-18 in	5/22/89 @ 1335	MH-176-4	40797		
06356	0-6 in.	5/22/89 @ 1345	MH-176-5	40797		

(X) Analyses Requested:

A. ____ All SPECIAL PROJECT Analyses (# 1, 2, 3, 4, 5)
1. X Total U, XRF method (ppm)
2. X Total Th, XRF method (ppm)
3. ____ U-234, U-235, U-236, U-238 (pCi/g)
4. ____ Th-228, Th-230, Th-232 (pCi/g)
5. ____ Tc-99 (pCi/g)

(X) Other Analyses Requested:

____ ____
____ ____
____ ____
____ ____
____ ____
____ ____

3

147

REQUEST FOR SPECIAL PROJECT SOIL SAMPLE ANALYSES - ANALYTICAL LABORATORIES

(7) Project No.: SOIL
(8) SubProject No.: 0012
(12) Cust. Dept. Number: 0001
(9) Customer Name: RI/FS

(15) Date/Time Rcvd. 5/23/89 @ 1019 (In Lab.)

(4) Chain of Custody: Y
(5) Priority: 1 (1,2,3)
(6) Deadline Date:
(10) Charge (Account #):
(16) Sample Matrix: SOIL
(18) Sampled By: ASI/IT
(23) Est. Disposal Date:

(Sample Receiving Lab - Add to Comments:)
1. Send copy of results to R. Conner.
2. Send excess sample to ASI.
3. Expedite U and Th results.

(11) Cust. Sample No.	(13) Sampled From: Depth	(17) Date/Time Sampled	(19) Material Description "Outfall Pipe Line Spill" LOCATION ~~Coordinates~~	(14) Customer Request Number (R/A Control No.)	COMMENTS	(1) Computer Lab. No. Assigned (For SRL Use Only)
06357	6-12in.	5/22/89@1350	~~IN~~ MH-176-5 ~~E~~	40798		
06359	0-6in	5/22/89@1405	~~IN~~ MH-176-6 ~~E~~	40798		
06360	6-12in	5/22/89@1410	~~IN~~ MH-176-6 ~~E~~	40798		
06361	12-18in.	5/22/89@1415	~~IN~~ MH-176-6 ~~E~~	40798		
			IN- E-			
			IN- E-			
			IN- E-			
			IN- E-			
			IN- E-			
			IN- E-			

(X) Analyses Requested:

A. ____ All SPECIAL PROJECT Analyses (# 1, 2, 3, 4, 5)
1. X Total U, XRF method (ppm)
2. X Total Th, XRF method (ppm)
3. ____ U-234, U-235, U-236, U-238 (pCi/g)
4. ____ Th-228, Th-230, Th-232 (pCi/g)
5. ____ Tc-99 (pCi/g)

(X) Other Analyses Requested:

OVER.