DOE/RFO
CORRESPONDENCE
INCOMING LETTER

92 DOE 14558

ACTION
Schassburger
ORGAN. #

DUE DATE 10/7/92

	LTR	ENC
VAETH, TA		
PAUOLE, AH		
BISHOP, ML		
BRAINARD, B		
HARTMAN, J	X	
IZELL, K		
KAROL, MS		
McBRIDE, MH		
SARGENT, D		
SIMONSON, DP		
WITHERILL, VF		
ADAMS, JJ		
ANDERSON, TW		
CRAUN, RL		
DUFFY, GG		
LEVERNIER, RJ		
LOCKHART, FR	X	
LUKOW, TE		
OLINGER, S		
RASK, WC		
RUSCITTO, DG		
SCHASSBURGER	X	
GRETHEL, T		
HARGREAVES, M		
HUFFMAN, GN		
MALCHESKI, D		
McCORMICK, MS		
MILLER, HG		
NELSON, G		
NISHIMOTO, GI		
OSTMEYER, RM		
PIETSCH, E		
POSLUSZNY, J		
RAMPE, J		
REECE, R		
STEWARD, JD		
VANDERPUY, M		
WALLIN, B		
WIENAND, J		
Birk	X	
W/P	X	
RECORDS	X	X

NOTE:

RECEIVED FOR ADDRESSEE
BY: DATE:
9/22/92

ROY ROMER
Governor

PATRICIA A. NOLAN, MD, MPH
Executive Director

Hazardous Materials and Waste Management Division
4210 East 11th Avenue
Denver, Colorado 80220-3716
(303) 331-4830 / FAX (303) 331-4401

Telefax Numbers:
Main Building, Denver
(303) 322-9076
Ptarmigan Place, Denver
(303) 320-1529
First National Bank Building, Denver
(303) 355-6559
Grand Junction Office
(303) 248-7198
Pueblo Office
(719) 543-8441

RADO
MENT
ALTH

September 21, 1992

Mr. Frazer Lockhart
Department of Energy
Rocky Flats Office
P.O. Box 928
Golden, CO 80402-0928

000020773

RECEIVED
U.S. DOE
MAIL ROOM
92 SEP 23 A 7:18

RE: Explosive Gas Monitoring at the Present Landfill (IHSS 114)

Dear Mr. Lockhart,

We have become aware that gas venting/monitoring wells were recently installed within the present landfill, which is a regulated hazardous waste unit. The Colorado Department of Health, Hazardous Materials and Waste Management Division, was not notified prior to this action. This action may have compromised the integrity of the landfill and raises concerns about its continued use.

The Division requests that you provide us with information in regard to the following issues:

1. What was the disposition of the drill cuttings?
2. Because these wells were drilled to bedrock, what steps were taken to ensure that no contamination reached bedrock aquifers? How were these wells completed in relation to the top of the bedrock?
3. Has water accumulation been monitored?
4. What gasses are being monitored and what are the monitoring methods and schedule?
5. What are the anticipated effects on the OU 7 Field Sampling Plan?

Please provide the requested information by October 9, 1992. If you have any questions concerning these issues, please contact Carl Spreng of my staff at 331-4457 (or 692-3358 after October 1, 1992).

Sincerely,

Gary W. Baughman

Gary W. Baughman, Chief
Facilities Section
Hazardous Waste Control Program

cc: Daniel S. Miller, AGO
Bob Birk, DOE
Tim O'Roarke, EG&G
Martin Hestmark, EPA
Jackie Berardini, CDH-OE