8945

RRES. CONTROL
TGOING LTR NO.
91 RF 5010

EG&G ROCKY FLATS

| DIST. | LTR | INC |
|---|---|---|
| T7 | | |
| TI JE, A.H. | | |
| P, R.D. | | |
| UCHER, D.W. | | |
| VID, J.G. | | |
| RED, J.E. | X | |
| RERA, D.W. | | |
| RIS, L.R. | | |
| KOR, F.J. | | |
| NCIS, G.E. | X | |
| DOWIN, R. | | |
| LY, T.J. | | |
| KER, E.H. | | |
| S, J.P. | | |
| LE, P.B. | | |
| ISH, J.M. | | |
| BY, W.A. | | |
| KEBO, J.A. | | |
| E.M. | X | |
| JESTIC, J.R. | | |
| THEWS, T.A. | | |
| URRENS, B.E. | | |
| RGAN, R.V. | X | |
| RTH, P. | | |
| MER, L.A. | | |
| TTER, G.L. | X | |
| ZUTO, V.M. | | |
| DADES, J.L. | X | |
| FELL, B.F. | | |
| ANSON, E.R. | | |
| BE, J.S. | | |
| KINSON, R.B. | | |
| LIAMS, R.E. | | |
| SON, J.M. | | |
| NG, E.R. | | |
| NE, J.O. | | |
| | | |
| NDT, [illegible] | X | |
| SB[illegible] | X | |
| AN, [illegible] | | |
| NGMAN, J.W. | X | |
| DBERG, R.D. | | |
| RTER, R.G. | | |
| TH, D.M. | | |
| RRES CONTROL | X | X |
| FFIC | | |

| CLASSIFICATION: | | |
|---|---|---|
| NI | | |
| CLASSIFIED | X | |
| NFIDENTIAL | | |
| RET | | |

THORIZED CLASSIFIER SIGNATURE
E 8/8/91

IN REPLY TO LTR NO.
219-RF-91

AP[illegible]ALS
[illegible]
SA
NG & TYP[illegible] INITIALS
AA/[illegible]
16469 (REV. 3/91)

EG&G ROCKY FLATS, INC.
ROCKY FLATS PLANT, P.O. BOX 464, GOLDEN, COLORADO 80402-0464 • (303) 966-7000

August 8, 1991 91-RF-5010

Robert M. Nelson, Jr.
Manager
DOE, RFO

Attn: F. R. Lockhart

DEPARTMENT OF ENERGY CONCERNS OVER SUBCONTRACTOR GROUNDWATER SAMPLING PROTOCOL (2219) - JEE-0199-91

Ref: F. R. Lockhart ltr (5780) to J. E. Evered, Observation of Ground Water Sampling, July 18, 1991

We are in receipt of your letter dated July 18, 1991, regarding concerns expressed by two of your staff observing groundwater sampling activities. Environmental Management (EM) is aware of the issues that were raised and is working to correct the problems.

The leaking VOA sampling nozzle is being modified to fit tighter into the bailers that are used for sampling. This should eliminate water flowing over the samplers hands.

Adequate field communications have been a chronic problem. Much of the terrain on plantsite does not allow direct line-of-site communication with subcontractor and EG&G base operations. The new radio system recently implemented on plantsite has eliminated most of the communication problems. Presently, EM has secured five new radios for the groundwater sample teams. However, to provide adequate communication for Health and Safety requirements a minimum of eight radios are required. EM anticipates acquiring the remaining three radios in the near future to minimize risk to the subcontractor sampling teams in the field.

If you have any additional questions regarding these or any other issues concerning the groundwater monitoring program, please contact Jim Langman at extension 5975.

J. E. Evered, Director
Environmental Management

GAA:csk

Orig. and 1 cc - R. M. Nelson, Jr.

DOCUMENT CLASSIFICATION
REVIEW WAIVER PER
CLASSIFICATION OFFICE

ADMIN RECORD

A-SW-001760