

## Contact Records Index

Additional files/attachments/figures supporting some contact records are available on the Contact Records webpage.

- CR-2016-04 Upgrade of the East Subsurface Drain Located in the East Perimeter Channel of the Original Landfill, with Soil Disturbance Review Plan
- CR-2016-03 Geoprobe Investigation of the Groundwater System Upgradient of the Original Landfill and the Soil Disturbance Review Plan
- CR-2016-02 Mound Site Plume Treatment System reconfiguration project Soil Disturbance Review Report and Explanation of Significant Differences
- CR 2016-01 Reportable condition for evaluation purposes for uranium at Walnut Creek Point of Compliance (WALPOC)
- CR 2015-10 Area of Concern Well 10304 Reportable Condition
- CR 2015-09 Soil Disturbance Review Plan for Solar Ponds Plume Treatment System Interim Configuration
- CR 2015-08 Solar Ponds Plume Treatment System Interim Design and Implementation
- CR 2015-07 Vinyl chloride results from the Present Landfill Treatment System (PLFTS) effluent triggered the consultative process
- CR 2015-06 Original Landfill (OLF) Implementation of Interim Action to Reestablish Surface Water Management on Portions of the OLF, with Soil Disturbance Review Plan
- CR 2015-05 Reportable condition for plutonium 12-month rolling average at Point of Evaluation SW027
- CR 2015-04 Mound Site Plume Treatment System (MSPTS) Reconfiguration Conceptual Approach
- CR 2015-03 Original Landfill (OLF) Immediate Response to Recent Precipitation
- CR 2015-02 Soil Disturbance Review Plan (SDRP) for Storage Shed Photovoltaic Upgrades
- CR 2015-01 Reportable condition for uranium 12-month rolling average at Point of Compliance WALPOC
- CR 2014-10 (rescinded) Reportable condition for uranium 12-month rolling average at Point of Compliance WALPOC
- CR 2014-09 Soil Disturbance Review Plan (SDRP) Update for Regrading the East Perimeter Channel (EPC) at the Original Landfill (OLF)
- CR 2014-08 Provide flexibility to the flow configuration at the Solar Ponds Plume Treatment System (SPPTS) as part of the ongoing optimization effort

## Contact Records Index

Additional files/attachments/figures supporting some contact records are available on the Contact Records webpage.

- CR 2014-07 Abandonment of Sentinel well 88104 at the Rocky Flats Site, Colorado
- CR 2014-06 Vinyl chloride results from the Present Landfill Treatment System (PLFTS) effluent triggered the consultative process
- CR 2014-05 Reportable condition for evaluation purposes for uranium at Point of Compliance WALPOC
- CR 2014-04 Approval of the installation and operation of an air stripper and the associated Rocky Flats Legacy Management Agreement (RFLMA) Soil Disturbance Review Plan as part of the reconfiguration of the East Trenches Plume Treatment System (ETPTS)
- CR 2014-03 Minor modification to the March 2008 Present Landfill (PLF) Monitoring and Maintenance Plan (M&M Plan)
- CR 2014-02 Minor Modification of Rocky Flats Legacy Management Agreement (RFLMA) Attachment 2, "Legacy Management Requirements"
- CR 2014-01 East Trenches Plume Treatment System (ETPTS) media removal and reconfiguration for air stripper treatment
- CR 2013-03 Soil Disturbance Review Plan (SDRP) for Regrading the East Perimeter Channel (EPC) and Associated Diversion Berms at the Original Landfill (OLF)
- CR 2013-02 Reportable Condition at the Original Landfill (OLF)
- CR 2013-01 GS10 Flume Replacement Project and Soil Disturbance Review Plan
- CR 2012-03 Minor Modification of *Rocky Flats Legacy Management Agreement* (RFLMA) Attachment 1, "Site Map," and of RFLMA Attachment 2, "Legacy Management Requirements"
- CR 2012-02 Improving Treatment at the East Trenches Plume Treatment System (ETPTS) by adding an air stripper component
- CR 2012-01 Soil Disturbance Review Plan – Roads Maintenance, including grading the road to former A-3 Pond to convert the road to two-track vehicle use
- CR 2011-08 Reportable Condition for Americium-241 (Am) at Rocky Flats Legacy Management Agreement (RFLMA) Point of Evaluation (POE) GS10
- CR 2011-07 Soil Disturbance Review Plan—Pond A-3 and Present Landfill (PLF) Pond Dam Breach Project

## Contact Records Index

Additional files/attachments/figures supporting some contact records are available on the Contact Records webpage.

- CR 2011-06 Soil Disturbance Review Plan—Roads upgrade project involving reconfiguration of a sharp curve west of Functional Channel 1
- CR-2011-05 Update for Reportable Condition for Uranium at Point of Evaluation GS10
- CR 2011-04 Reportable Condition for Uranium at Point of Evaluation GS10
- CR 2011-03 Resource Conservation and Recovery Act (RCRA) Well Monitoring Results at Original Landfill (OLF) and Present Landfill (PLF)
- CR 2011-02 Replace Sentinel Well 3370
- CR 2011-01 Replace Mound Site Plume Treatment System (MSPTS) Media and Maintain/Repair Discharge Gallery
- CR 2010-07 Monitoring Results and Water Treatment at the MSPTS and ETPTS
- CR 2010-06 Monitoring Results at Surface Water Point of Evaluation (POE) SW027
- CR 2010-05 Statistically Higher Concentrations of Analytes in Groundwater Downgradient of the Original Landfill (OLF) and Present Landfill (PLF)
- CR 2010-04 Rocky Flats Legacy Management Agreement Attachment 2: Modification to Revise Monitoring Points
- CR 2010-03 Non-Rocky Flats Legacy Management Agreement (RFLMA) Surface Water Monitoring Project for North and South Walnut Creeks
- CR 2010-02 Approval of Excavation Greater than 3-Foot Below Grade to Breach Dams A-3, A-4, B-5, C-2, and the Present Landfill Dam
- CR 2010-01 Targeted Soil Sampling at the Original Landfill (OLF) to Evaluate Residual Contamination Levels in Relation to the Colorado Department of Public Health and Environment's (CDPHE) August 2008 Policy, End of Post-Closure Care
- CR 2009-05 Installation of Snow Fencing North of the Original Landfill (OLF) and Approval of Work After Closeout of Contact Record
- CR 2009-04 Replace East Trenches Plume Treatment System (ETPTS) Media and Make Minor Changes to the Piping Configuration
- CR 2009-03 Soil Disturbance for Road Maintenance and Improvement Work Involving the Construction of Roadside Drainage Ditches that Will Not Return Excavation to Preexisting Grade
- CR 2009-02 Excavation by Xcel Energy for Valve Replacement on 12-Inch Golden Pipeline

## Contact Records Index

Additional files/attachments/figures supporting some contact records are available on the Contact Records webpage.

- CR 2009-01 Phase II and III Upgrades to Solar Ponds Plume Treatment System
- CR 2008-09 Revision of Sampling Locations to Reflect Site Reconfiguration
- CR 2008-08 Construction of Collection Sump For SPPTS
- CR 2008-07 Path Forward for Original Landfill (OLF) Seep 7 Drain Extension, Berm Maintenance and Repair, Perimeter Channel Slope Cut and Fill, and Modification of the OLF Monitoring and Maintenance Plan (M&M Plan)
- CR 2008-06 Management of Intercepted Groundwater During SPPTS Repair or Maintenance Activities
- CR 2008-05 Boron and Uranium in Groundwater Downgradient of the Original Landfill
- CR 2008-04 Notification of Well Replacement and Well Identification Change
- CR 2008-03 Exploratory Excavations to Greater than 3 Feet Below Grade Generally Between the Former Interceptor Trench Pump House and Solar Ponds Plume Treatment System
- CR 2008-02 Discussion and Approval Of Excavation Greater than 3 Feet Below Grade to Breach Dams A-1, A-2, B-1, B-2, B-3, and B-4
- CR 2008-01 Completion of Additional Ecological Sampling in Accordance With RFLMA Attachment 2, Table 5
- CR 2007-08 Changes to Present Landfill Inspection and Monitoring Frequencies and Modification of the PLF Monitoring and Maintenance Plan
- CR 2007-07 Replacement of Monitoring Well 45605 (B991 Slump)
- CR 2007-06 Evaluation of Elevated Nitrate in Groundwater Samples From AOC Well B206989
- CR 2007-05 Grading the Slump Area South Of FC-4 and Former Building 991
- CR 2007-04 Discussion and Approval of Soil Disturbance for Phase III Road Improvement Work Involving the Construction Of Roadside Drainage Ditches that Will Not Return Excavation to Preexisting Grade
- CR 2007-03 Discussion and Approval of Excavation Greater than 3 Feet Below Grade in FC-1 Soil Borrow Area and Placement of Soil South of Former B371 Location to Eliminate Ponding Around Well Heads for Wells 33502, 33604, and 33703

## **Contact Records Index**

Additional files/attachments/figures supporting some contact records are available on the Contact Records webpage.

- CR 2007-02 Discussion and Approval of Exploratory Excavations to Greater than 3 Feet Below Grade Around the Former Interceptor Trench Pump House
- CR 2007-01 Notification of Adverse Biological Condition, March 27, 2007, Central Operable Unit (COU) Boundary Fence Wildlife Deaths
- CR 2006-03 Disposition February–July 2006 Monitoring Results for Arsenic at the Present Landfill Treatment System (PLFTS)
- CR 2006-02 Disposition December–July 2006 Monitoring Results for Boron at the Present Landfill Treatment System (PLFTS)
- CR 2006-01 Disposition December 2005–May 2006 Monitoring Results for Manganese at the Present Landfill Treatment System (PLFTS)