

3769

**OHIO EPA REVIEW COMMENTS**

XX-XX-XX

OHIO EPA REVIEW COMMENT

Comment: One concern that we have involves the coordination between this removal action and plans to use waste materials from Pit 5 for a bench and pilot scale vitrification project. How will the waste materials be removed from Pit 5 without disturbing the water cover that this removal action will establish?

Response: The waste material can be removed from Waste Pit 5 without disturbing the water cover by submerging the auger head of the dredge used for this removal action under the surface of the water to collect the required sample material necessary for the vitrification bench and pilot scale projects.

Resolution: No resolution is necessary.