

7163

R-009-207.80

REPAIR OF DAMAGED SOUTH PLUME RECOVERY WELL SCREENS

09/06/95

USEPA

DOE-FN

1

COMMENTS



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY
REGION 5
77 WEST JACKSON BOULEVARD
CHICAGO, IL 60604-3590

7163

FERNALD
LOG I-3580
SEP 13 10 38 AM '95

FILE: _____
REPLY TO THE ATTENTION OF: _____
LIBRARY: _____

SEP 06 1995

Mr. Jack R. Craig
United States Department of Energy
Feed Materials Production Center
P.O. Box 398705
Cincinnati, Ohio 45239-8705

HRE-8J

RE: Repair of Damaged South Plume
Recovery Well Screens

Dear Mr. Craig:

The United States Environmental Protection Agency (U.S. EPA) has completed its review of your July 31, 1995, letter concerning the recommendations for repair of the screens in the damaged south plume recovery wells. The letter proposes to place smaller telescoping screens within the existing damaged well screens.

U.S. EPA approves the installation of the new screens.

Please contact me at (312) 886-0992 if you have any questions regarding this matter.

Sincerely,

James A. Saric, Remedial Project Manager
Technical Enforcement Section #1
RCRA Enforcement Branch

cc: Tom Schneider, OEPA-SWDO
Jack Baublitz, U.S. DOE-HDQ
Don Ofte, FERMCO
Charles Little, FERMCO
Terry Hagen, FERMCO
Michael Yates, FERMCO