



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY  
REGION 5  
77 WEST JACKSON BOULEVARD  
CHICAGO, IL 60604-3590

3165

FERNALD

LOG A-1665

AUG 1 9 55 AM '00

JUL 31 2000

FILE  
REPLY TO THE ATTENTION OF \_\_\_\_\_  
LIBRARY \_\_\_\_\_

SRF-5J

Mr. Johnny W. Reising  
United States Department of Energy  
Feed Materials Production Center  
P.O. Box 398705  
Cincinnati, Ohio 45239-8705

RE: Aquifer Re-injection  
Test Report

Dear Mr. Reising:

The United States Environmental Protection Agency (U.S. EPA) has completed its review of the United States Department of Energy's (U.S. DOE) aquifer re-injection test report.

This document presents the results of a year-long groundwater re-injection demonstration conducted at the site.

The report adequately describes the information obtained during the demonstration, and U.S. EPA concurs with U.S. DOE's conclusion that re-injection should continue and be included as part of the groundwater remedy at the site.

Please contact me at (312) 886-0992 if you have any questions regarding this matter.

Sincerely,

James A. Saric  
Remedial Project Manager  
Federal Facilities Section  
SFD Remedial Response Branch #2

cc: Tom Schneider, OEPA-SWDO  
Bill Murphie, U.S. DOE-HDQ  
John Bradburne, Fluor Fernald  
Terry Hagen, Fluor Fernald  
Tim Poff, Fluor Fernald

**000001**