

## Southwest District Office

401 East Fifth Street  
Dayton, Ohio 45402-2911

TELE: (937) 285-6357 FAX: (937) 285-6404

Bob Taft, Governor  
Maureen O'Connor, Lt. Governor  
Christopher Jones, Director

June 7, 2002

Mr. Johnny Reising  
U.S. Department of Energy, Fernald Area Office  
P.O. Box 538705  
Cincinnati, OH 45253-8705

**Re: COMMENTS - Silo 3 Civil Site Package**

Dear Mr. Reising:

Ohio EPA has reviewed DOE's submittal, "Silo 3 Project Civil Site Package" received on May 24, 2002. Attached are our comments on the document.

If you have any questions, please contact me at (937) 285-6466.

Sincerely,



Thomas A. Schneider  
Fernald Project Manager  
Office of Federal Facilities Oversight

cc: Jim Saric, U.S. EPA  
Terry Hagen, FDF  
Mark Shupe, HSI GeoTrans  
Mary Wojceichowski, Tetra Tech EM Inc.  
Ruth Vandergrift, ODH

SEARCHED  
INDEXED  
SERIALIZED  
FILED  
JUN 10 A 11:12  
FERNALD  
LOG C-1342  
FILE: 6446.591

**OHIO EPA COMMENTS**  
**Silo 3 Project Civil Site Package**  
**JUNE, 2002**

1. Commenting Organization: Ohio EPA                      Commentor: OFFO  
Section #: General Comment      Pg #: na      Line #: na      Code: C  
Original Comment #:  
Comment: The document does not include waste disposal details. Please describe how and where Silo 3 materials will be disposed.  
Response:  
Action:
  
2. Commenting Organization: Ohio EPA                      Commentor: OFFO  
Section #: Drawing 94X-3900-G-01296      Pg #:na      Line #: na      Code: C  
Original Comment #:  
Comment: Please explain the reasoning behind the surgical removal of concrete pad areas around Silo 3.  
Response:  
Action:
  
3. Commenting Organization: Ohio EPA                      Commentor: OFFO  
Section #: Drawing 94X-3900-G-01297      Pg #: na      Line #: na      Code: C  
Original Comment #:  
Comment: What is the purpose of the proposed 4' concrete ditch located just north of Silo 3 (reference #2)?  
Response:  
Action:
  
4. Commenting Organization: Ohio EPA                      Commentor: OFFO  
Section #: Drawing 94X-3900-G-01298      Pg #: na      Line #: na      Code: C  
Original Comment #:  
Comment: The silt fence located in the southern corner of Silo 3 (reference #3) is adequate, however additional silt fencing is needed around the Silo 4 area especially as runoff moves north of the silo.  
Response:  
Action: