

CORRES. CONTROL

OUTGOING LTR. NO.

DOE ORDER # 4700.1

04-RF-01257

DIST.	LTR	ENC
DIETER, T.J.		
FERRERA, D.W.	X	
LINDSAY, D.C.		
LONG, J.		
LYLE, J.L.		
MARTINEZ, L. A.		
PIZZUTO, V.M.		
SHELTON, D.C.		
SPEARS, M.S.		
TUOR, N. R.		

DEC 13 2004



04-RF-01257

BEAN, C.		
BUTLER, J. L.		
DECK, C.		
FOSS, D.		
FRANCIS, M.		
FREIBOTH, C.		
GEIS, A.		
GIBBS, F.	X	
HUMISTON, T.		
HUNTER, D.		
KNAPP, S.		
LINSINBGLER, H.		
MARSCHALL, J.R.		
MYERS, K.	X	X
NESTA, S.	X	X
NORTH, K.		
OMAN, K.		
PLAPPERT, R.		
PRIMROSE, A.		
RICHARDELLA, R.		
SNYDER, D.P.		
SWARTZ, J.M.	X	X
WARD, D.A.		
WIEMELT, K.		
SELAN, J.		
SILLS, S.		

Gary Morgan, Functional Lead  
Cadre Project Management Division  
DOE, RFPO

RSOP FOR FACILITY DISPOSITION - NOTIFICATION LETTER FOR BUILDING 528  
FEG-046-04

In accordance with the Rocky Flats Cleanup Agreement Standard Operating Protocol (RSOP) for Facility Disposition, this letter and its attachments is notification for RSOP implementation. This notification is for all activities required to demolish and disposition Building 528.

Please contact Steve NESTA x6386 with questions or concerns.

*Frank E. Gibbs*  
Frank E. Gibbs  
Deputy Project Manager  
Remediation, Industrial D&D, and Site Services

Attachment:  
As Stated

KLM:pvt

Orig. and 1 cc - Joe Legare

CORRES. CONTROL	X	X
ADMIN RECRD/T130G	X	X
TRAFFIC		
PATS/130		

CLASSIFICATION:	
UCNI	
UNCLASSIFIED	
CONFIDENTIAL	
SECRET	

AUTHORIZED CLASSIFIER  
SIGNATURE:

Date:

IN REPLY TO RFP CC NO.:

ACTION ITEM STATUS:


PARTIAL/OPEN  
 CLOSED

LTR APPROVALS:

ORIG. & TYPIST INITIALS:

KLM:pvt

RF-46469 (Rev. 9/94)



ADMIN RECORD

Kaiser-Hill Company, L.L.C.  
Rocky Flats Environmental Technology Site, 10808 Highway 93, Unit B, T130F, Golden, CO 80403-8200 ♦ (303) 966-6386

B559-A-000029

1/2

The scope of this demolition will include Building 528, the process waste pit for Building 559.

As stated in the Reconnaissance Level Characterization Report (RLCR), dated January 31, 2002, and approved by CDPHE on March 25, 2002, Building 528 was characterized as a Type 2 facility. The Pre-Demolition Survey Report (PDSR) - DWF-084-04, dated December 13, 2004, documents the condition of Building 528. As stated in the PDSR, B528 did not meet the unrestricted release criteria prior to application of a fixative; after the application of the fixative the building has the following radiological levels <94-600 dpm/100cm<sup>2</sup> fixed, <20 dpm/100cm<sup>2</sup> loose, and it will be demolished and disposition as low-level waste.

The point of contact for this project is Mike Swartz, who may be reached at x5107.

#### CERCLA Administrative File

- RCLR (January 31, 2002) approved March 25, 2002
- RSOP for Component Removal, Size Reduction, and Decontamination Activities Notification Letter for B528, B559 and B561 Component Removal (May 8, 2002), approved June 10, 2002
- PDSR for Building 528 – DWF-084-04 (submitted December 13, 2004)