

5144 RF 93



Department of Energy



ROCKY FLATS OFFICE
P O BOX 928
GOLDEN COLORADO 80402 0928

000313604

DEC 0 2 1993

93-DOE-13495

DUE
DATE

ACTION

DIST	LTR	ENC
BENEDETTI R L		
BENJAMIN, A		
BERMAN, H S		
CARNIVAL, G J		
COPP R D		
CORDOVA R C		
DAVIS J G		
FERRERA, D W		
FRANZ, W A		
HANNI B J		
HEALY T J		
HEDAHL T G		
HILBIG J G		
HUTCHINS N M	X	
JIRBY W A		
KUESTER A W		
MARAFFEY T W		
MANN H P		
MARX G E		
MCKENNA F G		
MORGAN R V		
PIZZUTO V M		
POTTER G L		
SANDLIN N B		
SATTERWHITE D G		
SCHUBERT A L		
SETLOCK G H		
SULLIVAN M T		
SWANSON E R		
WILKINSON R B		
WILSON J M		

Mr Martin Hestmark
U S Environmental Protection Agency, Region VIII
ATTN Rocky Flats Project Manager, 8HWM-FF
999 18th Street, Suite 500
Denver, Colorado 80202-2405

Mr Gary Baughman
Hazardous Waste Facilities Unit Leader
Colorado Department of Health
4300 Cherry Creek Drive South
Denver, Colorado 80222-1530

Gentlemen

On June 17, 1993, we sent you a letter (93-DOE-07070) where we agreed to notify you on a quarterly basis of periods of non-collection of water as a result of technical difficulties with the Operable Unit 2 Walnut Creek Interim Measure/Interim Remedial Action. Our last notification was June 24, 1993, (93-DOE-06773). This notification covers the period August through October 1993.

These events are summarized below

- August 3, 1993 generator problems, requiring 2 25 hours
- September 10, 1993 generator repair, requiring 25 minutes
- September 10, 1993 generator problems, requiring approximately 0 5 hours
- September 15, 1993 generator exchange/swap, requiring approximately 1 5 hours
- September 21, 1993 reaction tank TK-2 mixer failure, requiring approximately 3 25 hours
- October 6, 1993 generator oil change, requiring 1 25 hours
- October 11, 1993 generator problems, requiring 4 25 hours
- October 12, 1993 generator exchange/swap, requiring 5 5 hours

EG85
 ROCKY FLATS PLANT
 CORRESPONDENCE UNIT

Dec 6 12 21 PM '93

Premrose
A X

Ness TX

Busby WX

CORRES CONTROL	x	x
PATS/T130G		
ADMN RECORD/080	2	

Reviewed for Addressee
Corres Control RFP

12-693
DATE BY

Ref Ltr #

OE ORDER # 5400.1

ADMIN R

BZ-A-00086

M Hestmark & G Baughman
93-DOE-13495

2

DEC 0 2 1993

- October 18, 1993 clogged membrane required cleaning, requiring 4 75 hours
- October 31, 1993 generator oil change/problems, requiring 1 75 hours
- Weekly approximately one half hour per week for generator oil change

If you have any questions, please contact Scott Grace of my staff at (303) 966-7199 or Eric Dille at (303) 966-4651

Sincerely,



 Martin H McBride
Assistant Manager
Environmental Restoration

cc
A Rampertaap, EM-453
A Primrose, EG&G
T Vess, EG&G
B Fraser, EPA
J Schieffelin, CDH