

RECEIVED

Revised 10/03

CORRES. CONTROL
INCOMING LTR NO.

2003 OCT 20 P 1:42

STATE OF COLORADO

00976 RFO3

Bill Owens, Governor
Douglas H. Benevento, Executive Director

CORRESPONDENCE
CONTROL

Dedicated to protecting and improving the health and environment of the people of Colorado

DUE DATE
ACTION

4300 Cherry Creek Dr. S.
Denver, Colorado 80246-1530
Phone (303) 692-2000
TDD Line (303) 691-7700
Located in Glendale, Colorado

Laboratory and Radiation Services Division
8100 Lowry Blvd.
Denver, Colorado 80230-6928
(303) 692-3090



Colorado Department
of Public Health
and Environment

<http://www.cdphe.state.co.us>

DIST.	LTR	ENC
BERARDINI, J. H.	X	
BOGNAR, E. S.	X	
BROOKS, L.	X	
BUTLER, L.	X	
CROCKETT, G. A.		
DECK, C. A.	X	
DEGENHART, K. R.		
DIETER, T. J.		
DIETERLE, S. E.		
FERRERA, D. W.	X	
GIACOMINI, J. J.		
HIETT, S. B.	X	
ISOM, J. H.		
LINDSAY, D. C.	X	
LONG, J. W.		
LYLE, J. L.		
MARTINEZ, L. A.	X	
NAGEL, R. E.	X	
NORTH, K.	X	
PARKER, A. M.	X	
RODGERS, A. D.		
SHELTON, D. C.	X	
SPEARS, M. S.		
TRICE, K. D.		
TUOR, N. R.	X	
WILLIAMS, J. L.		
ZAHM, C.	X	
Westa, S.	X	
Freiboth, C.	X	
Wienand, P. K.	X	

October 14, 2003

Mr. Joe Legare
Acting Assistant Manager for Environment and Stewardship
U.S. Department of Energy, Rocky Flats Field Office
10808 Highway 93, Unit A
Golden, CO 80403-8200

RE: Closeout Reports for Buildings 125, 442 L & W, 452, 662, 663, 850, 864, and Trailers 452A, B, C, D, E, & G, 886B & C, 891E, P, & Q, and 893A & B

Dear Mr. Legare:

The Colorado Department of Public Health and Environment, Hazardous Materials and Waste Management Division has reviewed the Closeout Reports for Buildings 125, 442 L & W, 452, 662, 663, 850, 864, and Trailers 452A, B, C, D, E, & G, 886B & C, 891E, P & Q, 893A & B. All of these facilities have previously been identified as Type 1 facilities. Your letter, dated November 7, 2002, and the Closeout Reports for these facilities were received on November 14, 2002. In your letter, Trailer 891E appears to have been incorrectly identified as 893E. We appreciate being provided these Closeout Reports for our information, review and comments.

We previously provided comments regarding these reports via emails in November 2002, as well as in numerous discussions. Our previous concerns were related to the inadequate discussions regarding contamination identified and lack of appropriate discussion and maps showing the remaining infrastructure. Due to later ER activities some of these concerns have since been addressed in the ER Closure Reports for several of these facilities. However, we still have the following comments:

1. Closeout Reports should properly identify all removal activity and include a map of the facility identifying the structures involved, those removed, and the location of remaining infrastructure and its condition. Infrastructure includes all remaining materials and their location, and includes slabs, piers, footings, water pipes, gas lines, electrical conduits, drain lines, PWLs, sewer lines, etc. These maps are necessary for possible ER and/or future stewardship concerns.
2. The information provided does not specifically indicate if the basement of B850 was completely removed, as we believe it was, nor the locations or condition of the remaining/plugged piping and drains. As such, a more detailed discussion and a map should be provided.
3. The discussions for the trailers should identify the specific utilities that were removed (electrical, water, sewer, etc), the infrastructure remaining (asphalt pad, concrete pad, etc), as well as provide appropriate maps of these areas.

COR. CONTROL	X
ADMN. RECORD	X
PATS/130	

Reviewed for Addressee
Corres. Control RFP

10/20/03
Date By

Ref. Ltr. #

DOE ORDER #

5400.1

DOCUMENT CLASSIFICATION
REVIEW WAIVER PER
CLASSIFICATION OFFICE


ADMIN RECORD
IA-A-001705

1/2

4. Section C for B125 does not appear to include the disposition of the concrete slab, as concrete is not identified with any of the material discussed. The disposal of the concrete slab as discussed in Section A, should be identified in Section C.
5. The contamination found associated with the 452 trailers (T452B?) is not reflected in this discussion or the waste disposal. This should be properly addressed since at least some of the cement blocks and tiedowns that were being used to support the trailers were disposed as LLW, as was at least some of the slab under the trailers.

If you have any questions regarding this correspondence please contact me at (303) 692-3367 or David Kruchek at (303) 692-3328.

Sincerely,


Steven H. Gunderson
RFCA Project Coordinator

cc: Steve Tower, DOE
Tim Rehder, EPA
Karen Wiemelt, KH
David Abelson, RFCLOG

Cameron Freiboth, KH
Dave Shelton, KH
Steve Nesta, KH
Administrative Records Building T130G

OCT 7 2003
RECORDS CENTER

12/12