

RECEIVED

CORRES. CONTROL
INCOMING LTR NO.

00302 RFD5

DUE DATE

ACTION



Department of Energy

2005 JUN 13 P 3:27

ROCKY FLATS PROJECT OFFICE
12101 AIRPORT WAY, UNIT A
BROOMFIELD, COLORADO 80021-2583

CORRESPONDENCE
CONTROL

JUN - 7 2005

05-DOE-00354

DIST.	LTR	ENC
BERARDINI, J.H.	X	
BOGNAR, E.S.	X	
BROOKS, L.	X	
CARPENTER, M.	X	
CIUCCI, J.A.		
CROCKETT, G. A.	X	
DECK, C. A.	X	
DEGENHART, K. R.	X	
DEL VECCHIO, D.		
FERRERA, D. W.	X	
GIACOMINI, J. J.		
GILPIN, H.		
LINDSAY, D. C.	X	
LONG, J. W.		
NESTA, S.	X	
SHELTON, D. C.	X	
SPEARS, M. S.		
TUOR, N. R.	X	
WARD, D.	X	
WIEMELT, K.	X	
ZAHM, C.	X	
Freiboth, C.	X	

Mr. Steven H. Gunderson
Rocky Flats Cleanup Agreement Project Coordinator
Colorado Department of Public Health and Environment
4300 Cherry Creek Drive South
Denver, Colorado 80246-1530

Dear Mr. Gunderson:

Please find enclosed the Reconnaissance Level Characterization Report/Pre-Demolition Survey Report for Building 331 Garage, DWF-036-05. This report characterizes the physical, chemical and radiological hazards associated with this facility, summarizes the characterization activities, defines the Data Quality Objectives developed for this characterization, and presents the data quality assessment, verification and validation of the results. Building 331 had been anticipated to be a Type 2 facility, but a Reconnaissance Level Characterization was not previously performed due to the facility being in operation, rendering significant areas inaccessible. Performance of the Reconnaissance Level Characterization and the Pre-Demolition Survey (RLC/PDS) were performed in accordance with the Pre-Demolition Survey Plan (MAN-127-PDSP); therefore, no further characterization of this structure is necessary.

The RLC/PDS results indicate that no beryllium contamination exist in excess of the PDSP unrestricted release limits. The radiological surveys of the building were less than the PDSP unrestricted release limits; however, two trenches and five inaccessible, embedded floor drains are potentially contaminated and will either be managed as Low Level Waste or surveyed during demolition to verify they meet the unrestricted release criteria and then managed as sanitary waste. Asbestos abatement has been completed except for the exterior window caulking and transite panels which will be completed prior to demolition.

Based upon this RLCR/PDSR and subject to concurrence by the Colorado Department of Public Health and Environment, B331 Garage is a Rocky Flats Cleanup Agreement Type 2 Facility pursuant to the Rocky Flats Environmental Technology Site Decommissioning Program Plan (DPP; K-H, 1999) due to the potentially contaminated floor drains and trenches and is ready for demolition.


COR. CONTROL	X
ADMIN. RECORD	X
PATS	

Reviewed for Addressee
Corres. Control RFP

6-13-05 JB
Date By

Ref. Ltr. #
DWF03605

DOE ORDER #
5400.1



ADMIN RECORD

Mr. Steven H. Gunderson
05-DOE-00354

2

JUN - 7 2005

Questions may be directed to Gary Morgan, Rocky Flats Project Management, at
(303) 966-6003.

Sincerely,



John J. Rampe, Director
RFPO Project Management

Enclosure

cc w/o Encl:

S. Nesta, K-H RISS Env
C. Freiboth, K-H RISS D&D
K. Wiemelt, K-H RISS D&D
M. Aguilar, USEPA
D. Abelson, RFCLOG

cc w/Encl:

G. Morgan, RFPM, RFPO
D. McCranie, HQCPM, RFPO
Administrative Record