


RECEIVED



2001 MAY 24 P 1 34 Department of Energy

CORRESPONDENCE
CONTROL

ROCKY FLATS FIELD OFFICE
10808 HIGHWAY 93 UNIT A
GOLDEN COLORADO 80403-8200

MAY 23 2001

01 DOE 00849

Mr Steven Gunderson
Rocky Flats Cleanup Agreement Project Coordinator
Colorado Department of Public Health and Environment
4300 Cherry Creek Drive South
Denver Colorado 80246 1530

In accordance with the Rocky Flats Cleanup Agreement (RFCA) requirement in Attachment 5 Subpart 2 4(B) *Actions Determinations* we are providing two copies of the enclosed Source Evaluation Report for RFCA Point of Evaluation (POE) SW027 Specifically this report addresses the September 12 2000 notification of reportable 30-day moving averages for plutonium (Pu) water-quality results in the South Interceptor Ditch (SID) The associated reportable values were measured at the RFCA POE SW027 monitoring location on the SID just upstream of Pond C 2 for the periods June 26 29 2000 July 18 21 2000 and August 18 20 2000 This Source Evaluation Report fulfills the commitment outlined in our notification letter to you dated September 6 2000

Briefly the enclosed report identifies only diffuse radionuclide contamination from past Rocky Flats Environmental Technology Site operations as the possible cause of these reportable values No specific recommendations for source control are proposed in response to these measured values Our proposed course of action includes 1) continued monitoring 2) integration of these results to support progress on the Actinide Migration Evaluation and 3) stormwater control

If you have any questions concerning this report, please contact me at (303) 966-5918 or Glenn Doyle at (303) 966-3087

Sincerely

A handwritten signature in black ink, appearing to read "J. Legare".

Joseph A. Legare
Assistant Manager
for Environment and Infrastructure

Enclosure (2 copies)

Mr Steven Gunderson
01 DOE-00849

2

MAY 23 2001

cc w/o Enc
G Doyle AMEI RFFO
J Stover AI RFFO
D Shelton K H
R Ninninger K H

cc w/Enc
R DiSalvo OCC RFFO
L Brooks K H
CERCLA Administrative Record

RECEIVED

RF/EMM/WP-01 001 47
MARCH 2001

Revised 5/01

CORRES CONTROL
INCOMING LTR NO

02359 RF 01

DUE DATE
ACTION



2001 MAY 24 P 1 34
Department of Energy

CORRESPONDENCE
CONTROL

ROCKY FLATS FIELD OFFICE
10808 HIGHWAY 93 UNIT A
GOLDEN COLORADO 80403-8200

MAY 23 2001

01 DOE-00849

DIST	LTR	ENC
BOGENBERGER, V.		
BOGNAR, E.	✓	
BRAUNFORD, M.D.		
BURNS, T.F.		
CIAGLO, T.	✓	
DECK, C.A.	✓	
DIETERLE, S.E.		
FERRERA, D.W.		
FERRI, M.S.		
FRASER, R.G.		
FULTON, J.C.		
GERMAN, A.L.		
GIACOMINI, J.		
IBOM, J.H.		
LEONARD, R.C.		
MARTINEZ, L.A.	✓	
NOTES, J.I.		
NORTH, K.		
PARKER, A.M.		
POWERS, K.P.		
RAAZ, R.D.		
RODGERS, A.D.		
SANDLIN, N.B.	✓	
SCOTT, G.K.		
SHELTON, D.C.	✓	
SPEARS, M.		
TRICE, K.D.		
TUOB, N.B.		
VOORHEIS, G.M.		
<i>Brookland</i>	✓	
<i>Robbins, J.</i>	✓	
<i>Thompson, K.</i>	✓	

Mr Steven Gunderson
Rocky Flats Cleanup Agreement Project Coordinator
Colorado Department of Public Health and Environment
4300 Cherry Creek Drive South
Denver Colorado 80246 1530

In accordance with the Rocky Flats Cleanup Agreement (RFCA) requirement in Attachment 5 Subpart 2 4(B) *Actions Determinations* we are providing two copies of the enclosed Source Evaluation Report for RFCA Point of Evaluation (POE) SW027 Specifically this report addresses the September 12 2000 notification of reportable 30-day moving averages for plutonium (Pu) water-quality results in the South Interceptor Ditch (SID) The associated reportable values were measured at the RFCA POE SW027 monitoring location on the SID just upstream of Pond C 2 for the periods June 26 29 2000 July 18 21 2000 and August 18 20 2000 This Source Evaluation Report fulfills the commitment outlined in our notification letter to you dated September 6 2000

Briefly the enclosed report identifies only diffuse radionuclide contamination from past Rocky Flats Environmental Technology Site operations as the possible cause of these reportable values No specific recommendations for source control are proposed in response to these measured values Our proposed course of action includes 1) continued monitoring 2) integration of these results to support progress on the Actinide Migration Evaluation and 3) stormwater control

If you have any questions concerning this report, please contact me at (303) 966-5918 or Glenn Doyle at (303) 966 3087

Sincerely

Glenn Doyle
Joseph A Legare
Assistant Manager
for Environment and Infrastructure

COR CONTROL	X	X
ADMN RECORD		
PATS/130		

Reviewed for Addressee
Corres Control RFP

5/24/01
Date By

Ref Ltr #

Enclosure (2 copies)

DOE ORDER # 702

1/3

DOCUMENT CLASSIFICATION
REVIEW WAIVER PER
CLASSIFICATION OFFICE



ADMIN RECORD
SW-A-004200