



Department of Energy

ROCKY FLATS FIELD OFFICE
10808 HIGHWAY 93, UNIT A
GOLDEN, COLORADO 80403-8200

01-DOE-00055

JAN 31 2001

Mr. Timothy Rehder
Rocky Flats Team Lead
U.S. Environmental Protection Agency, Region VIII
999 18th Street, Suite 500, EPR-FT
Denver, Colorado 80202-2450

Mr. Steven Gunderson
Rocky Flats Cleanup Agreement Project Coordinator
Colorado Department of Public Health and Environment
4300 Cherry Creek Drive South
Denver, Colorado 80246-1530

Dear Gentlemen:

Enclosed is a copy of the Quarterly Report for the Rocky Flats Groundwater Plume Treatment Systems, October through December 2000. This quarterly report describes the activities and provides the available performance monitoring data for the five groundwater collection and treatment systems at the Rocky Flats Environmental Technology Site (Site). Three of the groundwater collection and treatment systems are reactive barriers designed to protect surface water. They include the Mound Site Plume, the East Trenches Plume, and the Solar Ponds Plume. Two other groundwater collection and treatment systems are currently operating at the Site. These are the Operable Unit (OU) 1 881 Hillside system and the OU 7 Present Landfill Seep Collection system.

If you should have any technical questions regarding this report, please contact Norma I. Castaneda of my staff at (303) 966-4226 or contact me at (303) 966-5918.

Sincerely,

Joseph A. Legare
Assistant Manager
for Environment and Infrastructure



Enclosure

1/2

DO NOT WRITE IN THESE SPACES
CLASSIFICATION

ADVISORY BOARD
SW-B-000017

Mr. Timothy Rehder
Mr. Steven Gunderson
01-DOE-00055

2

JAN 31 2001

cc w/Enc:
S. McMullin, EM-50, SRO
C. Lanigan, EM-50, SRO
N. Castaneda, ERWM, RFFO
G. Kleeman, EPA
C. Spreng, CDPHE
E. Pottorff, CDPHE
N. Korte, Oak Ridge National Laboratory
B. Dwyer, Sandia National Laboratory
M. Harlow, City of Westminster, CO
J. Brown, Bechtel Idaho
T. Ivory, Concurrent Technologies
Administrative Record

2/2