

1084

**PLANT 1 PAD EXPEDITED MAINTENANCE  
PROJECT**

**11-30-90**

**DOE/WMCO**

**DOE-234-91**

**2**

**LETTER**



**Department of Energy**

**FMPC Site Office**  
P.O. Box 398705  
Cincinnati, Ohio 45239-8705  
(513) 738-6319

1084

NOV 30 1990  
DOE-234-91

Mr. W. H. Britton, President  
Westinghouse Materials Company  
of Ohio  
P. O. Box 398704  
Cincinnati, OH 45239-8704

Dear Mr. Britton:

**PLANT 1 PAD EXPEDITED MAINTENANCE PROJECT**


The DOE has determined that the Plant 1 Pad expedited maintenance project did not constitute a removal action as defined in Section 101 of the Comprehensive Environmental Response, Compensation and Liability Act (CERCLA), as amended, 42 U.S.C. Section 9601.

The expedited maintenance project was undertaken by WMC0 to repair deteriorated concrete areas of the Plant 1 Pad, to prevent possible injury to workers caused by driving fork lifts over the deteriorated surfaces. The project was not intended to clean up or otherwise respond to a release or threatened release of hazardous substances from the Plant 1 Pad. The expedited maintenance work included removing approximately four inches of concrete in various locations, placing the removed concrete/rubble in drums for sampling, and replacing with new concrete.

Please ensure that WMC0 issues a final report to DOE addressing the quantities of rubble generated, the sample results of drummed material, and the disposition of the removed pad material as soon as analytical data is available. This information will be included in the FMPC Administrative Record together with the Removal Site Evaluation being prepared for the Plant 1 Pad upgrade.

If your staff has any questions, please ask them to contact Carlos J. Fermaintt at extension 6157.

Sincerely,



Gerald W. Westerbeck  
EMPC Site Manager

DP-84:Fermaintt

cc:

S. W. Coyle, WMCO  
S. J. Dechter, WMCO  
J. T. Grumski, WMCO  
J. P. Hopper, WMCO  
E. D. Savage, WMCO  
R. S. Shirley, WMCO  
P. C. Weddle, WMCO  
S. H. Wolinsky, ASI