

1818

OU2 ADDITIONAL WORK (LANDFILL)

01-29-91

OEPA/DOE-FMPC

3

LETTER



State of Ohio Environmental Protection Agency

Southwest District Office

40 South Main Street
Dayton, Ohio 45402-2086
(513) 449-6357
FAX (513) 449-6249

1818

Richard F. Celeste
Governor

January 29, 1991

RE: OU2 ADDITIONAL WORK
(LANDFILL)

Mr. Andrew Avel
U.S. DOE - FMPC
P.O. Box 398705
Cincinnati, Ohio 45239-8705

Dear Mr. Avel:

In a letter dated November 21, 1990, Ohio EPA approved the Work Plan for additional work in OU2 with the exception of the sanitary landfill. DOE responded on January 16, 1991, with additional justification for not needing another boring in the original disposal area. Nevertheless, it is still the opinion of Ohio EPA that an additional sample should be collected in the middle of the area encircled by Weston CIS samples 1, 2, 4, & 5. Ohio EPA maintains that most of the Weston CIS samples are located on the periphery of the original disposal area. The proposed location is in the center of what is believed to be the original disposal area, as shown in Figure 1-3 of the Revised OU2 ISA (1-91). The sample would also allow TCLP analysis in an area in which it has not been conducted. The sample proposed by Ohio EPA will allow for a more complete characterization of the original disposal area. The approximate location of the sample suggested by Ohio EPA is marked on the attached copies of the Figure 1 from the OU2 Additional Sampling Plan and Figure 1-3 of the Revised Initial Screening of Alternatives document.

If you have any questions, please contact me.

Sincerely,


Graham E. Mitchell
DOE Coordinator

GEM/klj

Enclosure

cc: Catherine McCord, USEPA
Ed Schuessler, PRC
Lisa August, Geotrans.

Date Rec'd JAN 31 1991
Log E-1525
File 1
Library _____



602 A. EN04.012.1012.DR

FIGURE 1-3. SANITARY LANDFILL




FIGURE 1. APPROXIMATE SAMPLING LOCATIONS, SANITARY LANDFILL