

6655

G-000-601 .20


**(REVIEW OF REMEDIAL ACTIVITIES AT THE FEMP) - (USED AS
A REFERENCE IN OU2 AND OU5 RI REPORTS)**

07/26/90

**OHIO HIST SOC. DOE-FN
1
LETTER**

Ohio Historic Preservation Office

Ohio Historical Center
 1982 Veima Avenue
 Columbus, Ohio 43211-2497
 (614) 297-2470



OHIO
 HISTORICAL
 SOCIETY
 SINCE 1885

July 26, 1990

Behram Shroff
 Department of Energy
 FMPC Site Office
 P.O. Box 398705
 Cincinnati, Ohio 45239-8705

Re: Review of Remedial Activities at the Feed Materials Production Center

Dear Mr. Shroff:

This letter is in response to your correspondence dated June 25, 1990 concerning the project noted above. Much survey work has been done in the Hamilton County area and many sites have been found. The information provided by your office was insufficient to determine that no potential exists for cultural resources to exist in the project area. Therefore, we are requesting that an archaeological survey be conducted for the proposed site of the drilling recovery wells. A survey is not necessary for the contaminated top soil removal area.

Unless an archaeological survey is performed for the recovery well area, we would not be able to conclude that there is not a potential for sites eligible for the National Register to exist in the permit area.

Any questions concerning this matter should be addressed to Tom Downey at (614) 297-2470 before 1 p.m. Thank you for your cooperation.

Sincerely,

Judith Kitchen, Department Head
 Technical and Review Services

JLK/TMD:td

1