

7152

R-009-207.79

APPROVAL SOUTH PLUME WELL REPAIR RECOMMENDATIONS

08/31/95

OEPA

DOE-FN

1

APPROVAL



State of Ohio Environmental Protection Agency

Southwest District Office

401 East Fifth Street
Dayton, Ohio 45402-2911
(513) 285-6357
FAX (513) 285-6249

7152

FERNALD

LOG F-3494

SEP 5 9 15 AM '95

George V. Voinovich
Governor

FILE: _____

LIBRARY: _____

August 31, 1995

RE: DOE FEMP
MSL 531-0297
HAMILTON COUNTY
APPROVAL SO. PLUME
WELL REPAIR RECOMMEND-
ATIONS

Mr. Jack Craig
Project Manager
US DOE FEMP
P. O. Box 398705
Cincinnati, OH 45239-8705

Dear Mr. Craig:

This letter provides approval of DOEs "Recommendations on Repair of Damaged South Plume Recovery Well Screens" letter received by Ohio EPA on July 31, 1995. We concur that Alternative 3-Place New Screens in Wells- is the preferred course of action. If you have any questions, please contact Tom Ontko, (513)-285-6073 or Mike Proffitt, (513)-285-6603.

Sincerely,

Thomas A. Schneider
Fernald Project Manager
Office of Federal Facilities Oversight

- cc: Jim Saric, U.S. EPA
- Terry Hagen, FERMC
- Ruth Vandergrift, ODH
- Mike Proffitt, DD&GW
- Sharon McClellan, PRC
Manager, TPSS/DERR,CO
- Lisa August, GeoTrans

1