



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY
REGION 5
77 WEST JACKSON BOULEVARD
CHICAGO, IL 60604-3590

5078

REPLY TO THE ATTENTION OF
LIBRARY
FILE: 6446.6617
2003 SEP 29 9:49
LOG D-1481
FERNALD

SEP 26 2003

Mr. Johnny W. Reising
United States Department of Energy
Feed Materials Production Center
P.O. Box 398705
Cincinnati, Ohio 45239-8705

SRF-6J

RE: Paddys Run Corridor Real
Time Scan


Dear Mr. Reising:

The United States Environmental Protection Agency (U.S. EPA) has completed its review of the United States Department of Energy's (U.S. DOE) revision 1 of the Project Specific Plan (PSP) for the real-time scan of the Paddys Run corridor and associated drainage features. This PSP provides the details of radiological scanning of Paddys Run, two adjacent oxbow areas, the Storm Sewer Outfall Ditch, and Pilot Plan Drainage ditch corridor.

Although the PSP appears technically adequate, U.S. EPA does have a few comments on the document that need to be clarified. Therefore, U.S. EPA disapproves the Paddys Run corridor real-time scan PSP. U.S. DOE must submit responses to comments and a revised document within thirty (30) days receipt of this letter.

Please contact me at (312) 886-0992 if you have any questions regarding this matter.

Sincerely,



James A. Saric
Remedial Project Manager
Federal Facilities Section
SFD Remedial Response Branch #2

Enclosure

cc: Tom Schneider, OEPA-SWDO
Sally Robison, U.S. DOE-HDQ
Jamie Jameson, Fluor Fernald
Terry Hagen, Fluor Fernald
Tim Poff, Fluor Fernald

