



State of Ohio Environmental Protection Agency

Southwest District Office

TELE: (937) 285-6357 FAX: (937) 285-6249

www.epa.state.ohio.us

RECEIVED
DEPT. OF ENERGY, EMCBC

401 East Fifth Street
Dayton Ohio 45402-2911

Ted Strickland, Governor
Lee Fisher, Lt. Governor
Laura Powell, Acting Director

2007 FEB -6 A 11: 58

January 30, 2007

LOG # 07-00244

FILE # 2251.1

Mr. Johnny Reising
Fernald Project Director
EMCBC
250 East 5th Street Suite 500
Cincinnati, Ohio 454202

RE: APPROVAL - RESPONSES TO OEPA TECHNICAL REVIEW COMMENTS ON THE CERTIFICATION RPT FOR THE FSWL, SP-7 FOOTPRINT, SWMP AND RAILYARD DRAINAGE BASIN AREA

Mr. Reising,

Ohio EPA has received DOE's "Transmittal Of Responses To Ohio Environmental Protection Agency Technical Review Comments On The Certification Report For The Former Solid Waste Landfill, Soil Pile 7 Footprint, Storm Water Management Pond And Railyard Drainage Basin Area (20600-RP-0013), Final, Rev 0," submitted on January 18, 2007. Ohio EPA approves of the report and the RtCs as certifying the areas met the FRLs at the time the samples were collected. Ohio EPA reserves the right to re-examine the certification status of the relevant property areas, if in the opinion of Ohio EPA, the areas have been subjected to re-contamination by airborne releases, contaminated storm water run-on or any similar mechanism.

If there are any questions, please contact me.

Sincerely,

Thomas A Schneider
Fernald Project Manager
Office of Federal Facilities Oversight

Cc: Jim Saric, US EPA
Michelle Cullerton, Tetra Tech Inc.
Mark Shupe, Geo Trans Inc

Q:\ou5\emp\Area6 Waste Pits and General Area\RtCs\FSWL,SP7Ftprt, SWMPond&RailydDrnageBasin Approv.doc