

2847 RF 92

DATE 7-1-92

memorandum

JUN 1 10 51 AM '92

Rocky Flats Office

ACTION	INITIALS
BENJAMIN, A.	
BERMAN, H.S.	
BRANCH, D.E.	
BRODINGAME, A.H.	
CARNIVAL, G.J.	
COFF, R.D.	
PROUCHER, D.W.	
DAVIS, J.G.	
EVERED, J.E.	ACT
FERRERA, D.W.	
GOODWIN, R.	
HANNI, E.J.	
HEALY, T.J.	
HILBIG, J.G.	X
DEKER, E.H.	X
KERSH, J.M.	X
KIRBY, W.A.	
KRIEG, D.	
KUESTER, A.W.	
LEE, E.M.	
MAJESTIC, J.R.	
MARX, G.E.	X
MORGAN, R.V.	
PIZZUTO, V.M.	X
POTTER, G.L.	
SANDLIN, N.E.	
SHEPLER, R.L.	
SULLIVAN, M.T.	
SWANSON, E.R.	
TALLMAN, K.G.	
WALSH, J.S.	
WILSON, R.E.	
WILSON, J.M.	
YOUNG, E.F.	
ZANE, J.O.	

MAY 29 1992

EG&G
ROCKY FLATS PLANT
CORRESPONDENCE CONTROL

ERD:BKT:6038

Transfer of IHSSs Among Operable Units (OUs)

Jack
J. M. Kersh, Associate General Manager
Environmental and Waste Management
EG&G Rocky Flats, Inc.

Please find attached DOE/RFO letter 92-DOE-5560 to EPA and CDH, dated May 22, 1992, regarding the transfer of IHSSs among OUs at the RFP. The OUs affected include Nos. 6, 8, 9, 10, 12, 13, 14 and 15. We request that EG&G take action, as necessary, in a timely manner to implement the transfer of IHSSs.

The primary impacts will be to the Phase I RFL/RJ Work Plans at OUs 8, 9, 10, 12, 13, 14 and 15. In addition, this transfer may require funding changes among OUs. Should this be the case, we request that these changes be made through the Plant Change Control Board and that DOE/RFO be kept informed throughout the process.

Questions or concerns should be directed to the appropriate DOE OU project manager.

[Signature]
James K. Hartman
Assistant Manager
for Environmental Management

Attachment

cc w/Attachment:
E. Evered, EG&G
P. Bunge, EG&G
C. Gee, EG&G
R. Ogg, EG&G

cc w/o Attachment:
F. Lockhart, ERD, RFO
R. Schassburger, ERD, RFO
H. Rose, ERD, RFO
B. Birk, ERD, RFO
S. Grace, ERD, RFO
J. Pepe, ERD, RFO
B. Thatcher, ERD, RFO

Junge P X X X
Gee C X X X
GG R X X X
Pepe J X X X
Thatcher B X X X

CORRESP CONTROL
TABLE

Reviewed for Addressee
Corres. Control RFP
7-1-92 *[Signature]*

DATE BY

ADMIN RECORDED