

**From:** [Montoya, Anna \(CONTR\)](#)  
**To:** ["Moritz.vera@epa.gov"](mailto:Moritz.vera@epa.gov)  
**Cc:** [Boylan, John \(CONTR\)](#); [DiSalvo, Rick \(CONTR\)](#); [Kaiser, Linda \(CONTR\)](#); [rc-westminster](#); [Barnes, Shannon \(CONTR\)](#); [Surovchak, Scott](#)  
**Subject:** Correspondence to Vera Moritz: "Notification that GS03 no longer an RFLMA Point of Compliance"  
**Date:** Monday, September 30, 2013 4:53:32 PM  
**Attachments:** [TO LM00-502 Notification that GS03 no longer RFLMA POC Moritz 9-30-13..pdf](#)

---

Attached is a copy the transmittal letter, "Notification that GS03 no longer an RFLMA Point of Compliance". Your original is being sent in the mail.

Submitted on behalf of Scott Surovchak.

Anna Montoya  
Administrative Support  
S.M. Stoller Corporation  
Contractor to the U.S. Department of Energy  
Office of Legacy Management  
11025 Dover Street, Unit 1000  
Westminster, CO 80021  
(720) 377-9671  
(720) 377-3829 (fax)  
[anna.montoya@lm.doe.gov](mailto:anna.montoya@lm.doe.gov)



## Department of Energy

Washington, DC 20585

September 28, 2013

Ms. Vera Moritz  
EPA Rocky Flats Project Coordinator  
USEPA Region 8  
1595 Wynkoop St., Mail Code: 8EPR-F  
Denver, CO 80202-2466

Subject: Notification that GS03 is no longer an RFLMA Point of Compliance (POC)

Reference: Rocky Flats Legacy Management Agreement (RFLMA) Attachment 2, Section 5.1, "Monitoring Requirements"

Dear Ms. Moritz:

In accordance with the criteria provided in Section 5.1 of RFLMA Attachment 2, this is to certify that surface water monitoring location WALPOC has been functioning as an RFLMA POC for 2 years and now replaces surface water monitoring location GS03 as the POC. This notification completes the process to remove the RFLMA Attachment 2 requirement for monitoring at GS03.

No modification to RFLMA Attachment 2 is needed to implement this POC change. Table 2, "Water Monitoring Locations and Sampling Criteria," footnote 5 provides that POC GS03 will be replaced by WALPOC per Section 5.1. Figure 1, "Water Monitoring Locations at Rocky Flats: RFLMA," includes a similar note.

Please contact me at (720) 377-9682 or [scott.surovchak@lm.doe.gov](mailto:scott.surovchak@lm.doe.gov) if you have any questions or need additional information regarding this notification. Please send any correspondence to:

U.S. Department of Energy  
Office of Legacy Management  
11025 Dover Street, Suite 1000  
Westminster, CO 80021

Sincerely,

Scott R. Surovchak  
LM Site Manager

cc: (electronic)  
Richard DiSalvo, Stoller  
Linda Kaiser, Stoller  
rc-rocky.flats  
File: RFS 030.02

