

From: [DOE Office of Legacy Management](#)
Subject: DOE has posted two new contact records to the Rocky Flats Legacy Management website
Date: Friday, July 10, 2015 10:58:20 AM

The U.S. Department of Energy has posted Rocky Flats Legacy Management Agreement (RFLMA) contact records [RFLMA CR 2015-05](#), *Reportable condition for plutonium 12-month rolling average at Point of Evaluation (POE) SW027*, and [RFLMA CR 2015-04](#), *Mound Site Plume Treatment System (MSPTS) Reconfiguration Conceptual Approach*, to the Rocky Flats DOE Legacy Management website.

[RFLMA CR 2015-05](#) documents the consultation between the RFLMA Parties regarding the evaluation of elevated concentrations of plutonium at POE SW027, which resulted in a reportable condition under RFLMA Attachment 2, "Legacy Management Requirements."

[RFLMA CR 2015-04](#) documents the consultation between the RFLMA Parties regarding a more cost-effective option to treat the Mound Site Plume Treatment System influent in the East Trenches Plume Treatment System air stripper.

Contact records may be accessed at http://www.lm.doe.gov/Rocky_Flats/ContactRecords.aspx or by going to the Community Involvement page at http://www.lm.doe.gov/Rocky_Flats/Sites.aspx?view=5 and clicking on the Contact Records link.

If you have any difficulty accessing this contact record or have any additional questions, please contact:

Bob Darr
Public Affairs



DOE Legacy Management Support Contractor
720-377-9672
bob.darr@lm.doe.gov