

**VARIANCE / FIELD CHANGE NOTICE**

Significant?  
(Yes or No): **NO**

V/F: 21130-PSP-0001-15

WBS NO.: PROJECT/DOCUMENT/ECDC # 21130-PSP-0001 Rev.0

Page: 1 of 1

PROJECT TITLE: Project Specific Plan for Area 9, Phase II Precertification Real-Time Scan

Date: 6/02/03

**VARIANCE / FIELD CHANGE NOTICE (Include justification):**

**4900**

This Variance/Field Change Notice (V/FCN) documents the collection of physical soil samples from an off-property location following a discharge of water from South Plume Optimization Well 6.

Eight surface soil samples were collected for total uranium analysis. Following sample submittal to the onsite laboratory, samples were analyzed by ICP-MS with an MDL of 8 ppm.

Samples were identified as KFWS-1-R through KFWS-5-R and KFWSB-6-R through KFWSB-8-R

Where:

- KFWS = Knollman's Farm Well Spill
- KFWSB = Knollman's Farm Well Spill Background
- 1, 2, 3, etc = consecutive sample number
- R = Total Uranium

QC samples were not required for this sampling event. Samples submitted under this V/FCN were analyzed to ASL B requirements. Field validation will be performed.

**Justification:**

**INFORMATION ONLY**

Samples were collected from an off-property location following a discharge of water from South Plume Optimization Well 6 to determine clean-up requirements.

Per Section 2.7 of the PSP, the collection of physical samples will be documented with a V/FCN.

REQUESTED BY: Denise Arico

Date: 6/02/03

X IF REQD	VARIANCE/FCN APPROVAL	DATE	X IF REQD	VARIANCE/FCN APPROVAL	DATE
X	QUALITY ASSURANCE: <i>Denise Arico</i>	<i>6/9/03</i>	X	PROJECT MANAGER: J.D. [Signature]	<i>6/2/03</i>
	DATA QUALITY MANAGEMENT		X	CHARACTERIZATION MANAGER: Frank Miller	<i>6/2/03</i>
X	ANALYTICAL CUSTOMER SUPPORT: <i>Deborah Medley</i>	<i>6/3/03</i>		RTIMP Manager	
X	WAO: <i>Linda Butler</i>	<i>6/9/03</i>	X	Sampling Manager: L. [Signature]	<i>6/2/03</i>
VARIANCE/FCN APPROVED [X] YES [ ] NO			REVISION REQUIRED: [ ] YES [x] NO		

**DISTRIBUTION**

PROJECT MANAGER:	DOCUMENT CONTROL: Jeannie Rosser	OTHER:
QUALITY ASSURANCE:	CHARACTERIZATION MANAGER: Frank Miller	OTHER:
FIELD MANAGER:	OTHER:	OTHER:

**1**