

B371/374 Closure Project

Rocky Flats Environmental Technology Site

INTEROFFICE CORRESPONDENCE

DATE: July 31, 2002

TO: ✓ Matt Francis, Safety, Eng. and Qual., B116, x2358
Mike Papp, Waste Management, T130J, x3382

FROM: D. A. Ward, Environmental Compliance, B371, x5938 *DW*

SUBJECT: BUILDING 910 AS A NON RCRA HAZARDOUS WASTE TREATMENT FACILITY.

The attached documents demonstrate that Building 910 did not treat RCRA hazardous waste. Therefore the facility, equipment and waste streams should not be RCRA hazardous waste based on past operations.

Interceptor Trench System Water (ITS)

1. 1995 Contact Record stating F039 did not apply to solar ponds leachate (ITS water).
2. 1996 RMRS letter recharacterizing the ITS water as non hazardous waste.

Solar Pond Water

1. 1993 Draft letter to regulators stating "Excess pond water will continue to be transferred to Building 374 for treatment."
2. 2000 Approved Reconnaissance Level Characterization Report stating "Liquids from the Solar Ponds were never treated in the facility."
3. Discussion with personnel that were present in B910 during operations. Confirmed that Solar Ponds water was never treated in B910.

RCRA Permit Status

1. 1997 DOE letter withdrawing Unit 910.3 from the permit reapplication at the suggestion of the CDPHE.



DOCUMENT CLASSIFICATION
REVIEW WAIVER PER
CLASSIFICATION OFFICE

ADMIN RECORD

IA-A-001088