

STATE OF COLORADO

Bill Owens, Governor
Douglas H. Benevento, Executive Director

Dedicated to protecting and improving the health and environment of the people of Colorado

4300 Cherry Creek Dr. S. Laboratory Services Division
Denver, Colorado 80246-1530 8100 Lowry Blvd.
Phone (303) 692-2000 Denver, Colorado 80230-6928
TDD Line (303) 691-7700 (303) 692-3090
Located in Glendale, Colorado
<http://www.cdphe.state.co.us>



Colorado Department
of Public Health
and Environment

January 24, 2005

Mr. Joseph A. Legare, Director
Project Management Division
U.S. Department of Energy, RFEO
10808 Highway 93, Unit A
Golden, CO 80403-8200

Mr. Stephen M. Nesta
Environmental Manager
Remediation, Industrial D&D, & Site Services
Kaiser-Hill Company, L.L.C.
Rocky Flats Environmental Technology Site
10808 Highway 93, Unit B
Golden, CO 80403-8200

RE: Approval, Administrative Closure of RCRA Permitted Container Storage Unit MS 001, Container Storage Sub-Unit 14 – at Building 906

Dear Mr. Legare and Mr. Nesta:

The Colorado Department of Public Health and Environment, Hazardous Materials and Waste Management Division (the "Division") has received the subject closure documentation.

The Division agrees that administrative closure, as described in State RCRA Permit CO-04-06-23-01, Permit Condition Part X.D.1.a, Clean Closure Option 1: Unit Review and Inspection, is appropriate. This decision is based on representations that the RCRA Operating Record, etc., indicate that no releases occurred at any time during the operational period or were quickly mitigated.


With the potential for prior redistribution of soils from contaminated construction sites, the Division must consider whether underlying soils may be contaminated. If observation immediately after slab removal reveals evidence of staining or backfilling of soils (other than contraction sand or gravel), RFETS should perform limited field method screening for radionuclides, metals and volatiles. Information indicating that the site was cleared prior to construction of the building in the mid 1990's may be sufficient.

If you have any questions concerning this correspondence, please contact me at 303-692-3367 or Harlen Ainscough at (303) 692-3337.

Sincerely,

Steven H. Gunderson
RFCA Project Coordinator

cc: Gary Morgan, DOE D. Ward, Kaiser-Hill
D. Shelton, K-H M. Aguilar, USEPA Region VIII
D. Miller, AGO S. Garcia, City of Broomfield



Administrative Record, RFETS Bldg. T-130G

ADMIN RECORD

C:\Documents and Settings\hainscou\My Documents\RFETS\Unit Closures-Closure pLan\Unit MS 001, Sub-Unit 14.doc

IA-A-002525