

03979 RF 94

United States Government

Department of Energy

Oct 21 2 10 PM '94

Rocky Flats Field Office

memorandum

CC ROCKY FLATS PL
EG&G
FFS C W F

DATE

OCT 18 1994

LOCATION

ER SRG 10700

DIST

Operable Unit No 1 Interim Measures/Interim Remedial Action Footing Drain and Collection Well Water

TR ENCL

Sue Stuger Associate General Manager
Environmental Restoration Management
EG&G Rocky Flats Inc

FRLINGAME, A H

JSBY, W S

RNIVAL, G J

DRDOVA, R C

VIS, J G

RRERA, D W

AY, R E

IS, J A

OVER, W S

DLAN, P M

ANNI, B J

EALY, T J

DAHL, T G

BIG, J G

TCHINS, N M

KSON, D T

I, R E

STER, A W

RX, G E

DONALD, M M

KENNA, F G

RGAN, R V

ZUTO, V M

TER, G L

NDLIN, N B

TERWHITE, D G

HUBERT, A L

HWARTZ, J K

LOCK, G H

GER, S G

BIN, P M

ORHEIS, G M

SON, J M

Timrose, A

Both the Environmental Protection Agency (EPA) and the Colorado Department of Public Health and Environment (CDPHE) have approved our request to discontinue collection and treatment of water from the Building 881 footing drain as part of the Operable Unit (OU) No 1 (881 Hillside) Interim Measure/Interim Remedial Action (IM/IRA). Therefore you are direct to immediately discontinue collection of water from the 881 footing drain

An earlier memorandum (ER SRG 10199 dated September 29 1994) laid the conditions of the approval from EPA. These included (1) that the water is sampled quarterly for the full suite of volatile organic compounds filtered and unfiltered metals filtered and unfiltered radionuclides and water quality parameters listed in GRASP (Sept 1990) (2) the results of monitoring be included in the OU 1 IM/IRA quarterly report and (3) with the strong recommendation that the water be routed through the OU 1 wetland prior to entering the South Interceptor Ditch. Your October 14 1994 letter (94 RF 10558 SGS 550 94) proposed a permanent design for routing footing drain to either the South Interceptor Ditch or the OU 1 wetland. We think this is a good idea. The only condition on the approval imposed by CDPHE was that the discharge from the footing drain is handled in accordance with the proposed Industrial Area IM/IRA.

We reiterate the direction that water from the collection well **not** be sent to the french drain. Rather an alternative method of collection and transportation to the 891 treatment building is requested. As directed in our September 29 1994 memorandum, the plan

RES CONTROL X X
IN RECORD/080 X
S/T130G

viewed for Addressee
Corres Control RFP

021 94
DATE BY

1 #

ORDER # 54001

MIN RECORD

S Stiger
ER SRG 10700

2

that proposed how you would collect water from the collection well was due by
October 14 1994

If you have any questions please contact Scott Grace at extension 7199



Jessie Roberson
Assistant Manager for
Environmental Restoration

cc
Claire Gesalman EM-453 HQ
M Silverman OOM RFFO
L Smith OOM RFFO
B Williamson ER RFFO
T Reeves SAIC
A Primrose SAIC
R Crillo EG&G