

**From:** [DOE Office of Legacy Management](#)  
**Subject:** DOE Legacy Management has posted a new contact record to the Rocky Flats webpage  
**Date:** Tuesday, February 04, 2014 2:18:59 PM

---

The U.S. Department of Energy has posted contact record [RFLMA CR 2014-02](#) to the Public Involvement page at [http://www.lm.doe.gov/Rocky\\_Flats/Sites.aspx?view=5](http://www.lm.doe.gov/Rocky_Flats/Sites.aspx?view=5) . This contract record addresses a minor modification to *Rocky Flats Legacy Management Agreement* (RFLMA), Attachment 2, Legacy Management Requirements, reflecting the changed status of monitoring locations GS 01 and GS 03 along Indiana Street. GS 01 and GS03 ceased being Point of Compliance locations in September, 2013. For background information on the changes to the POC locations, see Contact Record 2010-04, “[RFLMA] Attachment 2: Modification to Revise Monitoring Points”. GS 01 and GS 03 are currently being monitored under the Rocky Flats Surface Water Configuration Adaptive Management Plan.

If you have any difficulty accessing this document or have any other questions, please contact:

*Bob Darr*  
*Public Affairs*  
*SM Stoller Corporation*  
*DOE Legacy Management Support Contractor*  
*720-377-9672*  
[bob.darr@lm.doe.gov](mailto:bob.darr@lm.doe.gov)