

000006969



June 10, 1987

Department of Public Works

George H. Setlock, Ph. D.
Manager
Environmental Management
Rockwell International
Rocky Flats Plant
P.O. Box 464
Golden, Colorado 80402

Dear George:

The City of Westminster was first alerted of groundwater contamination at the Rocky Flats Plant site in July, 1985 during a briefing by Rockwell International personnel. At that point in time the accuracy of the data regarding the contaminants, primarily VOC's, was considered somewhat questionable due to improper sampling and analytical techniques and lack of knowledge regarding monitoring well construction. Therefore, individual sampling results were not distributed.

Since that time extensive sampling has been performed and in fact an entirely new monitoring network has been put in place. However, the City of Westminster has not seen any of the more recent sampling results nor do we have any documents or maps showing the location and depth of the new monitoring wells. An effort was also going to be made to characterize the groundwater flow at the Plant site, in terms of both direction and velocity, yet I have not seen any results from this work.

By this letter, I am requesting the above referenced information. I am currently attempting to obtain a copy of the CEARP Phase document from the Department of Energy if any of this information is contained in that document. I would also like to receive future sampling results on an on-going basis. This information will be most useful in the City's effort to evaluate the existing contamination and proposed clean-up at the Plant.

If you have any questions regarding this request, please feel free to call. Thank you for your assistance in this matter.

Sincerely,

Dave Kaunisto

Dave Kaunisto,
Water Resources Engineer

DOCUMENT CLASSIFICATION
REVIEW WAIVER PER
CLASSIFICATION OFFICE