

RECEIVED

Revised 02/02

CORRES CONTROL  
INCOMING LTR NO

00368 RF02

DUE DATE  
ACTION



Department of Energy

ROCKY FLATS FIELD OFFICE  
10808 HIGHWAY 93, UNIT A  
GOLDEN, COLORADO 80403-8200

2002 MAY -1 P 2:36  
CORRESPONDENCE  
CONTROL

APR 24 2002

02-DOE-00649

Mr Steven H Gunderson  
Rocky Flats Cleanup Agreement Project Coordinator  
Colorado Department of Public Health and Environment  
4300 Cherry Creek Drive South  
Denver, Colorado 80246-1530

Dear Mr Gunderson

The Department of Energy (DOE) is in receipt of your letter dated April 16, 2002, disapproving the Draft Environmental Restoration Rocky Flats Cleanup Agreement (RFCA) Standard Operating Protocol (ER RSOP) for Routine Soil Remediation Fiscal Year (FY) 2002 Notification #02-05 and #02-06. It was our assumption that we were continuing to utilize the consultative process via meetings to discuss the Notifications and come to resolution on the wording included in the documents. We were not of the understanding that resolution was not reached. In response to your four items, the following is provided

- There are three actions identified in Section 1.4 of the Final ER RSOP for Routine Soil Remediation. The first is to consult on what the notification will include. The Rocky Flats Environmental Technology Site (Site) met with the Agencies and discussed at length what would be included in the individual Notifications. The status of individual Notifications is provided at the monthly Decontamination and Decommissioning/Environmental Restoration (D&D/ER) meetings. To better facilitate early consultation on potential remediation projects, ER will meet with a Colorado Department of Public Health and Environment (CDPHE) representative in conjunction with the weekly Remediation, Industrial D&D, and Site Services (RISS) D&D Meeting to discuss upcoming projects and the integration with D&D. Environmental Restoration will also meet to discuss the specifics of each individual Notification either prior to or at the time the draft Notification is prepared.
- As agreed to with D. Krucke, on April 17, 2002, the following language will be added to Section 2.3: "Remove contaminated soil to below Tier I Action Levels (AL), if indicated through the Rocky Flats Cleanup Agreement Standard Operating Protocol (RSOP) stewardship evaluation (Section 2.4)." Additionally, the text in Section 2.4, third sentence has been changed to the following "Additional remediation to below Tier I ALs is not required by RFCA but may be indicated through the RSOP stewardship evaluation."

The language in the Draft ER RSOP Notifications 02-05 and 02-06 is the language that was agreed upon with CDPHE at a meeting on January 11, 2002. The CDPHE approved ER RSOP Notifications 02-01, 02-02, and 02-03 with the approved language. We are adding the language to ER RSOP Notifications 02-05 and 02-06 as requested. However, we note that this is not consistent with our understanding of the previous agreements. We expect that with the ongoing end state discussions, the language of the ER RSOP will require changes. We expect that during these revisions we can reach agreement on appropriate content for future notifications.

DIST	LTR	ENC
BOGENBERGER, V.		
BOGNAR, E.	X	
BRAILSFORD, M.D.		
BURNS, T.F.		
DECK, C.A.	X	
DEGENHART, K.		
DIETERLE, S.E.		
FERRERA, D.W.	X	
FERRI, M.S.		
GERMAIN, A.L.		
GIACOMINI, J.		
HALL, L.		
ISOM, J.H.		
MARTINEZ, L.A.	X	
MCLAUGHLIN, J.	X	
NORTH, K.	X	
PARKER, A.M.	X	
POWERS, K.		
RAAZ, B.D.		
RODGERS, A.D.		
SCOTT, G.K.	X	
SHELTON, D.C.	X	
SPEARS, M.S.		
TRICE, K.D.		
TUOR, N.R.		
VOORHEIS, G.M.		
WILLIAMS, J.L.		
NORLAND, L.	X	
BUTLER, L.	X	
BROOKS, L.	X	

COR CONTROL	X	X
ADMN RECORD	X	
PATS/130		

Reviewed for Addressee  
Corres Control RFP

5/1/02 Date *lg*

Ref Ltr #

DOE ORDER #  
NONE

DOCUMENT CLASSIFICATION  
REVIEW WAIVER PER  
CLASSIFICATION OFFICE

ADMIN RECORD  
SW-A-004504

1/2

Mr Steven H Gunderson  
02-DOE-00649

2

APR 24 2002

- 3 Section 2 3 will be clarified An example follows "Tanks 24 and 32 at Building 887 which will be removed by D&D"
- 4 Two issues from the April 11, 2002, meeting were not resolved at that time because they required more information These issues and the Site response follow

**Draft ER RSOP #02-05**


Where are storm drains? Storm drains are in the same location as the foundation drains at Building 881. Most of the utilities at this site are in the same utility corridor.

**Draft ER RSOP #02-06**

Groundwater well 84201 has been renamed 84202 because it was installed in FY 2002. This well is located west of Building 883. Three new wells, 85102, 85202, and 85302, were installed in the vicinity of Individual Hazardous Substance Site Group 400-7 These wells are currently being sampled.

The revised Notifications were forwarded to Dave Kruchek for his review on Thursday, April 18, 2002 If you would like to meet or have any questions regarding this correspondence, please contact Norma Castaneda, of my staff, at (303) 966-4226, or you may contact me at (303) 966-2282

Sincerely,



Joseph A. Legare  
Assistant Manager  
for Environment and Stewardship

cc  
N Castaneda, ER, RFFO  
L O'Mary, ER, RFFO  
R McCallister, ER, RFFO  
L Butler, K-H  
L Norland, K-H  
D Shelton, K-H  
E Pottorff, CDPHE  
D Kruchek, CDPHE  
T Rehder, EPA  
G Kleeman, EPA  
Administrative Record, T130G

