


**POSTED**

OCT 20 1989



NE-23  
Wagoner  
10/18/89

NE-23  
10/19/89

Mr. Carl Balonick  
Marden Manufacturing Company  
5823 North Ravenswood  
Chicago, Illinois 60611

Dear Mr. Balonick:

Enclosed is a copy of the final survey report for your facility in Chicago, Illinois, which is the site of the former Quality Hardware & Machine Corporation. This survey report documents the fact that the radiological condition of your facility is in compliance with applicable Department of Energy Guidelines and that no remedial action or further investigations are necessary.

If you have any questions regarding the survey results or our associated actions, contact Mr. James Wagoner of my staff at 301-353-2802.

Sincerely,

151

James J. Fiore, Director  
Division of Facility and Site  
Decommissioning Projects  
Office of Nuclear Energy

Enclosure

bcc:  
OTS

NE-23 RF  
Wagoner RF  
NEG (4)

NE-23: JWagoner:jw:353-4937:10/18/89:IBM:290/81

3.17.11