LMS/FER/S07409

FERNALD PRESERVE

2010 Site Environmental Report

U.S. Department of Energy
Office of Legacy Management

Issued May 2011 (S07409)



This page intentionally left blank

LMS/FER/S07409

Fernald Preserve

2010 Site Environmental Report

May 2011

This page intentionally left blank

Contents

Abbreviations iv
Measurement Abbreviations v
Units (Abbreviations) and Conversion Table vi
Executive Summary vii
1.0 Site Background 1–1
1.1 The Path to Site Closure 1–3
1.2 Environmental Monitoring Program 1–5
1.3 Characteristics of the Site and Surrounding Area 1–6
1.3.1 Land Use and Demography 1–6
1.3.2 Geography 1–6
1.3.3 Geology 1–11
1.3.4 Surface Hydrology 1–11
1.3.5 Natural Resources 1–15
2.0 Remediation Status and Compliance Summary 2–1
2.1 CERCLA Remediation Status 2–1
2.2 Summary of Compliance with Other Requirements 2–6
2.2.1 RCRA 2–6
2.2.1.1 RCRA Property Boundary Groundwater Monitoring 2–6
2.2.1.2 Waste Management 2–6
2.2.2 Clean Water Act 2–7
2.2.3 Clean Air Act 2–7
2.2.4 Superfund Amendments and Reauthorization Act of 1986 2–7
2.2.5 Other Environmental Regulations 2–8
2.2.6 Other Permits 2–8
2.2.7 Pollution Prevention and Source Reduction 2–8
2.2.8 Federal Facilities Compliance Agreement 2–12
2.2.9 Environmental Management Systems Requirement 2–12
2.3 Split Sampling Program 2–12
3.0 Groundwater Pathway 3–1
3.1 Summary of the Nature and Extent of Groundwater Contamination 3–1
3.2 Selection and Design of the Groundwater Remedy 3–2
3.3 Groundwater Monitoring Highlights for 2010 3–6
3.3.1 Restoration Monitoring 3–12
3.3.1.1 Operational Summary 3–12
3.3.1.2 South Plume/South Plume Optimization Module Operational Summary 3–14
3.3.1.3 South Field Module Operational Summary 3–14
3.3.1.4 Waste Storage Area Module Operational Summary 3–16
3.3.1.5 Monitoring Results for Total Uranium 3–17
3.3.1.6 Monitoring Results for Non-Uranium Constituents 3–18
3.3.2 Other Monitoring Commitments 3–20
3.4 Groundwater Remediation Assessment 3–21
3.5 OSDF Monitoring 3–22
4.0 Surface Water and Treated Effluent Pathway 4–1
4.1 Summary of Surface Water and Treated Effluent Pathway 4–1
4.2 Remediation Activities Affecting the Surface Water Pathway 4–3
4.3 Surface Water, Treated Effluent, and Sediment Monitoring Program 4–3

4.3.1 Surveillance Monitoring 4–4
4.3.2 Compliance Monitoring 4–8
4.3.2.1 FFCA and OU5 ROD Compliance 4–8
4.3.2.2 NPDES Permit Compliance 4–12
4.3.3 Uranium Discharges in Surface Water and Treated Effluent....4–12
5.0 Direct Radiation Pathway and Radiation Dose 5–1
5.1 Monitoring for Direct Radiation 5–1
5.2 Direct Radiation Dose....5–3
5.3 Total of Doses to the Maximally Exposed Individual 5–5
5.4 Significance of Estimated Radiation Doses for 2010 5–5
5.5 Estimated Dose to Biota 5–7
6.0 Natural Resources 6–1
6.1 Ecological Restoration Activities 6–3
6.1.1 Ecological Restoration Repair and Enhancement 6–3
6.1.2 Restored Area Maintenance Activities 6–3
6.1.3 Ecological Restoration Monitoring 6–5
6.1.3.1 Wetland Mitigation Monitoring 6–5
6.1.3.2 Functional Monitoring 6–13
6.2 Fernald Preserve Site and OSDF Inspections 6–14
6.3 Affected Habitat and Inspection Findings 6–14
6.4 Threatened and Endangered Species and Species Inventories 6–15
6.5 Cultural Resources....6–16
7.0 References 7–1
8.0 Glossary....8–1

Figures

Figure 1–1. Fernald Preserve and Vicinity.... 1–7
Figure 1–2. Major Communities in Southwestern Ohio 1–8
Figure 1–3. Fernald Preserve Perspective 1–9
Figure 1–4. Cross Section of the New Haven Trough, Looking North.... 1–12
Figure 1–5. Regional Groundwater Flow in the Great Miami Aquifer.... 1–13
Figure 1–6. Great Miami River Drainage Basin 1–14
Figure 1–7. Annual Precipitation, 1994–2010 1–16
Figure 1–8. Monthly Precipitation for 2010 Compared to Average Monthly Precipitation for 1951–2010.... 1–17
Figure 2–1. Uncertified Areas and Subgrade Utility Corridors 2–3
Figure 2–2. 2010 DOE and OEPA Groundwater Split Sample Locations.... 2–14
Figure 3–1. Extraction Wells Active in 2010.... 3–3
Figure 3–2. Diagram of a Typical Groundwater Monitoring Well 3–7
Figure 3–3. Monitoring Well Relative Depths and Screen Locations 3–8
Figure 3–4. Locations for Semiannual Total Uranium Monitoring 3–9
Figure 3–5. Locations for Semiannual Non-Uranium Monitoring.... 3–10
Figure 3–6. IEMP Groundwater Elevation Monitoring Wells.... 3–11
Figure 3–7. Net Mass of Uranium Removed from the Great Miami Aquifer, 1993–2010.. 3–13
Figure 3–8. Total Uranium Plume in the Aquifer with Concentrations Greater Than 30 µg/L at the End of 2010 3–15
Figure 3–9. Non-Uranium Constituents with 2010 Results Above FRLs.... 3–19

Figure 3–10. OSDF Footprint and Monitoring Well Locations 3–23
Figure 4–1. Controlled Surface Water Areas and Uncontrolled Runoff Flow Directions 4–2
Figure 4–2. IEMP/NPDES Surface Water and Treated Effluent Sample Locations 4–5
Figure 4–3. IEMP Background Surface Water Sample Locations 4–7
Figure 4–4. Annual Average Total Uranium Concentrations in Paddys Run at Willey Road (SWP-03) Sample Location, 1985−2010 4–9
Figure 4–5. Pounds of Uranium Discharged to the Great Miami River through the Parshall Flume (PF 4001) in 2010 4–10
Figure 4–6. 2010 Monthly Average Total Uranium Concentration in Water Discharged Through the Parshall Flume (PF 4001) to the Great Miami River 4–11
Figure 4–7. Uranium Discharged via the Surface Water Pathway, 1993−2010 4–13
Figure 5–1. Direct Radiation (OSL) Monitoring Locations 5–2
Figure 5–2. Quarterly Results for OSL Monitoring Locations 5–4
Figure 5–3. Comparison of 2010 All-Pathway Doses and Allowable Limits 5–6
Figure 6–1. Restoration Project Areas 6–2
Figure 6–2. Ecological Monitoring Activities 6–7
Figure 6–3. Threatened and Endangered Species Habitat Areas 6–17
Figure 6–4. Cultural Resource Survey Area 6–18

Tables

Table 1–1. Operable Unit Remedies 1–4
Table 2–1. Compliance with Other Environmental Regulations 2–9
Table 2–2. 2010 DOE/OEPA Groundwater Split Sampling Comparison 2–13
Table 3–1. Groundwater Restoration Module Status for 2010 3–12
Table 3–2. Non-Uranium Constituents with Results Above FRLs During 2010 3–18
Table 3–3. OSDF Groundwater, Leachate, and LDS Monitoring Summary 3–24
Table 5–1. Direct Radiation (OSL) Measurement Summary 5–3
Table 5–2. Dose to MEI 5–5
Table 6–1. Amphibian Monitoring Summary 6–9
Table 6–2. Hydrological Monitoring Summary 6–10
Table 6–3. Soil Biogeochemistry Sampling Summary 6–11
Table 6–4. Prairie Functional Monitoring Summary 6–12
Table 6–5. Functional Monitoring Comparison 6–12

Appendixes

Appendix A Supplemental Groundwater Information
Appendix B Supplemental Surface Water, Treated Effluent, and Sediment Information
Appendix C Supplemental Air Information
Appendix D Ecological Restoration Monitoring