

Post-Closure LANL Data:
Surface Water, Treatment System, Well

- Predominantly Natural
- Predominantly Anthropogenic
- LANL Data Pending


Pre-Closure LANL Data:
Surface Water, Treatment System, Well

- Predominantly Natural
- Predominantly Anthropogenic

Other Features

- GW Treatment System
- Major Road
- Topographic contour (10-foot interval)
- Stream, ditch, or other drainage feature
- Lake or Pond
- Constructed Wetland
- Refuge Boundary
- Central OU Boundary
- Landfill

Notes:
 Additional LANL data are pending for locations GS10, GS13, SW093, 00193, 15699, A3 POND, A4 POND, B5 POND, C2 POND, B206989, PLFPONDEFF, POM2, SPIN, and SPPDISCHARGEALLERY.
 SPPTS: Solar Ponds Plume Treatment System
 MSPTS: Mound Site Plume Treatment System
 ETPTS: East Trenches Plume Treatment System
 PLFTS: Present Landfill Treatment System



U.S. DEPARTMENT OF ENERGY <small>GRAND JUNCTION, COLORADO</small>	<small>Work Performed by</small> S.M. Stoller Corporation <small>Under DOE Contract No. DE-AM01-07LM00060</small>
Figure 1 Sampling Locations for Pre- and Post- Closure LANL Uranium Quantitative Analysis	
<small>DATE PREPARED:</small> November 3, 2008	<small>FILENAME:</small> S0483600