

4931

**APPROVAL OF THE CAMERA
INSTALLATION/BENTONITE INSPECTION WORK
PLAN**

11/24/93

USEPA/DOE-FN

1

LETTER

OU4



-49 8 1
UNITED STATES ENVIRONMENTAL PROTECTION AGENCY
REGION 5
77 WEST JACKSON BOULEVARD
CHICAGO, IL 60604-3590

LOG
FILE
LIBR

H-1657

AR

DEC 1 1 09 PM '93

REPLY TO THE ATTENTION OF:

NOV 24 1993

Mr. Jack R. Craig
United States Department of Energy
Feed Materials Production Center
P.O. Box 398705
Cincinnati, Ohio 45239-8705

HRE-8J

RE: Approval of the Camera
Installation/Bentonite
Inspection Work Plan

Dear Mr. Craig:

The United States Environmental Protection Agency (U.S. EPA) has completed its review of the Operable Unit 4 Silo 2 Camera Installation/Bentonite Inspection Work Plan. The Work Plan details installation of two cameras in Silo 2 to inspect the bentonite cap.

U.S. EPA hereby, approves the Work Plan. U.S. DOE must submit the report documenting the investigation and any recommendations for further action to U.S. EPA when completed.

Please contact me at (312) 886-0992 if you have any questions.

Sincerely,

James A. Saric
Remedial Project Manager

cc: Graham Mitchell, OEPA-SWDO
Pat Whitfield, U.S. DOE-HDQ
Nick Kaufman, FERMCO
Jim Theising, FERMCO
Paul Clay, FERMCO



Printed on Recycled Paper