

**ROCKY FLATS ENVIRONMENTAL TECHNOLOGY SITE
REGULATORY CONTACT RECORD**

Date: July 12, 2001

Site Contact(s): Mike Putney (Radian)

Extension: X2692

Regulatory Contact: Arch Crouse

Extension: X2793 or 692-3156

Agency: Colorado Department of Public Health and Environment, Air Pollution Control Division (CDPHE, APCD)

Purpose of Contact (include topics discussed and documentation supplied):

Arch Crouse with CDPHE, APCD, Jon Dion with DOE, RFFO and Mike Putney with Radian Air Quality Management, a subcontractor to K-H ESS, participated in an air compliance inspection of Buildings 707/708 and 776/777 with environmental and building representatives on July 11 2001. Field inspections of buildings and operations are part of the CDPHE surveillance program for the Rocky Flats Environmental Technology Site and are conducted annually.

Building 707/708

Attendance: The group met with Building 707 project representatives Bob Cathel and Richard Bloom.

Verification: Richard Bloom briefed the group on current activities in the building and addressed building specific questions. The CDPHE representative inquired about current D&D activities, future D&D schedules, and chemical usage.

Results: No deficiencies were identified.

Records Transmitted: Building representatives transmitted Building 707 HEPA filter pressure drop readings and DOP testing information, and emergency generator hour meter readings to the CDPHE representative.

Follow-up required (list any documents requested): Opacity observations need to be performed on the building emergency generators and pump.

Building 776/777

Attendance: The group met with Building 776/777 project representatives Bob Cathel and Jeff Theesfeld.

Verification: Bob Cathel and Jeff Theesfeld briefed the group on current activities in the building and addressed building specific questions. The CDPHE representative inquired about current D&D activities, future D&D schedules, chemical usage, and chiller registration.

Results: No deficiencies were identified.



1/2

Records Transmitted: Building representatives transmitted Building 776 HEPA filter pressure drop readings and DOP testing information, and emergency generator hour meter readings to the CDPHE representative.

Follow-up required (list any documents requested): An opacity observation needs to be performed on the building emergency generator.

Contact Record Prepared by: Mike Putney

DISTRIBUTION

Required Distribution:

T. Hopkins, B707 & 776
C. Deck, K-H Legal
K. North, K-H ESS
A. Rosenman, K-H ESS

Additional Distribution:

Bob Cathel, B707 & 776
Richard Bloom, B707
Jon Dion, DOE, RFFO
Rob Garren, Radian

2/2