


## Type 1 Facility Closeout Report

<b>Section A. Facility Data</b>	
Facility No.	T707B
Facility Descriptor:	Office trailer, single wide, 10 ft x 50 ft
Project:	RISS
Date of Demolition:	7/29/04
Additional Information:	See attached description
<i>(Must include information on environmental releases and conditions of site at turnover to Environmental Restoration)</i>	

<b>Section B. Final Characterization Data</b>	
Reconnaissance Level Characterization Report <i>(concurrence received)</i>	RLCR approved 7/27/04 AR Doc. No. B707-A-000106, 00322-RF-04
In-process Characterization	Not applicable
Pre-Demolition Survey Report <i>(approval received)</i>	PDSR included with RLCR. Submitted to CDPHE 7/14/04, AR Doc. Nos. B707-A-000108, 109, 04-RF-00746
Post-Demolition Survey Report <i>(as necessary)</i>	Not applicable.

<b>Section C. Waste Data <i>(complete categories as appropriate)</i></b>	
<b>Sanitary Disposal</b>	
Disposal Site:	BFI Foothills Landfill, Hwy 93
Waste Volume (m <sup>3</sup> ):	84.1 m <sup>3</sup>
Waste Weight (tons):	12.84 tons
Additional Information:	
<b>Hazardous Disposal</b>	
Disposal Site:	Superior Special Services, Inc.; Onyx, Henderson, CO
Waste Volume (m <sup>3</sup> ):	Minor amounts
Additional Information:	Electronic circuit boards, thermostats, exit signs, batteries, fluorescent light bulbs, and miscellaneous containerized chemicals were removed prior to demolition and managed with Building 707/778 CERCLA wastes.
<b>TSCA Waste Disposal</b>	
Disposal Site:	BFI Foothills Landfill, Hwy 93
Waste Volume (m <sup>3</sup> ):	Minor amounts
Additional Information:	Fluorescent light ballasts were removed prior to demolition and managed with Building 707/778 CERCLA wastes.
<b>Asbestos Waste Disposal</b>	
Additional Information:	NA RLCR identified no asbestos waste
<b>Low-Level Waste Disposal</b>	
Additional Information:	NA No LLW was generated
<b>Low-Level Mixed Waste Disposal</b>	
Additional Information:	NA No LLM waste was generated
<b>Recycled Material</b>	
Waste Volume (m <sup>3</sup> ):	Freon Minor amounts
Additional Information:	Air conditioners and refrigerators were removed prior to demolition and freon was reclaimed by Colorado licensed technicians. Freon was transferred to PU&D for offsite resale/reuse
<b>Property Disposition</b>	
Receiver Locations <i>(major items only)</i> :	NA
Additional Information:	Furniture was demolished with the trailer.

<b>Section D. Approvals</b>	
Kaiser-Hill Project Manager	 Name: _____ Signature: _____
	Date: 6/15/05



## Type 1 Facility Closeout Report T707B

Trailer T707B was a single-wide office trailer located in the courtyard between Buildings 707 and 750. Figure 1 shows the trailer location. It had no utility service except electrical, LSDW, and telephone. The electrical service, which was connected above ground, was disconnected at Building 731, just south of the trailer.

The Reconnaissance Level Characterization Report, dated July 14, 2004, included the pre-demolition survey report. The trailer was characterized as a Type 1 facility. The RLCR was approved by CDPHE on July 27, 2004. Hazardous materials were removed from the trailer prior to demolition. There were no environmental releases associated with T707B.

The trailer was demolished on July 29, 2004, and the waste dispositioned at a sanitary landfill. The trailer sat on asphalt, which was removed by RISS following the trailer demolition to allow access to new process waste lines located beneath the trailer. These process waste lines were not associated with T707B.

Figure 1



ADMIN RECORD