

CORRES. CONTROL
INCOMING LTR NO.

00324 RFO4

DUE DATE
ACTION

RECEIVED

2004 AUG -4 A 6:15 STATE OF COLORADO

Bill Owens, Governor
Douglas H. Benevento, Executive Director
CORRESPONDENCE CONTROL
Dedicated to protecting and improving the health and environment of the people of Colorado

4300 Cherry Creek Dr. S. Laboratory and Radiation Services Division
Denver, Colorado 80246-1530 8100 Lowry Blvd.
Phone (303) 692-2000 Denver, Colorado 80230-6928
TDD Line (303) 691-7700 (303) 692-3090
Located in Glendale, Colorado



Colorado Department
of Public Health
and Environment

<http://www.cdphe.state.co.us>

July 29, 2004

Mr. Joe Legare
Director, Project Management Division
U.S. Department of Energy, Rocky Flats Project Office
10808 Highway 93, Unit A
Golden, CO 80403-8200

RE: Pre-Demolition Survey Report (PDSR) for Building 774 East Dock Slab - Approval

Dear Mr. Legare:

The Colorado Department of Public Health and Environment, Hazardous Materials and Waste Management Division has reviewed the PDSR for Building 774 East Dock Slab, Revision 0 dated July 19, 2004. This PDSR was received on July 29, 2004. Based on the information contained in this PDSR, we are hereby approving the PDSR for the Building 774 East Dock Slab.

Even though we are approving the PDSR for the B774 East Dock Slab, we are concerned that the PDS was not performed and a PDSR not provided for the entire B774 East Dock facility, which would have included the slab, prior to demolition of the East Dock facility above the slab. We recognize that the above slab structure did not meet the unrestricted release limits and was demolished with our agreement. However, according to Section 1.2 and Figure 1 of the B771 DOP, PDSs and PDSRs are supposed to be performed and provided for all facilities prior to demolition to properly document the environmental condition of the structures, which would include the nature, location, and levels of contamination remaining, as well as recognition of measures needed to prevent releases of the contamination that remains.

It is also our understanding that even though no contamination is currently known to exist on the B774 East Dock Slab, appropriate measures will be taken to properly investigate and identify possible radiological contamination that may be found in association with the unexposed portions of this slab during removal activities.

If you have any questions regarding this correspondence please contact me at (303) 692-3367, Denise Onyskiw at (303) 692-3371, or David Krueck at (303) 692-3328.


Sincerely,

Steven H. Gunderson
RFCA Project Coordinator

cc: Gary Morgan, DOE
Warren Seyfert, DOE
Mark Aguilar, EPA
Sam Garcia, EPA

Chris Gilbreath, KH
Dave Shelton, KH
Steve Nesta, KH

Administrative Records Building T130G



ADMIN RECORD

B771-A-000262

DIST.	LTR	ENC
BERARDINI, J.H.	X	
BOGNAR, E.S.	X	
BROOKS, L.	X	
BUTLER, L.	X	
CARPENTER, M.	X	
CROCKETT, G. A.		
DECK, C. A.	X	
DEGENHART, K. R.		
DIETER, T. J.	X	
FERRERA, D. W.	X	
GIACOMINI, J. J.		
LINDSAY, D. C.	X	
LONG, J. W.		
LYLE, J. L.		
MARTINEZ, L. A.	X	
NAGEL, R. E.	X	
NESTA, S.	X	
NORTH, K.	X	
RODGERS, A. D.		
SHELTON, D. C.	X	
SPEARS, M. S.	X	
PIZZUTO, V.M.		
TOBIN, M.		
TUOR, N. R.	X	
WIEMELT, K.		
WILLIAMS, J. L.		
ZAHM, C.	X	
Gilbreath, C.	X	

COR. CONTROL	X
ADMIN. RECORD	X
PATS/130	

Reviewed for Addressee
Corres. Control RFP

8/4/04
Date By

Ref. Ltr. #

DOE ORDER #

5400.1