

ROCKY FLATS ENVIRONMENTAL TECHNOLOGY SITE REGULATORY CONTACT RECORD

Date/Time: June 22, 1999 / 11:30 a.m.

Site Contact(s):

W. Sproles, RMRS	Phone: 966-5790
K. Garland, RMRS	Phone: 966-6399
J. Whiting, KH	Phone: 966-7592
S. Tower, DOE	Phone: 966-2133

Regulatory Contact(s):

E. Kray, CDPHE	Phone: 966-2115
M. Agular, EPA	Phone: 312-6251

Purpose of Contact:

Discussion regarding characterization and demolition of the vestibule between B886 and T886A to allow for the relocation of T886A.

Discussion

Kevin Garland presented the radiological survey results and the Property Release Evaluation for the vestibule between B886 and T886A. The survey results indicated no radiological contamination. Based on a review of the radiological survey results, Ed and Mark approved demolition of the structure.

Contact Record Prepared By: Wayne Sproles, RMRS, Building 886 Closure Project

Distribution:

T. Hopkins, RMRS
F. Hughes, RMRS
J. Law, RMRS
B. McPherson, RMRS
R. Neveau, RMRS
K. North, K-H
F. Phillips, K-H
J. Whiting, K-H

FDPM
FACILITY
Disposition
Program Manual



Contact Record 3/18/99

DOCUMENT CLASSIFICATION
REVIEW WAIVER PER
CLASSIFICATION OFFICE

Page 1 of 1

CEX-105-01

ADMIN RECORD

B886-A-000072