



000061141

INTEROFFICE MEMORANDUM

Rocky Flats Environmental Technology Site
P.O. Box 464
Golden, Colorado 80402-0464
Phone: (303) 966-2677
Fax: (303) 966-8244

DATE: March 26, 1996
TO: M. T. Vess, Environmental Restoration Projects, Bldg. T891B, X6540
FROM: J. E. Law, Sitewide Actions, Bldg. T893A, X484 *J.E. Law*
SUBJECT: DRAIN IDENTIFICATION STUDY INSPECTION OF THE BUILDING 891 DRAIN SYSTEM - JEL-047-96
Action: No Action Required.

The National Pollutant Discharge Elimination System/Federal Facilities Compliance Agreement between the Environmental Protection Agency and the Department of Energy/Rocky Flats Field Office requires Rocky Flats Environmental Technology Site (Site) to "review foundation footing drains where hazardous materials could be introduced into the sanitary sewer system" and to "review other possible sources of hazardous or otherwise inappropriate influents to the sanitary sewer system." The Drain Identification Study (DIS) project was developed to address these requirements by inspecting drain systems in buildings throughout the Site. The DIS is an internal assessment developed to minimize the potential for Clean Water Act violations by revealing possible pathways for inadvertent or inappropriate release of hazardous substances to the sanitary sewer system.

DIS personnel performed inspections of Building 891 drainage systems and identified no potential risk to the sanitary sewer system. The attached documents provide a room-by-room summary of the DIS inspections: (1) Drains and Pathways Inspection Report listing each room and the observations made; (2) Foundation Drain Data Sheet showing available foundation drain information. DIS observations were current as of the inspection dates and the dates can be found in the attached documents.

If you have any questions or need additional information call Frank Rukavina at extension 7370/D5323 or Doug Watson at extension 2143/D0876.

DRW:dql

Attachments:
As Stated

cc:
K. M. Motyl
A. M. Parker
F. Rukavina
D. R. Watson
ER Records Center (2)
RMRS Records

22.015.F



ADMIN RECCRD

IA-A-000689

1/3

BUILDING FOUNDATION DRAIN
 DATA SHEET
 BUILDING NO. 891

SOURCE	COMMENTS	SIGNATURE/DATE
DRAWING SEARCH		
INTERVIEWS 3-12-96	building representatives indicated that no foundation or footing drains are present for this building	
FOUND. DR. REPORT 3-12-96	no reference to this building was located found in the Foundation Drain Report (SWD-012-92)	
FIELD INSPECTION 3-12-96	no evidence of a foundation drain system was discovered during the field investigation	
OTHER		