ROCKY FLATS ENVIRONMENTAL TECHNOLOGY SITE
ER REGULATORY CONTACT RECORD

Date/Time: 6-10-04

Site Contact(s): Annette Primrose, Norma Castaneda
Phone: 303 966-4385, 303 966-4226

Regulatory Contact: Dave Kruchek
Phone: 303 692-3328
Agency: CDPHE

Purpose of Contact: Backfill of 700-6 excavation

Discussion

Radiological and VOC preliminary data were received for the samples collected within the excavation caused by the removal of the B712 structure. All results are well below action levels.

The excavated area is filling with water as a result of groundwater and recent precipitation. To stabilize the area, the excavation will be backfilled at this time rather than waiting for the metals and semivolatile analyses.

If these outstanding results show that a remedial action is required, then the area will be re-excavated.

Contact Record Prepared By: Annette Primrose

Required Distribution:

M. Aguilar, USEPA
H. Ainscough, CDPHE
S. Bell, DOE-RFPO
J. Berardini, K-H
B. Birk, DOE-RFPO
L. Brooks, K-H ESS
L. Butler, K-H RISS
G. Carnival, K-H RISS
N. Castaneda, DOE-RFPO
C. Deck, K-H Legal
N. Demos, SSOC
S. Gunderson, CDPHE
M. Keating, K-H RISS
G. Kleeman, USEPA
D. Kruchek, CDPHE
J. Legare, DOE-RFPO
D. Mayo, K-H RISS
J. Mead, K-H ESS
S. Nesta, K-H RISS
L. Norland, K-H RISS
K. North, K-H ESS
E. Pottorff, CDPHE
A. Primrose, K-H RISS
R. Schassburger, DOE-RFPO
S. Serreze, K-H RISS
D. Shelton, K-H ESS
C. Spreng, CDPHE
S. Surovchak, DOE-RFPO
J. Walstrom, K-H RISS
K. Wiemelt, K-H RISS
C. Zahm, K-H Legal

Additional Distribution:

Beth Loehrke, K-H RISS
Sherry Lopez, K-H RISS
Dave Chojnacki, K-H RISS

RECEIVED

ADMIN RECORD

IA-A-002208