



August 2, 2005

05-RF-00737

Gary Morgan, Director
Project Support
DOE, RFPO

**TRANSMITTAL OF CLOSE OUT REPORT FOR BUILDINGS 120, 120A, S120 (BUS STOP),
920 AND 920A -- DWF-074-05**

Attached is the Closeout Report for the Type 1 facilities 120, 120A, S120 (BUS STOP), 920 and 920A. Please note that a copy of the report has been submitted to the CERCLA AR by the Kaiser-Hill RISS project.

Please contact Steve Nesta x6386 with questions or concerns.

Dennis W. Ferrera
Vice President and Project Manager
Remediation, Industrial D&D, and Site Services

Attachment:
As Stated

SMN:jlh

Orig. and 1 cc - Gary Morgan


cc:
John Rampe

Type 1 Facility Closeout Report

Section A. Facility Data	
Facility No.	Buildings 120, 120A, S120 (Bus Stop), 920 and 920A
Facility Descriptor:	East and West Access Posts, Vehicle Search Facilities
Project:	RISS - Area 5 Group 15 D&D
Date of Demolition:	6/29/05 (120) and 4/27/05 (920)
Additional Information:	Guard posts and portable shelters demolished and disposed of as sanitary waste.
<i>(Must include information on environmental releases and conditions of site at turnover to Environmental Restoration)</i>	

Section B. Final Characterization Data	
Reconnaissance Level Characterization Report <i>(concurrence received)</i>	Reconnaissance Level Characterization Report - Concurrence, Steven H. Gunderson to Joseph A. Legare, dated July 18, 2005.
In-process Characterization	N/A
Pre-Demolition Survey Report <i>(approval received)</i>	N/A
Post-Demolition Survey Report <i>(as necessary)</i>	N/A

Section C. Waste Data <i>(complete categories as appropriate)</i>	
Sanitary Disposal	
Disposal Site:	BFI Foothills Landfill, Golden, Colorado
Waste Volume (m ³):	6,900 Cubic yards
Waste Weight (tons):	5,157.7 net tons
Additional Information:	Above grade building debris
Hazardous Disposal	
Disposal Site:	Kettleman Hills Facility, Kettleman City, CA, Bethlehem Apparatus Co, Hellertown, PA or Onyx, Henderson, CO.
Waste Volume (m ³):	Minor amounts
Additional Information:	Electronic circuit boards, thermostats, exit signs, batteries, fluorescent light bulbs and any other RCRA hazardous components were removed and taken to the RFCA temporary unit for combination with like waste streams for disposal.
TSCA Waste Disposal	
Disposal Site:	
Waste Volume (m ³):	N/A
Additional Information:	
Asbestos Waste Disposal	
Disposal Site:	
Waste Volume (m ³):	N/A
Additional Information:	
Low-Level Waste Disposal	
Disposal Site:	
Waste Volume (m ³):	N/A
Additional Information:	
Low-Level Mixed Waste Disposal	
Disposal Site:	
Waste Volume (m ³):	N/A
Additional Information:	
Recycled Material	
Recycle Facility:	
Waste Volume (m ³):	
Additional Information:	




ADMIN RECORD

5002

Type 1 Facility Closeout Report

Property Disposition	
Receiver Locations (major items only):	N/A
Volume (m ³):	
Weight (tons):	
Additional Information:	

Section D. Approvals		
Kaiser-Hill Project Manager		8/1/05
	Name/Signature	Date


Additional Facility Information

Buildings 120 and 920 were each 560 square-foot Guard Posts located at the west and east access gates, respectively. The buildings were constructed with concrete walls, concrete foundation, and an insulated metal roof. Each building was connected to the vehicle access gates and the control equipment for the access gates.

Each of the buildings had the following utilities: electrical, potable water, and sanitary drains. The buildings were equipped with external emergency diesel generators, including a diesel-fuel tank.

Buildings 120A and 920A were 120 square-foot wooden, skid-mounted portable shelters used as general offices and break rooms for site security personnel. The 120A and 920A shelters were located at the west and east Vehicle Search Facilities, respectively. Buildings 120A and 920A were equipped with electricity.

Buildings 120, 120A, 920 and 920A were removed during D&D activities, and sent offsite for disposal. The utilities were disconnected and removed to at least three feet below final grade as indicated on the attached map. There are no remaining structural components, utility lines, or parts of the foundation. The buildings are not in an IHSS or PAC therefore no soil sampling is required.



NOTE; UNDERGROUND DIESEL
FUEL STORAGE TANK LOCATED
SOUTH OF BAZO REMOVED
2/17/05.

6" WATER SERVICE MAIN
TO B060 & B061 ISOLATED
12/21/04 NEAR WATER
PLANT Bldg.

WATER SERVICE ISOLATED
5' DEEP 12/22/04 @ VALVE
-PIT-REMOVED

SEPTIC TANK & SEWAGE
HOLDING TANK (NO LEACH
FIELD) REMOVED 1/27/05

40' 20' 0' 40'

8/5



WATER SERVICE
ISOLATED 5 1/2'
DEEP 2/2/05 AT
VALVE PIT NEAR
INNER EAST
GATE B900

NOTE: UNDERGROUND DIESEL FUEL
STORAGE TANK LOCATED NORTH
OF B920 REMOVED 2/17/05.

WATER VALVE PIT
REMOVED 2/17/05

SEPTIC TANK & SEWAGE HOLDING
TANK (NO LEACH FIELD) REMOVED
2/17/05

SEE ZONE D-9

