

ATTACHMENT 2 CROSSWALK WELL RATIONALE

Site Number	Site Type	Area	Site Status/Comments
<b>SITES NOT DRILLED</b>			
01591	MW	Mound	Not drilled because site was in Protected Area (PA)
01691	MW	Mound	Not drilled because site was in Protected Area (PA)
10091	BH	Mound	Not drilled because site was in Protected Area (PA)
03291	MW	NE Trenches	Not drilled due to underground power lines
04391	MW	SE Trenches	
04791	MW	SE Trenches	Contingency well
05491	MW	SE Trenches	Contingency well
05591	MW	903 Pad	Contingency well
05791	MW	SE Trenches	Contingency well
05891	MW	SE Trenches	Contingency well
07791	BH/MW	Mound	Not drilled because site was in Protected Area (PA)
<b>SITES ABANDONED</b>			
00591	MW	903 Pad	Abandoned due to high bedrock
01191	MW	903 Pad	Abandoned due to high bedrock
03491	MW	NE Trenches	Abandoned due to high bedrock
11091	MW	NE Trenches	Abandoned due to high bedrock
11191	MW	SE Trenches	Abandoned due to contaminated augers
11391	MW	NE Trenches	Abandoned because screen became plugged with mud
11591	MW	NE Trenches	Abandoned because augers were lost downhole but were retrieved
12591	MW	NE Trenches	Abandoned because sand was not encountered
11991	MW	NE Trenches	Abandoned due to high bedrock
<b>SITES MOVED</b>			
02591	MW	NE Trenches	
03691	MW	NE Trenches	
03991	MW	NE Trenches	
<b>ADDITIONAL SITES</b>			
11091	BH	NE Trenches	
11191	BH	NE Trenches	
11291	MW	NE Trenches	
11391	BH	NE Trenches	
11491	MW	NE Trenches	
11591	BH	NE Trenches	
11691	MW	NE Trenches	
11791	MW	903 Pad	
11891	MW	NE Trenches	
11991	BH	NE Trenches	
12091	MW	Mound	
12191	MW	NE Trenches	
12291	MW	Mound	Offset because of saturated thickness
12391	MW	NE Trenches	
12491	MW	NE Trenches	
12591	BH	NE Trenches	Sand offset abandoned because sand wasn't encountered in the offset hole
12691	MW	NE Trenches	
12791	BH	903 Pad	
12891	MW	SE Trenches	
12991	MW	903 Pad	
13091	BH/MW	903 Pad	
13191	MW	903 Pad	
13291	MW	903 Pad	
13391	MW	NE Trenches	
13491	MW	NE Trenches	
13591	MW	903 Pad	