

Contents

Acronyms.....	vii
List of Measurement Abbreviations.....	ix
Units (Abbreviations) and Conversion Table.....	xi
Executive Summary.....	xiii
1.0 Site Background.....	1-1
1.1 The Path to Site Closure.....	1-1
1.2 Environmental Monitoring Program.....	1-1
1.3 Characteristics of the Site and Surrounding Area.....	1-1
1.3.1 Land Use and Demography.....	1-1
1.3.2 Geography.....	1-1
1.3.3 Geology.....	1-1
1.3.4 Surface Hydrology.....	1-1
1.3.5 Meteorology.....	1-1
1.3.6 Natural Resources.....	1-1
2.0 Remediation Status and Compliance Summary.....	2-1
2.1 CERCLA Remediation Status.....	2-1
2.2 Summary of Compliance with Other Requirements.....	2-1
2.2.1 Resource Conservation and Recovery Act.....	2-1
2.2.1.1 RCRA Property Boundary Groundwater Monitoring.....	2-1
2.2.1.2 Waste Management.....	2-1
2.2.2 Clean Water Act.....	2-1
2.2.3 Clean Air Act.....	2-1
2.2.4 Superfund Amendments and Reauthorization Act of 1986.....	2-1
2.2.5 Other Environmental Regulations.....	2-1
2.2.6 Other Permits.....	2-1
2.2.7 Pollution Prevention and Source Reduction.....	2-1
2.2.8 Site-Specific Regulatory Agreement.....	2-1
2.2.8.1 Federal Facility Compliance Agreement.....	2-1
2.2.8.2 Federal Facility Agreement, Control, and Abatement of Radon- 222 Emissions.....	2-1
2.2.9 Environmental Management Systems Requirement.....	2-1
2.3 Split Sampling Program.....	2-1
3.0 Groundwater Pathway.....	3-1
3.1 Summary of the Nature and Extent of Groundwater Contamination.....	3-1
3.2 Selection and Design of the Groundwater Remedy.....	3-1
3.3 Groundwater Monitoring Highlights for 2007.....	3-1
3.3.1 Restoration Monitoring.....	3-1
3.3.1.1 Operational Summary.....	3-1
3.3.1.2 South Plume/South Plume Optimization Module Operational Summary.....	3-1
3.3.1.3 South Field Module Operational Summary.....	3-1
3.3.1.4 Waste Storage Area Module Operational Summary.....	3-1
3.3.1.5 Monitoring Results for Total Uranium.....	3-1
3.3.1.6 Monitoring Results for Non-Uranium Constituents.....	3-1
3.3.2 Other Monitoring Commitments.....	3-1
3.4 On-Site Disposal Facility Monitoring.....	3-1

4.0	Surface Water and Treated Effluent Pathway.....	4-1
4.1	Summary of Surface Water and Treated Effluent Pathway.....	4-1
4.2	Remediation Activities Affecting the Surface Water Pathway.....	4-1
4.3	Surface Water, Treated Effluent, and Sediment Monitoring Program for 2007....	4-1
4.3.1	Surveillance Monitoring	4-1
4.3.2	Compliance Monitoring	4-1
4.3.2.1	FFCA and Operable Unit 5 Record of Decision Compliance..	4-1
4.3.2.2	NPDES Permit Compliance.....	4-1
4.3.3	Uranium Discharges in Surface Water and Treated Effluent	4-1
4.4	Sediment Monitoring	4-1
5.0	Air Pathway	5-1
5.1	Activities Affecting the Air Pathway.....	5-1
5.2	Air Monitoring Program Summary for 2007	5-1
5.3	Radiological Air Particulate Sampling Results.....	5-1
5.4	Radon Monitoring.....	5-1
5.5	Monitoring for Direct Radiation	5-1
6.0	Radiation Dose.....	6-1
6.1	Estimated Dose from Airborne Emissions.....	6-1
6.2	Direct Radiation Dose.....	6-1
6.3	Total of Doses to the Maximally Exposed Individual	6-1
6.4	Significance of Estimated Radiation Doses for 2007	6-1
6.5	Estimated Dose from Radon	6-1
6.6	Estimated Dose to Biota.....	6-1
7.0	Natural Resources	7-1
7.1	Ecological Restoration Activities	7-1
7.2	Fernald Preserve Site and On-Site Disposal Facility Inspections.....	7-1
7.3	Affected Habitat and Inspection Findings	7-1
7.4	Threatened and Endangered Species	7-1
7.5	Cultural Resources	7-1
8.0	References.....	8-1
9.0	Glossary	9-1

Figures

Figure 1-1.	Fernald Preserve and Vicinity	1-1
Figure 1-2.	Major Communities in Southwestern Ohio.....	1-1
Figure 1-3.	Fernald Preserve Perspective.....	1-1
Figure 1-4.	Cross Section of the New Haven Trough, Looking North	1-1
Figure 1-5.	Regional Groundwater Flow in the Great Miami Aquifer	1-1
Figure 1-6.	Great Miami River Drainage Basin.....	1-1
Figure 1-7.	2002-2006 Wind Rose, 33-ft (10-m) Height	1-1
Figure 1-8.	2002-2006 Wind Rose, 197-ft (60-m) Height	1-1
Figure 1-9.	Average Annual Precipitation, 1994-2007	1-1
Figure 1-10.	Monthly Precipitation for 2007 Compared to Average Monthly Precipitation for 1951-2006.....	1-1
Figure 2-1.	Uncertified Areas.....	2-1
Figure 2-2.	2007 DOE and OEPA Groundwater Split Sample Locations	2-1
Figure 3-1.	Extraction Wells Active in 2007	3-1

Figure 3–2. Diagram of a Typical Groundwater Monitoring Well.....	3–1
Figure 3–3. Monitoring Well Relative Depths and Screen Locations	3–1
Figure 3–4. Locations for Semiannual Total Uranium Monitoring.....	3–1
Figure 3–5. Locations for Semiannual Non-Uranium Monitoring	3–1
Figure 3–6. IEMP Groundwater Elevation Monitoring Wells.....	3–1
Figure 3–7. Net Mass of Uranium Removed from the Great Miami Aquifer, 1993–2007	3–1
Figure 3–8. Total Uranium Plume in the Aquifer with Concentrations Greater Than 30 µg/L at the End of 2007	3–1
Figure 3–9. Non-Uranium Constituents with 2007 Results Above Final Remediation Levels.....	3–1
Figure 3–10. On-Site Disposal Facility Footprint and Monitoring Well Locations	3–1
Figure 4–1. Controlled Surface Water Areas and Uncontrolled Runoff Flow Directions.....	4–1
Figure 4–2. IEMP/NPDES Surface Water and Treated Effluent Sample Locations	4–1
Figure 4–3. IEMP Background Surface Water Sample Locations	4–1
Figure 4–4. Annual Average Total Uranium Concentrations in Paddys Run at Willey Road (SWP-03) Sample Location, 1985–2007	4–1
Figure 4–5. Pounds of Uranium Discharged to the Great Miami River Through the Parshall Flume (PF 4001) in 2007	4–1
Figure 4–6. 2007 Monthly Average Total Uranium Concentration in Water Discharged Through the Parshall Flume (PF 4001) to the Great Miami River	4–1
Figure 4–7. Uranium Discharged via the Surface Water Pathway, 1993–2007	4–1
Figure 4–8. 2007 Sediment Sample Locations	4–1
Figure 5–1. Radiological Air Monitoring Station (AMS) Locations.....	5–1
Figure 5–2. Monthly Results and Measurement Error for Uranium in Collected Air Particulate	5–1
Figure 5–3. Annual Activity and Uncertainty for Isotopes Used in NESHAP Analysis.....	5–1
Figure 5–4. Radon Monitoring Locations.....	5–1
Figure 5–5. 2007 Average Radon Results Compared to Historical Levels (no background correction)	5–1
Figure 5–6. Direct Radiation (TLD) Monitoring Locations	5–1
Figure 5–7. Quarterly Results and Measurement Error Recorded by TLD Monitoring Location	5–1
Figure 6–1. Comparison of 2007 Air-Pathway Doses and Allowable Limits	6–1
Figure 6–2. Comparison of 2007 All-Pathway Doses and Allowable Limits	6–1
Figure 7–1. Priority Natural Resource Areas.....	7–1
Figure 7–2. Cultural Resource Survey Areas	7–1

Tables

Table 1–1. Operable Unit Remedies.....	1–1
Table 2–1. Compliance With Other Environmental Regulations	2–1
Table 2–2. 2007 DOE/OEPA Split Sampling Comparison	2–1
Table 3–1. Groundwater Restoration Module Status for 2007.....	3–1
Table 3–2. Non-Uranium Constituents With Results Above Final Remediation Levels During 2007	3–1
Table 3–3. On-Site Disposal Facility Groundwater, Leachate, and Leak Detection System Monitoring Summary.....	3–1

Table 4–1. 2007 Summary Statistics for the Sediment Monitoring Program.....	4–1
Table 5–1. Summary of Total Uranium and Particulate Concentrations in Air	5–1
Table 5–2. Annual Summary for Monthly Average Radon Concentrations	5–1
Table 5–3. Direct Radiation (Thermoluminescent Dosimeter) Measurement Summary	5–1
Table 6–1. Dose to Maximally Exposed Individual (MEI)	6–1
Table 6–2. 2007 Radon Dose Estimate.....	6–1

Appendix

Appendix A	Supplemental Groundwater Information
Appendix B	Supplemental Surface Water, Treated Effluent, and Sediment Information
Appendix C	Supplemental Air Information
Appendix D	2006 National Emissions Standards for Hazardous Air Pollutants (NESHAP) Annual Report
Appendix E	Ecological Restoration Monitoring