

**ROCKY FLATS ENVIRONMENTAL TECHNOLOGY SITE
REGULATORY CONTACT RECORD**

Date/Time March 29, 2001

Site Contact(s) Karl Shuler

Phone. 966-3423

Regulatory Contact Dave Kruchek

Phone 966-6728

Agency CDPH&E

Purpose of Contact Document Discussion between Mr Karl Shuler and Mr Dave Kruckeck regarding Building 881 Room 286

Discussion

- 1 Mr Shuler talked with Mr Kruchek regarding the removal of the heat exchanger, pump, and table sitting to the left of the annular tank in Building 881 Room 286 Mr Kruchek stated he has no problems with the removal of those two items provided that
 - The piping from the heat exchanger to that drain was just used for ordinary water
 - That piping gets blanked off or flanged at the pipe union near the annular tank
 - The annular tank remains

- 2 If further history of the annular tank could be provided, Mr Kruckeck might be prepared to hold further discussions For example, was the heat exchanger used to cool/heat the annulus using ordinary water?

- 3 Mr Kruchek might consider removal of the items if handled under a satisfactory work package

This contact record serves to document the consultative process, in accordance with section 1 1 5 of the DPP, for removal of fixed equipment

Contact Record Prepared By Kent A Dorr

Required Distribution

J Legare, RFFO

S Tower, RFFO

S Gunderson, CDPH&E

D Kruchek, CDPH&E

(rehder_timothy@epamail.epa.gov)

L Brooks, K-H

C Deck, K-H

K Dorr, K-H

F Gibbs, K-H

S Nesta, K-H RISS

D Shelton, K-H

K Myers, RISS

K North, K-H ESS

