


000061140

## INTEROFFICE MEMORANDUM

Rocky Flats Environmental Technology Site  
P.O. Box 464  
Golden, Colorado 80402-0464  
Phone: (303) 966-2677  
Fax: (303) 966-8244

DATE: March 26, 1996

TO: D. R. Pierson, Waste Storage and Disposal, Bldg. T130B, X3190

FROM: J. E. Law, Sitewide Actions, Bldg. T893A, X4842 

SUBJECT: DRAIN IDENTIFICATION STUDY INSPECTION OF THE BUILDING 964 DRAIN SYSTEM – JEL-048-96

The National Pollutant Discharge Elimination System/Federal Facilities Compliance Agreement between the Environmental Protection Agency and the Department of Energy/Rocky Flats Field Office requires Rocky Flats Environmental Technology Site (Site) to "review foundation footing drains where hazardous materials could be introduced into the sanitary sewer system" and to "review other possible sources of hazardous or otherwise inappropriate influents to the sanitary sewer system." The Drain Identification Study (DIS) project was developed to address these requirements by inspecting drain systems in buildings throughout the Site. The DIS is an internal assessment developed to minimize the potential for Clean Water Act violations by revealing possible pathways for inadvertent or inappropriate release of hazardous substances to the sanitary sewer system.

DIS personnel performed inspections of Building 964 drainage systems and identified no potential risk to the sanitary sewer system. The attached documents provide a room-by-room summary of the DIS inspections: (1) Drains and Pathways Inspection Report listing each room and the observations made; (2) Foundation Drain Data Sheet showing available foundation drain information. DIS observations were current as of the inspection dates and the dates can be found in the attached documents.

If you have any questions or need additional information call Frank Rukavina at extension 7370/D5323 or Doug Watson at extension 2143/D0876.

DRW:dqj

Attachments:  
As Stated

cc:  
K. M. Motyl  
A. M. Parker  
F. Rukavina  
D. R. Watson  
ER Records Center (2)  
RMRS Records



22.015.F

ADMIN RECCRD

1/3

IA-A-000688

**DRAINS and PATHWAYS**  
SUMMARY  
BUILDING 964

Inspector	Date	Room #	RCA	Drains	SS Sinks	PW Sinks	UL Sinks	SS FLD	PW FLD	UL FLD	SS Sumps	PW Sumps	UL Sumps	Open Pipe	Funnel Drain	WF	Comments	FL PEN	FL Cracks	Trenches /Pits	Comments/Recommendations
Watson/Lusero	4-Mar-96	100	y	no													No drawings available				No drawings available
<b>Drains Accounted For</b>																					
					0	0	0	0	0	0	0	0	0	0	0	0					
<b>Total Drains Accounted For</b>																					
					0																

2

BUILDING FOUNDATION DRAIN  
 DATA SHEET  
 BUILDING NO. 964

SOURCE	COMMENTS	SIGNATURE/DATE
DRAWING SEARCH		
INTERVIEWS 2-28-96	contact with the building representative revealed no evidence of a foundation drain system	
FOUND. DR. REPORT 2-28-96	no reference to this building was found in the Foundation Drain Report (SWD - 012-92)	
FIELD INSPECTION		
OTHER		